

## Six Year Facilities Master Plan Fiscal Years 2024-2029

November 2022

## **Table of Contents**

| INTRODUCTION                                                                                      | 2  |
|---------------------------------------------------------------------------------------------------|----|
| BACKGROUND                                                                                        | 2  |
| SIX YEAR ENROLLMENT PROJECTIONS                                                                   | 3  |
| Qualifiers                                                                                        | 3  |
| Table 1 – Fall Division-wide Enrollment Counts                                                    | 5  |
| Exhibit 1 – Graphic Display of Total Student Count 2012-2022                                      | 5  |
| Exhibit 2 – Graphic Display of Upper County Elementary Growth: Magruder, Waller Mill, Yorktown    | 6  |
| Exhibit 3 – Graphic Display of Lower County Growth: All Other Elementary Schools                  | 6  |
| Table 2 – Year-to-Date New Home Construction 2012-2022                                            | 8  |
| Table 3 – Enrollment Projections - Elementary Schools                                             | 9  |
| Table 4– Enrollment Projections – Middle Schools                                                  | 10 |
| Table 5– Enrollment Projections –High Schools                                                     | 11 |
| CAPACITY AND UTILIZATION ANALYSIS                                                                 | 12 |
| Table 6 – Average Number of Students per Class                                                    | 12 |
| Table 7 – School Program Capacities                                                               | 12 |
| ATTENDANCE ZONE ANALYSIS                                                                          | 14 |
| STRATEGIES TO OPTIMIZE FACILITIES' SUPPORT OF PROGRAM OF STUDIES                                  | 14 |
| Choices                                                                                           | 15 |
| Attendance Zone Adjustments                                                                       | 15 |
| DEFERRED MAINTENANCE NEEDS                                                                        | 15 |
| PROPOSED ARPA PROJECT SCHEDULE                                                                    | 16 |
| BUDGET ESTIMATES FOR SCHEDULED PROJECTS                                                           | 16 |
| SUMMARY                                                                                           |    |
| Table 8 – Six-Year Facility Master Plan                                                           | 17 |
| Exhibit 4 – Important Agreements between York County School Board and York County Board of        |    |
| Supervisors Affecting the Physical Plant                                                          |    |
| Exhibit 5 – York County Planning Division Summary of Residential Data Affecting School Enrollment | 23 |
| Table 9 – Active Residential Developments in School Attendance Zones                              | 29 |
| Table 10 – Pending Residential Developments by Attendance Zone                                    | 30 |
| Table 11 – Planned Residential Developments by Attendance Zone                                    | 31 |
| Exhibit 6 – School Building Assessment Reports                                                    | 32 |
| Exhibit 7 - CIP Project Worksheets                                                                | 54 |
| Exhibit 8 – School Zone Attendance Maps                                                           | 81 |

### INTRODUCTION

The Six Year Facilities Master Plan (FMP) addresses the requirements of the York County School Division (YCSD) for new or expanded facilities and major maintenance of existing facilities. Student population, changes in academic programs, and the age of existing facilities drive such needs. The focus of each edition of the FMP is a draft list of recommended capital construction projects and capital maintenance projects to be included in the next fiscal year's Capital Improvement Program (CIP). Recommendations for new classroom facilities are derived from an analysis of both demographic projections prepared by York County staff, and current attendance zone boundary lines for specific schools. Recommendations for capital maintenance projects are based on relevant machinery and system histories and observed conditions of each school's building and campus.

#### **BACKGROUND**

Starting with Fiscal Year 2008, the FMP incorporated a recommendation from MGT of America's efficiency review of YCSD conducted in late 2005. As a result, the FMP compiles all data, analysis and related information on CIP recommendations into one document. Important agreements between the York County School Board and the York County Board of Supervisors also shape the FMP. Exhibit 4 summarizes these agreements.

The pace of residential development in York County drives planning for additional classroom capacity. Most additional capacity for the past two decades has been created through additions to existing schools.

Coventry Elementary School (CES) was the last new building added to the elementary school inventory, opening in 1989. Magruder Elementary School (MES) was rebuilt using the CES design and opened in 1990. Grafton Middle School (GMS) and Grafton High School (GHS) were the last secondary schools built, opening in September 1996.

The School Board owns property in Kiln Creek, which is currently being leased to the Board of Supervisors for use as a park and athletic fields. Land has also been proffered near the Marquis South Pod property in the Bruton Zone and the division has done preliminary design work to evaluate viability of that property as a future elementary school site. It is important to note that the School Board also owns property next to the Yorktown Middle School (YMS) campus that is insufficient in size for an elementary school site. Additionally, there are plans for a development in the Fenton Mill area that is currently in the plan review process. The current plans have space provided for a school; however, no official proffer has been made at this point in the development process.

Most current school sites will not easily accommodate any further expansion of the school buildings. However, the sites at the following schools can accommodate limited future expansion: Dare Elementary School (DES), Seaford Elementary School (SES), Waller Mill Elementary School (WMES), Queens Lake Middle School (QLMS), Yorktown Middle School (YMS) and Bruton High School (BHS).

Before the recent downturn in enrollment attributed to the Covid-19 pandemic, the highest potential for new students from future residential development was, and remains, in the Bruton and York attendance zones as there are 87 active units planned and another 1,300 pending review. The current YCSD physical plant cannot support extensive student enrollment gains from residential

development in the aforementioned zones. The volume of planned upper county development indicates the potential for significant increased capacity demands on the existing schools located in the Bruton area of York County: BHS, QLMS, WMES, and MES. Likewise, recent existing home turnover trends in the Grafton and Tabb zones are creating significant pressure on already high elementary capacities in those zones.

The attendance zones for BHS, QLMS, and MES were modified in FY09 to provide short-term relief from increased enrollment demands. Additionally, the attendance zones for Coventry Elementary School (CES), Grafton Bethel Elementary School (GBES), Seaford Elementary School (SES), and Yorktown Elementary School (YES) were modified in 2018 in response to increasing enrollment at YES and GBES.

The ten-classroom addition to MVES in FY10 and the six-classroom addition to Tabb Elementary School (TES) in FY13 provided some relief to capacity demands for elementary schools in this area.

In October 2020, COVID-19 related reductions in enrollment left only two of the elementary schools GBES in the Grafton zone, and CES located in the Tabb area with enrollment greater than 600 students. COVID-19 effects on enrollment eased in FY22, with the September 30 enrollment at 12,685. Additionally, the implementation of the One-to-One laptop initiative allowed schools to abandon many desktop computer labs, which allowed schools to increase their instructional capacity.

The Smith Farms development will bring additional students to MVES, (currently at 578 students) in future years. Enrollment patterns for elementary schools in the Tabb area may warrant further consideration with the completion of the development as well as Commonwealth Green.

During each fiscal year, community input to the planning process for facilities is received through a public forum in November and a public hearing in December on the proposed CIP. Both events are an agenda item for the School Board Regular Meeting during those months.

## SIX YEAR ENROLLMENT PROJECTIONS

#### Qualifiers

The reader should keep in mind eleven important qualifications in studying the data contained in this plan.

- 1. The information presented in <u>Table 2</u> provides a comprehensive summary of residential development and associated effects on school enrollment. Part of this period witnessed unprecedented low interest rates leading to high home sales volume.
- 2. Enrollment projections in this annual report fall usually within 100 students division-wide. The FY21 and FY22 years were significantly skewed due to the Covid-19 viral pandemic.
- 3. The division decision to start the school year in full remote learning for COVID-19 mitigation resulted in a significant percentage of families to withdraw their children from school division. The total enrollment on October 16 was 12,344. To date, the division has not returned to its FY20 peak in enrollment of 12,997.
- 4. The enrollment projections shown in Tables 3, 4 and 5 use the historical methodology taking the current enrollment and extrapolated in out years using recent enrollment trends and compounded over time. It is a general projection that does not take into account possible

- economic downturn or increased special population or programming demands. However, this year's projection will omit FY21 data to eliminate the outlier variance caused by the significant withdrawals associated with the implementation of remote learning leading to different hybrid formats.
- 5. The information in <u>Tables 9</u> and <u>10</u> group active and planned residential developments by current elementary school attendance zones for ease of reference.
- 6. Beginning with FY20, the division has frozen all elementary attendance zones from Out-of-District attendance requests, with the exception of employees. This was done in order to add stability to the elementary attendance picture while maintaining a powerful teacher recruitment/retention strategy.
- 7. The division eliminated its three-year waiting period for tuition-free attendance for the children of staff in the spring of 2022 to enhance this recruitment and retention strategy.
- 8. The division opened its secondary schools to tuition-free attendance of employees of the County of York starting in fall of 2022.
- Enrollment projections are an inexact science and need not be exact. Decisions made to increase permanent space are based on sustained enrollment increases while anomalies and variances can be absorbed in existing structures or accommodated through temporary strategies.
- 10. See Table 1 below for actual elementary September 30 enrollment for the past 10 years. Note the steep decline in enrollment in the years before FY21 for the combination of Magruder, Yorktown and Waller Mill, which is depicted in Exhibits 2 and the steep incline of the rest of the division in Exhibit 3. Looking back, any hurried decision to build an elementary in the upper county between 2014 and 2017 would have failed to solve our rising elementary enrollment numbers without a drastic and unrealistic rezoning plan. In addition, the COVID-19 withdrawals, further highlight the need for slow and deliberate pacing of new school construction.
- 11. The nation is currently experiencing unparalleled inflation and rising interest rates that are predicted to rise at least once more before stepping down. The rise in interest rates is sure to soften the real estate market to some extent which may slow down the pace of developments moving from planned to active.

Table 1 – Fall Division-wide Enrollment Counts 2012-2022

|                                | FY13  | FY14  | FY15  | FY16  | FY17  | FY18  | FY19  | FY20  | FY21  | FY22  | FY23  |
|--------------------------------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|
| September 30 Enrollment Counts | 2012  | 2013  | 2014  | 2015  | 2016  | 2017  | 2018  | 2019  | 2020  | 2021  | 2022  |
|                                |       |       |       |       |       |       |       |       |       |       |       |
| Elementary Schools             |       |       |       |       |       |       |       |       |       |       |       |
| BETHEL MANOR ELEMENTARY        | 421   | 501   | 595   | 598   | 625   | 613   | 631   | 652   | 582   | 620   | 611   |
| COVENTRY ELEMENTARY            | 582   | 560   | 568   | 577   | 559   | 571   | 680   | 732   | 698   | 683   | 646   |
| DARE ELEMENTARY                | 409   | 366   | 374   | 377   | 416   | 417   | 406   | 420   | 369   | 383   | 391   |
| GRAFTON BETHEL ELEMENTARY      | 532   | 539   | 533   | 550   | 564   | 637   | 618   | 657   | 607   | 629   | 624   |
| MAGRUDER ELEMENTARY            | 624   | 613   | 617   | 623   | 619   | 600   | 577   | 620   | 561   | 613   | 694   |
| MOUNT VERNON ELEMENTARY        | 553   | 529   | 526   | 523   | 555   | 616   | 597   | 613   | 548   | 587   | 578   |
| SEAFORD ELEMENTARY             | 476   | 484   | 472   | 453   | 436   | 447   | 519   | 533   | 500   | 530   | 485   |
| TABB ELEMENTARY                | 630   | 628   | 665   | 623   | 595   | 618   | 661   | 692   | 589   | 652   | 664   |
| WALLER MILL ELEMENTARY         | 275   | 291   | 284   | 315   | 335   | 394   | 369   | 361   | 327   | 370   | 377   |
| YORKTOWN ELEMENTARY            | 658   | 651   | 648   | 698   | 687   | 674   | 608   | 592   | 579   | 595   | 635   |
| Middle Schools                 |       |       |       |       |       |       |       |       |       |       |       |
| GRAFTON MIDDLE                 | 857   | 867   | 867   | 870   | 881   | 897   | 932   | 926   | 880   | 878   | 873   |
| QUEENS LAKE MIDDLE             | 451   | 445   | 457   | 460   | 462   | 465   | 475   | 518   | 520   | 538   | 573   |
| TABB MIDDLE                    | 834   | 884   | 920   | 928   | 853   | 855   | 866   | 899   | 886   | 884   | 902   |
| YORKTOWN MIDDLE                | 746   | 768   | 771   | 769   | 791   | 746   | 725   | 711   | 663   | 645   | 648   |
| High Schools                   |       |       |       |       |       |       |       |       |       |       |       |
| BRUTON HIGH                    | 592   | 582   | 597   | 602   | 569   | 598   | 549   | 576   | 611   | 654   | 712   |
| GRAFTON HIGH                   | 1288  | 1223  | 1190  | 1183  | 1192  | 1179  | 1168  | 1176  | 1127  | 1169  | 1207  |
| TABB HIGH                      | 1112  | 1090  | 1166  | 1170  | 1178  | 1126  | 1108  | 1121  | 1074  | 1072  | 1115  |
| YORK HIGH                      | 1071  | 1070  | 1099  | 1061  | 1071  | 1113  | 1125  | 1129  | 1130  | 1076  | 1040  |
| YORK RIVER ACADEMY             | 72    | 78    | 86    | 80    | 78    | 73    | 74    | 69    | 57    | 62    | 67    |
| Division Totals                | 12183 | 12169 | 12435 | 12460 | 12466 | 12639 | 12688 | 12997 | 12308 | 12640 | 12842 |

Note: Pre-Kindergarten and Alternative Placement enrollment not included

Source: Internal Enrollment Tracking Spreadsheet 2012-2022

Exhibit 1 – Graphic Display of Total Student Count 2012-2022




Exhibit 2 – Graphic Display of Upper County Elementary Growth: Magruder, Waller Mill, Yorktown






Exhibit 3 – Graphic Display of Lower County Growth: All Other Elementary Schools



THIS PAGE LEFT INTENTIONALLY BLANK

*Table 2 – Year-to-Date New Home Construction 2012-2022* 



## FY23-29 ENROLLMENT VS. CAPACITY PROJECTIONS

Table 3 – Enrollment Projections - Elementary Schools

#### Historical projection based on FY23 enrollment and 3-year trailing average growth extrapolation, omitting FY21

|        | Ac         | tual FY                   | <b>723</b>                | Proj       | ected F                   | Y24                       | Proj       | ected F                   | Y25                       | Proj       | ected F                   | Y26                       | Pro        | jected I                  | Y27                       | Pro        | jected I                  | FY28                      | Pro        | jected F                  | TY29                      |
|--------|------------|---------------------------|---------------------------|------------|---------------------------|---------------------------|------------|---------------------------|---------------------------|------------|---------------------------|---------------------------|------------|---------------------------|---------------------------|------------|---------------------------|---------------------------|------------|---------------------------|---------------------------|
| School | Enrollment | Instructional<br>Capacity | (Over)/ Under<br>Capacity |
| BMES*  | 611        | 653                       | 42                        | 605        | 653                       | 48                        | 598        | 653                       | 55                        | 592        | 653                       | 61                        | 586        | 653                       | 67                        | 580        | 653                       | 73                        | 574        | 653                       | 79                        |
| CES*   | 646        | 630                       | (16)                      | 636        | 630                       | (6)                       | 625        | 630                       | 5                         | 615        | 630                       | 15                        | 605        | 630                       | 25                        | 596        | 630                       | 34                        | 586        | 630                       | 44                        |
| DES    | 391        | 450                       | 59                        | 386        | 450                       | 64                        | 382        | 450                       | 68                        | 377        | 450                       | 73                        | 373        | 450                       | 77                        | 368        | 450                       | 82                        | 364        | 450                       | 86                        |
| GBES*  | 624        | 608                       | (16)                      | 626        | 608                       | (18)                      | 628        | 608                       | (20)                      | 630        | 608                       | (22)                      | 633        | 608                       | (25)                      | 635        | 608                       | (27)                      | 637        | 608                       | (29)                      |
| MES*   | 694        | 563                       | (131)                     | 739        | 563                       | (176)                     | 786        | 563                       | (223)                     | 837        | 563                       | (274)                     | 891        | 563                       | (328)                     | 949        | 563                       | (386)                     | 1,010      | 563                       | (447)                     |
| MVES*  | 578        | 563                       | (15)                      | 572        | 563                       | (9)                       | 566        | 563                       | (3)                       | 560        | 563                       | 3                         | 554        | 563                       | 9                         | 548        | 563                       | 15                        | 542        | 563                       | 21                        |
| SES*   | 485        | 518                       | 33                        | 475        | 518                       | 43                        | 465        | 518                       | 53                        | 455        | 518                       | 63                        | 445        | 518                       | 73                        | 436        | 518                       | 82                        | 427        | 518                       | 91                        |
| TES    | 664        | 720                       | 56                        | 665        | 720                       | 55                        | 666        | 720                       | 54                        | 667        | 720                       | 53                        | 668        | 720                       | 52                        | 669        | 720                       | 51                        | 670        | 720                       | 50                        |
| WMES   | 377        | 428                       | 51                        | 380        | 428                       | 48                        | 384        | 428                       | 44                        | 387        | 428                       | 41                        | 391        | 428                       | 37                        | 394        | 428                       | 34                        | 398        | 428                       | 30                        |
| YES*   | 635        | 653                       | 18                        | 645        | 653                       | 8                         | 655        | 653                       | (2)                       | 665        | 653                       | (12)                      | 675        | 653                       | (22)                      | 686        | 653                       | (33)                      | 697        | 653                       | (44)                      |
| TOTALS | 5,705      | 5,786                     | 81                        | 5,728      | 5,786                     | 58                        | 5,755      | 5,786                     | 31                        | 5,786      | 5,786                     | (0)                       | 5,821      | 5,786                     | (35)                      | 5,860      | 5,786                     | (74)                      | 5,904      | 5,786                     | (118)                     |

<sup>\*</sup>Classroom trailers currently in use and are not included in instructional capacity calculation.

Notes: Anticipated increased enrollment from new developments is not included in projection.

Enrollment data does not include Pre-Kindergarten students.

Enrollment projections represent a compounding of 2022 enrollment (SEP 30) using a growth percentage from the trailing 3-year average at each school, omitting COVID-related FY21 decreases

Table 4– Enrollment Projections – Middle Schools

## Historical projection based on FY23 enrollment and 3-year trailing average growth extrapolation, omitting FY21

|        | Ac         | ctual FY            | 723                       | Proj       | ected F             | Y24                       | Proj       | ected F             | Y25                       | Proj       | ected F             | Y26                       | Pro        | jected I            | ected FY27 Projected FY28 |            | Projected FY28      |                           | Projected FY29 |                     | FY29                      |
|--------|------------|---------------------|---------------------------|------------|---------------------|---------------------------|------------|---------------------|---------------------------|------------|---------------------|---------------------------|------------|---------------------|---------------------------|------------|---------------------|---------------------------|----------------|---------------------|---------------------------|
| School | Enrollment | Maximum<br>Capacity | (Over)/ Under<br>Capacity | Enrollment     | Maximum<br>Capacity | (Over)/ Under<br>Capacity |
| GMS    | 873        | 1,215               | 342                       | 854        | 1,215               | 361                       | 836        | 1,215               | 379                       | 818        | 1,215               | 397                       | 801        | 1,215               | 414                       | 784        | 1,215               | 431                       | 767            | 1,215               | 448                       |
| QLMS*  | 573        | 681                 | 108                       | 610        | 681                 | 71                        | 650        | 681                 | 31                        | 692        | 681                 | (11)                      | 737        | 681                 | (56)                      | 785        | 681                 | (104)                     | 836            | 681                 | (155)                     |
| TMS*   | 902        | 1,178               | 276                       | 915        | 1,178               | 263                       | 927        | 1,178               | 251                       | 940        | 1,178               | 238                       | 953        | 1,178               | 225                       | 967        | 1,178               | 211                       | 980            | 1,178               | 198                       |
| YMS    | 648        | 982                 | 334                       | 625        | 982                 | 357                       | 602        | 982                 | 380                       | 581        | 982                 | 401                       | 560        | 982                 | 422                       | 540        | 982                 | 442                       | 521            | 982                 | 461                       |
| TOTALS | 2,996      | 4,056               | 1,060                     | 3,004      | 4,056               | 1,052                     | 3,016      | 4,056               | 1,040                     | 3,031      | 4,056               | 1,025                     | 3,051      | 4,056               | 1,005                     | 3,075      | 4,056               | 981                       | 3,103          | 4,056               | 953                       |

<sup>\*</sup>Classroom trailer currently in use and not included in maximum capacity.

Notes Anticipated increased enrollment from new developments are not included in projection.

Enrollment projections represent a compounding of 2022 enrollment (SEP 30) using a growth percentage from the trailing 3-year average at each school, omitting COVID-related FY21 decreases

Table 5- Enrollment Projections -High Schools

## Historical projection based on FY23 enrollment and 3-year trailing average growth extrapolation, omitting FY21

|        | Ac         | ctual FY            | 723                       | Proj       | ected F             | Y24                       | Proj       | Projected FY25      |                           |            | ected F             | Y26                       | Pro        | jected I            | 'Y27                      | Pro        | jected I            | FY28                      | Pro        | ected I             | Y29                       |
|--------|------------|---------------------|---------------------------|------------|---------------------|---------------------------|------------|---------------------|---------------------------|------------|---------------------|---------------------------|------------|---------------------|---------------------------|------------|---------------------|---------------------------|------------|---------------------|---------------------------|
| School | Enrollment | Maximum<br>Capacity | (Over)/ Under<br>Capacity |
| BHS    | 712        | 1,039               | 327                       | 777        | 1,039               | 262                       | 848        | 1,039               | 191                       | 925        | 1,039               | 114                       | 1,009      | 1,039               | 30                        | 1,101      | 1,039               | (62)                      | 1,201      | 1,039               | (162)                     |
| GHS    | 1207       | 1,397               | 190                       | 1,220      | 1,397               | 177                       | 1,234      | 1,397               | 163                       | 1,248      | 1,397               | 149                       | 1,262      | 1,397               | 135                       | 1,276      | 1,397               | 121                       | 1,290      | 1,397               | 107                       |
| THS*   | 1115       | 1,288               | 173                       | 1,118      | 1,288               | 170                       | 1,121      | 1,288               | 167                       | 1,124      | 1,288               | 164                       | 1,127      | 1,288               | 161                       | 1,130      | 1,288               | 158                       | 1,133      | 1,288               | 155                       |
| YHS*   | 1040       | 1,214               | 174                       | 1,013      | 1,214               | 201                       | 987        | 1,214               | 227                       | 962        | 1,214               | 252                       | 937        | 1,214               | 277                       | 913        | 1,214               | 301                       | 890        | 1,214               | 324                       |
| TOTALS | 4,074      | 4,938               | 864                       | 4,129      | 4,938               | 809                       | 4,190      | 4,938               | 748                       | 4,259      | 4,938               | 679                       | 4,335      | 4,938               | 603                       | 4,420      | 4,938               | 518                       | 4,515      | 4,938               | 423                       |

<sup>\*</sup>Classroom trailer currently in use and not included in maximum capacity.

Notes Anticipated increased enrollment from new developments are not included in projection.

Enrollment projections represent a compounding of 2022 enrollment (SEP 30) using a growth percentage from the trailing 3-year average at each school, omitting COVID-related FY21 decreases

### CAPACITY AND UTILIZATION ANALYSIS

Program capacity of each school is based on a model developed by Professor Glenn Earthman of Virginia Tech, which he used in conducting the initial YCSD capacity survey in 1992.

YCSD staff using Professor Earthman's methodology have conducted subsequent periodic updates of each building's program capacity. The capacity discussion in this FMP is based on the average number of students per class that were used in the 2004 edition of program capacities and in subsequent updates.

Table 6 - Average Number of Students per Class

| Students per Class | Kindergarten | 1 <sup>st</sup> & 2 <sup>nd</sup> | 3 <sup>rd</sup> to 5 <sup>th</sup> | 6 <sup>th</sup> to 8 <sup>th*</sup> | 9 <sup>th</sup> to 12 <sup>th</sup> * |
|--------------------|--------------|-----------------------------------|------------------------------------|-------------------------------------|---------------------------------------|
| Earthman           | 18           | 22                                | 22                                 | 23                                  | 25                                    |
| 2004               | 20           | 22                                | 25                                 | 25                                  | 25                                    |

The capacity of a building to accommodate a certain number of students is not a static number. There is not a determined capacity for a building that could stand for the life of the structure. The capacity of a building is best determined by how it is used. Capacity can never be independent of utilization; the size of the cafeteria, gymnasium and media center must also be considered. Any change in mandated programs or educational practices affects the stated capacity of a building. At the elementary level, the division uses the term instructional capacity to reflect the number of students who can effectively receive instruction in a building under the current educational program, given appropriate instructional spaces. Multiple programs beyond dedicated K-5 classrooms impact an elementary school's capacity. These programs include art, computer labs, dance, drama, English Learners (EL), math resource, Pre-Kindergarten, reading, science resource and special education (pull-out or self-contained). The instructional capacity for elementary schools is calculated for each edition of the FMP because of changes in programming. Instructional capacities for secondary schools are the same as the building capacities because of the manner in which middle and high school students are scheduled.

The following tables present a historical perspective of building capacities as well as the FY22 instructional capacities for all schools.

Table 7 – School Program Capacities

#### **HIGH SCHOOLS**

| School | Earthman 1992<br>Building<br>Capacities | FY04 Building<br>Capacities | FY20 Building<br>Capacities | FY20 Instructional<br>Capacities | Enrollment<br>9/26/2022 |
|--------|-----------------------------------------|-----------------------------|-----------------------------|----------------------------------|-------------------------|
| BHS    | 878                                     | 1,039                       | 1,039                       | 1,039                            | 712                     |
| GHS    | Open 1996                               | 1,397                       | 1,397                       | 1,397                            | 1,207                   |
| THS    | 972                                     | 1,288                       | 1,288                       | 1,288                            | 1,115                   |

| School | Earthman 1992<br>Building<br>Capacities | FY04 Building<br>Capacities | FY20 Building<br>Capacities | FY20 Instructional<br>Capacities | Enrollment<br>9/26/2022 |
|--------|-----------------------------------------|-----------------------------|-----------------------------|----------------------------------|-------------------------|
| YHS    | 1,154                                   | 1,214                       | 1,214                       | 1,214                            | 1,040                   |
| YRA    | N/A                                     | N/A                         | 105                         | 105                              | 67                      |
| Total  | 3,004                                   | 4,938                       | 5,043                       | 5,043                            | 4,141                   |

#### **MIDDLE SCHOOLS**

| School | Earthman 1992<br>Building Capacities | FY04 Building<br>Capacities | FY20 Building<br>Capacities | FY20 Instructional<br>Capacities | Enrollment<br>9/26/2022 |
|--------|--------------------------------------|-----------------------------|-----------------------------|----------------------------------|-------------------------|
| GMS    | Open 1996                            | 1,215                       | 1,215                       | 1,215                            | 873                     |
| QLMS   | 455                                  | Renovation                  | 681                         | 681                              | 573                     |
| TMS    | 657                                  | 1,178                       | 1,178                       | 1,178                            | 902                     |
| YMS    | 558                                  | 558                         | 982                         | 982                              | 648                     |
| Total  | 1,670                                | 2,558                       | 4,056                       | 4,056                            | 2,996                   |

<sup>\*</sup>Where appropriate, the Virginia Department of Education ceiling of 30 students was used for middle school and high school calculations.

#### **ELEMENTARY SCHOOLS**

| School | Earthman 1992<br>Building | FY04 Building<br>Capacities | FY20 Building<br>Capacities | FY23Instructional<br>Capacities | Enrollment<br>9/26/2022 | Enrollment<br>9/30/2022 |
|--------|---------------------------|-----------------------------|-----------------------------|---------------------------------|-------------------------|-------------------------|
|        | Capacities                |                             |                             |                                 |                         | Pre-K Included          |
| BMES   | 344                       | 616                         | 698                         | 653                             | 611                     | 638                     |
| CES    | 435                       | 708                         | 708                         | 630                             | 646                     | 649                     |
| DES    | 412                       | 409                         | 552                         | 450                             | 391                     | 391                     |
| GBES   | 437                       | 685                         | 703                         | 608                             | 624                     | 624                     |
| MES    | 430                       | 650                         | 740                         | 563                             | 694                     | 710                     |
| MVES   | 489                       | 489                         | 782                         | 563                             | 578                     | 578                     |
| SES    | 432                       | 476                         | 656                         | 518                             | 485                     | 503                     |
| TES    | 550                       | 661                         | 777                         | 720                             | 664                     | 686                     |
| WMES   | 264                       | 297                         | 508                         | 428                             | 377                     | 394                     |
| YES    | 474                       | 510                         | 734                         | 653                             | 635                     | 655                     |
| Total  | 4,267                     | 5,492                       | 6,858                       | 5,786                           | 5,705                   | 5,828                   |

The following programs are worthy of note in the context of space utilization because the needs of these programs for space surpass other components of the program of studies.

| Special Education                                    | Classrooms dedicated to special education and pre-school programs currently occupy classrooms at the elementary level, middle school level and high school level.                                   |
|------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Computer Labs                                        | Despite the reduction in the need for labs due to the laptop device One-to-One program, some labs remain, especially for CTE programs.                                                              |
| Use of Classrooms for Non-<br>Instructional Purposes | As enrollment increases and division needs dictate, classrooms in some of our schools are used for other instructional purposes such as resource, enrichment (gifted instruction), and remediation. |
| Leased Space                                         | At Yorktown Middle School, seven classrooms are leased for use by the Center for Autism.                                                                                                            |

#### ATTENDANCE ZONE ANALYSIS

The information in <u>Exhibits 5</u> and <u>Table 9</u> point to the elementary school attendance zones where developers are particularly active. However, not all new development will generate enrollment increases at the same rate. In September 2018, several elementary schools experienced increased enrollment growth from new residential developments as well as from existing neighborhoods within those respective zones.

The following schools have the greatest potential for enrollment to remain or increase beyond the school's instructional capacity during the span of the FY23 FMP and beyond.

- Bethel Manor Elementary School
- Coventry Elementary School
- Grafton Bethel Elementary School
- Magruder Elementary School
- Mt. Vernon Elementary School
- Waller Mill Elementary School
- Yorktown Elementary School
- Queens Lake Middle School

Choices for dealing with the corresponding capacity concerns or enrollment increases in certain elementary schools and Queens Lake Middle School are provided in the following section. Current attendance zones are presented in <a href="Exhibit 8"><u>Exhibit 8.</u></a>

## STRATEGIES TO OPTIMIZE FACILITIES' SUPPORT OF PROGRAM OF STUDIES

Several criteria shape the School Board's decisions for dealing with anticipated school enrollment increases in different sections of YCSD. A number of schools are situated on campuses that can accommodate only modest expansion of the building's footprint. The School Board and Board of Supervisors have agreed that in order to meet the demands of increased enrollment, the first approach will be to review the feasibility of expanding existing schools, secondly, to adjust attendance zone boundary lines to balance enrollment, and lastly, to construct new schools. Another less popular solution is the addition of portable classrooms, given available space. The School Board has also set

maximum enrollment parameters as follows: elementary schools – 700 students; middle schools – 700 to 1000 students; and high schools – 1200 to 1800 students per building.

The following discussion of choices for dealing with increasing enrollment in different areas of YCSD is provided in an "if, then" format. These choices represent staff presentation of a comprehensive discussion of possibilities within the framework set by governing agreements and School Board policy. The specific recommendations for the FY23 CIP are presented in the section titled *Recommended New Projects*.

#### Choices

If enrollment projections for the aforementioned schools exceed the instructional capacities during FY23 and beyond, then the Board will consider the following:

- 1. Place temporary classroom units at schools with enrollment beyond the school's instructional capacity.
- 2. Consider the removal of all computer labs in elementary and middle schools due to division's new one-to-one computer program
- 3. Construct new classrooms to existing facilities and balance elementary enrollment as feasible.
- 4. Begin the construction of a new elementary school to relieve enrollment pressure at the elementary level or other intermediary step (Pre-K).
- 5. Expand Queens Lake Middle School to accommodate future students from the new residential developments in the upper county when warranted.

#### Attendance Zone Adjustments

Specific options for modifying elementary school attendance zone boundaries were prepared by a consultant in FY17. A committee comprised of staff and community members reviewed the proposed options during the fall of 2017. Subsequently, committee recommendations were presented and approved by the School Board in December 2017 for implementation in September 2018. Elementary schools affected by the rezoning recommendations were Coventry Elementary School, Grafton Bethel Elementary School, Seaford Elementary School and Yorktown Elementary School.

A final recommendation of the committee was to resume its work as needed in future years, as increased enrollment growth is likely to continue; however, it will need to factor in any new school additions such as the Seaford expansion underway currently.

The division plans to issue an RFP for an attendance zone study again in early 2023 to factor in the SES expansion and changing enrollments post-Covid-19 looking especially for solutions regarding enrollment at Magruder Elementary School and Mt. Vernon Elementary School where, even with additional portable classroom space, enrollment numbers are taxing the instructional capacity more than the other elementary schools.

### DEFERRED MAINTENANCE NEEDS

The effort to maintain the current physical plants in good condition relies on funds from the general operating budget of each fiscal year, the CIP budget for maintenance projects that exceed \$30,000 and miscellaneous funds appropriated by the General Assembly for capital purposes. The capital maintenance projects scheduled in the CIP represent staff's forecast of efforts needed to maintain

buildings and associated systems in good condition. This schedule of major maintenance projects represents the known primary maintenance needs in the York County School Division. An assessment of each school building physical condition is provided in Exhibit 6.

## PROPOSED ARPA PROJECT SCHEDULE

In 2022. The County of York granted the division \$3 million of federal ARPA funds. It was decided to use these funds for individual cash projects across the division. Below is an update and adjusted project plan for these funds.

#### **FY22 Completed Projects:**

- CES Improved soccer field drainage
- DES Added a gravel track between the Grades 3-5 playground and softball field
- TES Fixed playground drainage
- QLMS Installed wood gym floor
- BHS Repainted gym floor lines and corrected various outdoor plumbing issues, and Installed synthetic turf at "The Pit"

#### **FY23 Remaining Projects:**

|      | FY23 Remaining Additional Cash Projects from York County ARPA Funds                   | E  | st. Cost |
|------|---------------------------------------------------------------------------------------|----|----------|
| BMES | Improve drainage at football field by raising the sidewalk 2 - 3" and tapering        | \$ | 60,000   |
| GBES | Install a resilient gym floor                                                         | \$ | 110,000  |
| MES  | Replace wall pads behind the basketball goals                                         | \$ | 25,000   |
| MVES | Replace four (4) side basketball backboards and rims in gym                           | \$ | 40,000   |
| YES  | Replace mismatched wall pads/Add storage to gym and add shades to high windows in gym | \$ | 60,000   |
| GSC  | Replace Auxiliary Gym floor with Resilient flooring                                   | \$ | 210,000  |
| THS  | Modernize weight room and fencing at soccer field                                     | \$ | 160,000  |
|      | Replace doors to training room / Replacement of basketball goal motors / Field Hockey |    |          |
| YHS  | Scoreboard                                                                            | \$ | 32,000   |
| ALL  | Contingency                                                                           | \$ | 60,000   |
|      | TOTAL                                                                                 | \$ | 757,000  |

## BUDGET ESTIMATES FOR SCHEDULED PROJECTS

Construction project costs have fluctuated significantly during the past three years and the outlook forecasts continuation of this trend. With the help of consultants and project architects, YCSD staff adjusts budget amounts in an effort to anticipate changes in construction costs. As labor and material costs continue to fluctuate, project cost projections are adjusted accordingly.

## **SUMMARY**

FY23 FMP modifications are presented in <u>Table 8</u>. This table presents a graphic summary of the capital maintenance projects modifications and additions discussed above.

Table 8 – Six-Year Facility Master Plan

## **Elementary Projects**

| SCHOOL/PROJECT                                                                                                                                                                                                                   | FY23E                      | FY24      | FY25 | FY26 | FY27      | FY28      | FY29      | TOTAL<br>Excludes<br>Current FY |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------|-----------|------|------|-----------|-----------|-----------|---------------------------------|
| ELEMENTARY SCHOOL PROJECTS                                                                                                                                                                                                       | -                          | -         | -    | -    | -         | -         | -         |                                 |
| Dare Elementary - A&E and 68 classroom expansion, property acquisition, and common area adjustments                                                                                                                              | -                          |           |      |      | 1,750,000 | 7,700,000 | 7,700,000 | 17,150,000                      |
| Dare Elementary & SBO - Create bus loop and additional parking spaces                                                                                                                                                            | -                          |           |      |      | 100,000   | 1,000,000 |           | 1,100,000                       |
| Dare Elementary -<br>Replace gym HVAC system                                                                                                                                                                                     | -                          |           |      |      | 200,000   | 2,000,000 |           | 2,200,000                       |
| Mt. Vernon Elementary -<br>A&E and replace HVAC and controls                                                                                                                                                                     |                            | 200,000   |      |      |           |           |           | 200,000                         |
| Seaford Elementary -<br>Expand parking lot                                                                                                                                                                                       | 423,000                    |           |      |      |           |           |           | -                               |
| Seaford Elementary -<br>Replace gym HVAC                                                                                                                                                                                         | 190,800                    |           |      |      |           |           |           | 1                               |
| Seaford Elementary - A&E and 9 classroom expansion to include roof coating, window replacement, media center and main office expansions, cafeteria, bus loop, relocation athletic fields (A&E and construction - 2 year project) | <b>4,100,000</b> 7,848,000 | 1,940,000 |      |      |           |           |           | 1,940,000                       |
| Waller Mill Elementary - A&E and 6 classroom expansion and common area adjustments                                                                                                                                               | 7,040,000                  | 1,940,000 |      |      |           | 1,100,000 | 5,500,000 | 6,600,000                       |

Note: Cash funding designated in green

## Middle School Projects

| SCHOOL/PROJECT                                                                     | FY23E     | FY24      | FY25      | FY26      | FY27      | FY28      | FY29 | TOTAL<br>Excludes<br>Current FY |
|------------------------------------------------------------------------------------|-----------|-----------|-----------|-----------|-----------|-----------|------|---------------------------------|
| MIDDLE SCHOOL PROJECTS                                                             | 1         | 1         | -         |           | -         | 1         | -    |                                 |
| Queens Lake Middle -<br>Expand parking lot and bus loop                            | -         |           |           |           | 815,000   |           |      | 815,000                         |
| Queens Lake Middle - A&E and Eight classroom expansion + create security vestibule | -         |           | 1,111,208 | -         | 010,000   |           |      | 1,111,208                       |
| (construction - 2 year project) and low slope roof                                 |           |           |           | 1,600,000 | 9,000,000 | 9,000,000 |      | 19,600,000                      |
| Queens Lake Middle -<br>Renovate locker and team rooms                             | -         |           |           |           |           |           |      | -                               |
|                                                                                    |           |           |           | 60,000    | 600,000   |           |      | 660,000                         |
| Tabb Middle - Renovate locker and team rooms                                       | -         | -         |           |           |           |           |      | =                               |
|                                                                                    |           |           | 60,000    | 600,000   |           |           |      | 660,000                         |
| Tabb Middle - A&E and replace HVAC and controls                                    | 1,660,000 |           |           |           |           |           |      | -                               |
| '                                                                                  |           | 1,800,000 |           |           |           |           |      | 1,800,000                       |
| Yorktown Middle -<br>Renovate locker and team rooms                                | -         |           |           |           |           |           |      | -                               |
| Transfer to the transfer and tourn tooms                                           |           |           | 60,000    | 600,000   |           |           |      | 660,000                         |

Note: Cash funding designated in green

## High School Projects

| SCHOOL/PROJECT                                                                                                | FY23E     | FY24      | FY25      | FY26      | FY27 | FY28 | FY29 | TOTAL<br>Excludes<br>Current FY |
|---------------------------------------------------------------------------------------------------------------|-----------|-----------|-----------|-----------|------|------|------|---------------------------------|
| HIGH SCHOOL PROJECTS                                                                                          | -         | -         | -         | -         | -    | -    | -    |                                 |
| Bruton High -<br>Renovate locker and team rooms                                                               | -         |           | 90,000    | 900,000   |      |      |      | 990,000                         |
| Bruton High -<br>Replace HVAC equipment and controls                                                          | -         |           |           | 3,400,000 |      |      |      | 3,400,000                       |
| Bruton High -<br>A&E and coat low slope roof                                                                  | -         | 1,700,000 | 3,800,000 |           |      |      |      | 5,500,000                       |
| Tabb High - A&E and Replace HVAC equip & controls + create security vestibule (construction - 2 year project) | 1,500,000 | 4,470,000 | 7,000,000 |           |      |      |      | 11,470,000                      |
| Tabb High - Renovate restrooms, locker and team rooms                                                         | -         | 120,000   | 1,800,000 |           |      |      |      | 1,920,000                       |
| York High -<br>Replace/coat low slope roof (2 year project)                                                   | 1,798,200 |           |           |           |      |      |      | -                               |
| York High -<br>Renovate locker & team rooms                                                                   | -         |           | 150,000   | 1,500,000 |      |      |      | 1,650,000                       |
| York High - Create bus parking loop and expand parking                                                        | -         |           | 150,000   | 1,500,000 |      |      |      | 1,650,000                       |
| York High -<br>Renovate Annex Facility to include bathrooms, windows and<br>interior offices                  | -         |           | 80,000    | 800,000   |      |      |      | 880,000                         |

Note: Cash funding designated in green

## Other Projects and Totals


| SCHOOL/PROJECT                                                                                                  | FY23E      | FY24       | FY25       | FY26       | FY27       | FY28       | FY29       | TOTAL<br>Excludes<br>Current FY |
|-----------------------------------------------------------------------------------------------------------------|------------|------------|------------|------------|------------|------------|------------|---------------------------------|
| OTHER PROJECTS                                                                                                  | -          | -          | -          | =          | =          | -          | =          |                                 |
| Temporary<br>Modular classrooms                                                                                 | 300,000    | 350,000    | 350,000    | 350,000    | 400,000    | 450,000    | 500,000    | 2,400,000                       |
| Division-wide Reconfigure security vestibule at MES                                                             | -          |            |            | 100,000    |            |            |            | 100,000                         |
| Division-wide Replacement of division-wide communication system 800 MHz radios                                  |            | 250,000    | 250,000    | 250,000    |            |            |            | 750,000                         |
| Division-wide Replacement P.A. systems at MES, DES and WMES                                                     | -          | 750,000    |            |            |            |            |            | 750,000                         |
| Division-wide Replacement P.A. systems at QLMS, TMS, BHS, and THS                                               | -          |            | 1,000,000  |            |            |            |            | 1,000,000                       |
| Pre-School Space(s) - A&E and construction of standalone or Hubs for 12 pre-k classrooms                        | -          |            |            |            | 550,000    | 2,200,000  | 3,300,000  | 6,050,000                       |
| New Elementary School 500 student classroom capacity, 700 student core capacity (construction - 2 year project) | -          |            |            |            |            |            | 600,000    | 600,000                         |
| TOTAL CAPITAL PROJECTS                                                                                          | 17,820,000 | 11,580,000 | 15,901,208 | 11,660,000 | 13,415,000 | 23,450,000 | 17,600,000 | 93,606,208                      |
| TOTAL CAPITAL PROJECTS - CASH                                                                                   | 7,260,000  | 1,000,000  | 2,361,208  | 250,000    | 0          | 0          | 0          | 3,611,208                       |
| GRAND TOTAL CAPITAL PROJECTS - BOND ONLY                                                                        | 10,560,000 | 10,580,000 | 13,540,000 | 11,410,000 | 13,415,000 | 23,450,000 | 17,600,000 | 89,995,000                      |

This page left intentionally blank


## Exhibit 4 – Important Agreements between York County School Board and York County Board of Supervisors Affecting the Physical Plant

- Agreement between York County School Board and York County Board of Supervisors, dated June 23, 1992, on maintaining the fields and grounds of schools in York County School Division.
   The agreement provides that capital improvements to elementary and middle school grounds will flow from coordinated staff planning.
- Memorandum of Understanding between the York County School Board and the York County Board of Supervisors, dated August 5, 1993, in which the Boards agree to the following general guidelines regarding school construction decisions.
  - 1. Existing buildings will be expanded as the preferred means of obtaining needed student capacity, rather than constructing new buildings.
  - The Comprehensive Plan shall include the following program capacities for planning purposes: elementary school – 700; middle school – 1000; high school – 1200 to 1800. (Subsequently, the Boards agreed that Grafton High School would be designed for a 1300 program capacity.)
  - 3. Renovation projects should be planned and funded to accommodate projected needs for the next decade following renovation.
  - 4. Renovation projects shall be designed to optimize the use of school sites for community recreational purposes. (Subsequent practice has focused this effort on elementary and middle schools, with high schools exempted from generalized community use for recreation.)
  - 5. New buildings will exclude flat roofs (devoid of tapered insulation).
  - 6. When a cost analysis warrants, temporary classroom units will be purchased or acquired by lease/purchase agreements rather than simply leased.
- Memorandum of Understanding between York County School Division Superintendent and York County Administrator, dated January 21, 1997, on coordinated staff work, in which these officials agreed that:
  - 1. York County planners would provide demographic projections for the use of York County School Division staff in preparing recommendations for the CIP and for the annual operating budget.
  - 2. County staff and School Division staff would coordinate planning of FMP construction projects that affected the community recreational attributes of school grounds.
  - 3. County and School Division staff would coordinate planning of FMP maintenance projects where coordination would provide cost savings to County and School Division CIP budgets.
- Agreement between York County School Board and York County Board of Supervisors, dated March 21, 2005, on optimizing use of schools and park facilities for all York County citizens, in which the Boards agreed that the York County staff would manage the use of playing fields and grounds and gyms at elementary and middle schools outside of the regular school day. (Management of high school facilities is vested in the high school principal.)


## New Home Construction 2011-2021




## New Home Construction by Area 2011-2021




## New Home Construction by Area 2011-2021




## New Home Construction by Type 2011-2021




## Approved/Active Housing Units by Elementary School Attendance Zone




## Pending Housing Units by Elementary School Attendance Zone




# Planned Housing Units by Elementary School Attendance Zone




# Approved/Active, Pending, & Planned Housing Units by Elementary School Attendance Zone




## Approved/Active Housing Units by Secondary School Attendance Zone




# Pending Housing Units by Secondary School Attendance Zone



## Planned Housing Units by Secondary School Attendance Zone



Approved/Active, Pending, & Planned Housing Units by Secondary School Attendance Zone



### Table 9 – Active Residential Developments in School Attendance Zones

### **ACTIVE (Platted Subdivision or approved Site Plan)**

| Housing Development                   | Location                                | School Zone  |        | COs as of 10/1/22 | Future<br>Units |  |
|---------------------------------------|-----------------------------------------|--------------|--------|-------------------|-----------------|--|
| ACTIVE (Platte                        | ed Subdivision or approved              | d Sito Plan) | Ullita | 10/1/22           | Office          |  |
| Commonwealth Green live-aboves        | Commonwealth Drive                      | CES          | 9      | 3                 | 6               |  |
| Mainstay Condominiums at Commonwealth | Commonwealth Drive                      | CES          | 94     | 68                | 26              |  |
| Total CES                             | COMMONWEART DIVE                        | 020          | J-7    | 00                | 32              |  |
| Hidden Harbor                         | Hidden Harbor Lane                      | DES          | 5      | 1                 | 4               |  |
| Little Harbor                         | Ship Point Road                         | DES          | 10     | 4                 | 6               |  |
| Total DES                             | , - · · · · · · · · · · · · · · · · · · |              |        |                   | 10              |  |
| Patrick's Creek Estates (Owen's Fen)  | Patrick's Creek Rd                      | GBES         | 9      | 7                 | 2               |  |
| Total GBES                            |                                         |              |        |                   | 2               |  |
| Marquis Hills - Phase 1 & 2           | Marquis Parkway                         | MES          | 108    | 103               | 5               |  |
| Washington Ridge                      | Bethune Drive                           | MES          | 22     | 20                | 2<br><b>7</b>   |  |
| Total MES                             |                                         |              |        |                   | 7               |  |
| Bunting Point, Phase 2                | Bunting Point Road                      | MVES         | 12     | 10                | 2               |  |
| Shallow Marsh                         | Calthrop Neck Road                      | MVES         | 7      | 5                 | 2               |  |
| Smith Farm Estates, Phases 1A & 1B    | Yorktown Road                           | MVES         | 43     | 37                | 6               |  |
| Tabb Meadows                          | Big Bethel Road                         | MVES         | 14     | 13                | 1               |  |
| Tequesta Village                      | Heavens Way                             | MVES         | 15     | 7                 | 8               |  |
| Total MVES                            |                                         |              |        |                   | 19              |  |
| Sparrer Point                         | Sunset Drive                            | SES          | 3      | 2                 | 1               |  |
| Yorktown Crescent townhouses          | Ft. Eustis Blvd.                        | SES          | 36     | 34                | 2               |  |
| Total SES                             |                                         |              |        |                   | 3               |  |
| Arbordale - Phase IV (townhouses)     | Bulifants Boulevard                     | WMES         | 75     | 74                | 1               |  |
| Burgesses Quarters - SFA              | Bypass Road                             | WMES         | 97     | 79                | 18              |  |
| The Oaks at Fenton Mill               | Fenton Mill Rd                          | WMES         | 82     | 66                | 16              |  |
| Skimino Landing Estates               | Skimino Road                            | WMES         | 109    | 93                | 16              |  |
| Total WMES                            |                                         |              |        |                   | 51              |  |
| Huntfield                             | Crawford & Goosley Roads                | YES          | 7      | 6                 | 1               |  |
| Nelson's Grant condos                 | Route 17/Battle Road                    | YES          | 36     | 25                | 11<br><b>12</b> |  |
| Total YES                             |                                         |              |        |                   |                 |  |
| TOTAL ACTIVE                          |                                         |              |        |                   | 136             |  |

Table 10 – Pending Residential Developments by Attendance Zone

## **PENDING (Under Review)**

| Housing Development                      | Location                | School Zone | Lots/<br>Units | COs as of 10/1/22 | Future<br>Units |  |
|------------------------------------------|-------------------------|-------------|----------------|-------------------|-----------------|--|
|                                          | PENDING (Under Review)  |             |                |                   |                 |  |
| Pleasantville                            | Militia Court           | CES         | 7              | 0                 | 7               |  |
| Total CES                                | •                       |             |                |                   | 7               |  |
| Dawson Landing                           | Dare Road               | DES         | 6              | 0                 | 6               |  |
| Holly Point Farms                        | Holly Point Road        | DES         | 4              | 0                 | 4               |  |
| Lincoln-Dare Estates                     | Dare Road               | DES         | 3              | 0                 | 3               |  |
| Total DES                                |                         |             |                |                   | 13              |  |
| Country Club Acres, Sec, 5, Phases 2 & 3 | Tam-O-Shanter Boulevard | MES         | 66             | 0                 | 66              |  |
| The Marquis apartments                   | Marquis Parkway         | MES         | 265            | 0                 | 265             |  |
| Marquis Hills - Phase 3                  | Marquis Parkway         | MES         | 74             | 0                 | 74              |  |
| Total MES                                |                         |             |                |                   | 405             |  |
| Celestial Way                            | Heavens Way             | MVES        | 45             | 0                 | 45              |  |
| Smith Farms, Phase 2                     | Yorktown Road           | MVES        | 39             | 0                 | 39              |  |
| Total MVES                               |                         |             |                |                   | 84              |  |
| 409 Old Wormley Creek Road               | Old Wormlley Creek Road | SES         | 10             | 0                 | 10              |  |
| Total SES                                |                         |             |                |                   | 10              |  |
| Tabb Trace                               | Big Bethel Road         | TES         | 11             | 0                 | 11              |  |
| Total TES                                |                         |             |                |                   | 11              |  |
| Fenton Mill                              | Newman Road             | WMES        | 295            | 0                 | 295             |  |
| Fenton Mill 200                          | Fenton Mill Rd          | WMES        | 9              | 0                 | 9               |  |
| Powell Plantation - Phase 1              | Bypass Road             | WMES        | 129            | 0                 | 129             |  |
| Powell Plantation - Remainder            | Bypass Road             | WMES        | 197            | 0                 | 197             |  |
| Total WMES                               |                         |             |                |                   |                 |  |
| Rose Hill, Phase I                       | Baptist Road            | YES         | 39             | 0                 | 39              |  |
| Rose Hill, remainder                     | Baptist Road            | YES         | 203            | 0                 | 203             |  |
| Total YES                                |                         |             |                |                   |                 |  |
| TOTAL PENDING                            |                         |             |                |                   | 1,402           |  |

Table 11 – Planned Residential Developments by Attendance Zone

## Planned (Not yet under review)

| Housing Development                    | Location         | School<br>Zone |    | COs as of 10/1/22 | Future<br>Units |
|----------------------------------------|------------------|----------------|----|-------------------|-----------------|
| Smith Farm Estates - Phase 3           | Yorktown Road    | MVES           | 31 | 0                 | 31              |
| Total MVES                             |                  |                | •  |                   | 31              |
| Yorktown Crescent Ph. 2 - SFA          | Ft. Eustis Blvd. | SES            | 30 | 0                 | 30              |
| Yorktown Crescent Ph. 2 - Live Above   | Ft. Eustis Blvd. | SES            | 8  | 0                 | 8               |
| Yorktown Crescent Ph. 3+ (Rental Apts) | Ft. Eustis Blvd. | SES            | 64 | 0                 | 64              |
| Yorktown Crescent Ph. 3+ (Condos)      | Ft. Eustis Blvd. | SES            | 36 | 0                 | 36              |
| Total SES                              |                  |                |    |                   | 138             |
| Kelton Station live-above apartments   | Lightfoot Road   | WMES           | 12 | 0                 | 12              |
| Total WMES                             |                  |                | _  |                   | 12              |
| TOTAL PLANNED                          |                  |                |    |                   | 181             |

## Exhibit 6 – School Building Assessment Reports

These reports present the assessments of the school buildings as of October 13, 2021.

| ROOF 100 Hall 200 Hall 300/400 Hallways Excellent 100 Hall 100 Hall 200 Hall 300/400 Hallways Excellent Main Entrance Canopy Poor Replaced in 2017 Needs to enclose to prevent birds nesting Needs to enclose to prevent birds nesting Replaced in 2017 Needs to enclose to prevent birds nesting Needs to enclose to prevent birds nesting Replaced in 2017 Needs to enclose to prevent birds nesting Needs to enclose to prevent birds nesting Replaced in 2017 Needs to enclose to prevent birds nesting Replaced in 2017 Replaced  | BETHEL MANOR ELEMENTARY SCHOOL     |                |                                                 |  |  |  |  |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------|----------------|-------------------------------------------------|--|--|--|--|
| 100 Hall 200 Hall 200 Hall 200 Hall 300/400 Hallways Excellent Main Entrance Canopy Poor Needs to enclose to prevent birds nesting Poor Replaced in 2017 Replaced in 2017 Replaced fan shaft and bearings Replaced in 2017 Replaced fan shaft and bearings Replaced fan shaft and bearings Replaced in 2017 Replaced fan shaft and bearings Replaced fan shaft and bearings Replaced in 2017 Replaced fan shaft and bearings Replaced fan shaft and be | COMPONENT                          | CONDITION      | COMMENT                                         |  |  |  |  |
| Soft needed   Soft needed   Soft needed   Soft needed   2017   Social   Soft needed   2017   Social    | ROOF                               |                |                                                 |  |  |  |  |
| 300/400 Hallways Main Entrance Canopy HVAC 100 Hall 100 Hall 200 Hall 300/400 Hallways Excellent 300/400 Hallways Excellent 300/400 Hallways Excellent 300/400 Hallways Excellent 300/400 Hall 300/400 Hallways Excellent 300/400 Hall 300/400 Hall 300/400 Hall 300/400 Hall 300/400 Hall 300/400 Hall 300/400 Hallways Excellent 300/400 Hallw | 100 Hall                           | Poor           |                                                 |  |  |  |  |
| Main Entrance Canopy HVAC 100 Hall Fair 200 Hall Poor 300/400 Hallways Excellent Cooling Tower BUILDING ENVELOP Doors, Windows, Fascia 100 Hall Sood Windows, Fascia 100 Hall Sood Poor Windows need replacement Dinstalled on 2017 Windows need replacement Replacement Windows need replacement Windows need to be repaired/replaced 2019 Installed on blacktop 2019 Existing gym is too small  Windows need to be repaired/replaced 2019 Installed on blacktop 2019 Existing gym is too small  School needs a full size gymnasium Poor  CONCRETE & PAVEMENT Sidewalks Good Bus Loop Parking Lot Poor Additional parking capacity needed badly  Fair Mulch needs replacement Need to be repaired/                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         | 200 Hall                           | Excellent      | Roof coated in 2017                             |  |  |  |  |
| HVACC  100 Hall  200 Hall  300/400 Hallways  Cooling Tower  BUILDING ENVELOP  Doors, Windows, Fascia  100 Hall  200 Hall  300/400 Hallways  BUILDING ENVELOP  Doors, Windows, Fascia  100 Hall  300/400 Hallways  Excellent  300/400 Hallways  Excellent  Good  Windows need replacement  Windows replaced in 2017  Boody Excellent  Windows replaced in 2017  Installed security vestibule in 2017  Installed security vest | 300/400 Hallways                   | Excellent      |                                                 |  |  |  |  |
| 100 Hall                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       | Main Entrance Canopy               | Poor           | Needs to enclose to prevent birds nesting       |  |  |  |  |
| 200 Hall 300/400 Hallways Excellent Good Replaced in 2017 Replaced in 2017 Replaced fan shaft and bearings  BUILDING ENVELOP Doors, Windows, Fascia 100 Hall 200 Hall 300/400 Hallways Excellent Windows replaced in 2017 Windows replaced in 2017 Windows replaced in 2017 Windows replaced in 2017  FUMBING Good/Excellent Good Windows replaced in 2017  PUMBING 100 Hall Fair 300/400 Hallways Excellent Replaced in 2017  FIDORS  | HVAC                               |                |                                                 |  |  |  |  |
| Box    | 100 Hall                           | Fair           |                                                 |  |  |  |  |
| Cooling Tower  BUILDING ENVELOP Doors, Windows, Fascia 100 Hall 200 Hall 300/400 Hallways Excellent Windows replacement Windows replaced in 2017 Walls (Painting) FLUMBING 100 Hall 300/400 Hall 300/400 Hall 400 800 800 800 800 800 800 800 800 800                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          | 200 Hall                           | Poor           |                                                 |  |  |  |  |
| BUILDING ENVELOP  Doors, Windows, Fascia  100 Hall 200 Hall 300/400 Hallways Walls (Painting)  FUMBING 100 Hall 200 Hall 300/400 Hallways Walls (Painting)  Food  Fair FLORS  FICORS  FECURICAL 100 Hall 300/400 Hallways FECURITY & ALARMS FERRY MANAGEMENT SYSTEM FOOD  School needs a full size gymnasium Food  CONCRETE & PAVEMENT Sidewalks Bus Loop Farking Lot FAIR FAIR FROY FAIR FAIR FROY FAIR FROY FAIR FOOD FOOD FOOD FROY FAIR MUIch needs replacement Poved Athletic Surfaces FOOD FAIR Mulch needs replacement Need to be repaved                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   | 300/400 Hallways                   | Excellent      |                                                 |  |  |  |  |
| Doors, Windows, Fascia 100 Hall 200 Hall 200 Hall 300/400 Hallways Excellent Windows replaced in 2017  Windows replaced in 2017  FUMBING 100 Hall 200 Hall 300/400 Hallways Excellent Windows replaced in 2017  FUMBING 100 Hall Good 200 Hall 300/400 Hallways Excellent Renovated restrooms in 2017  FLOORS GOOd  ELECTRICAL 100 Hall Good 300/400 Hallways Excellent Wain electrical switchgear upgraded in 2017  ESCURITY & ALARMS Good ENERGY MANAGEMENT SYSTEM Excellent Windows need replacement Rood Main electrical switchgear upgraded in 2017  EXCELLANEOUS FIXTURES/EQUIPMENT Fair Good School needs a full size gymnasium Poor  CONCRETE & PAVEMENT Sidewalks Bus Loop Good Parking Lot GROUNDS Playground Equipment Fair Mulch needs replacement Mulch needs replacement Poor Need to be repaved                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 | Cooling Tower                      | Good           | Replaced fan shaft and bearings                 |  |  |  |  |
| 100 Hall 200 Hall 200 Hall 200 Hall 200 Hall 300/400 Hallways Excellent Windows replaced in 2017 Walls (Painting)  FluMBING 100 Hall 200 Hall 200 Hall 300/400 Hallways Food Excellent Good 200 Hall 300/400 Hallways Fair 100 Hall Fair Prinking fountains need replacement Renovated restrooms in 2017  FLOORS FLECTRICAL 100 Hall Good 300/400 Hallways Facellent Food Main electrical switchgear upgraded in 2017  SECURITY & ALARMS Food EXECURITY & ALARMS Food EXECURITY & ALARMS Food FOOD EXECURITY & ALARMS FOOD  FOOD FINENCY MANAGEMENT SYSTEM FOOD MODULAR Classrooms FOOD  SCHOOL RESTRUTES/EQUIPMENT Food Good School needs a full size gymnasium FOOT  CONCRETE & PAVEMENT Sidewalks Bus Loop Parking Lot FOOD FOOD FOOD FOOD FOOD FOOD FOOD FOO                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               | BUILDING ENVELOP                   |                |                                                 |  |  |  |  |
| 200 Hall     Poor Excellent     Windows need replacement       300/400 Hallways     Excellent     Windows replaced in 2017       Walls (Painting)     Good/Excellent     Installed security vestibule in 2017       PLUMBING       100 Hall     Good       200 Hall     Fair     Drinking fountains need replacement       300/400 Hallways     Excellent     Renovated restrooms in 2017       FLOORS       ELECTRICAL     Good     Main electrical switchgear upgraded in 2017       200 Hall     Good     Upgraded in 2017       300/400 Hallways     Excellent     Upgraded in 2017       SECURITY & ALARMS     Good       ENERGY MANAGEMENT SYSTEM     Excellent     Upgraded in 2017       MISCELLANEOUS FIXTURES/EQUIPMENT     Fair     Café Bi-fold doors need to be repaired/replaced 2019 installed on blacktop 2019       Existing gym is too small       CONCRETE & PAVEMENT       Sidewalks     Good       Bus Loop     Good       Parking Lot     Poor     Additional parking capacity needed badly       GROUNDS       Playground Equipment     Fair     Mulch needs replacement       Paved Athletic Surfaces     Poor     Need to be repaved                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  | Doors, Windows, Fascia             |                |                                                 |  |  |  |  |
| Second   S   | 100 Hall                           | Good           |                                                 |  |  |  |  |
| Walls (Painting) Good/Excellent  PLUMBING 100 Hall 200 Hall 300/400 Hallways Excellent Fair FLOORS Good ELECTRICAL 100 Hall 300/400 Hallways Excellent Floors Good ELECTRICAL 100 Hall Good 300/400 Hallways Excellent Fair Good Belectrical switchgear upgraded in 2017  FECURITY & ALARMS FOOD ENERGY MANAGEMENT SYSTEM FINENGY MANAGEMENT SYSTEM FINENGY MANAGEMENT SYSTEM FINENGY MANAGEMENT SYSTEM FOOD FOOD FOOD FOOD FOOD FOOD FOOD FOO                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 | 200 Hall                           | Poor           | Windows need replacement                        |  |  |  |  |
| PLUMBING  100 Hall  200 Hall  300/400 Hallways  Excellent  Fair  FlOORS  Good  ELECTRICAL  100 Hall  300/400 Hallways  Excellent  Fair  FlOORS  Good  ELECTRICAL  100 Hall  Good  300/400 Hallways  Excellent  Good  Wain electrical switchgear upgraded in 2017  Excellent  Upgraded in 2017  EXCEURITY & ALARMS  Good  ENERGY MANAGEMENT SYSTEM  MISCELLANEOUS FIXTURES/EQUIPMENT  MISCELLANEOUS FIXTURES/EQUIPMENT  Fair  Café Bi-fold doors need to be repaired/replaced 2019 Installed on blacktop 2019  Existing gym is too small  CONCRETE & PAVEMENT  Sidewalks  Bus Loop  Parking Lot  Poor  Additional parking capacity needed badly  GROUNDS  Playground Equipment  Paved Athletic Surfaces  Poor  Need to be repaved                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               | 300/400 Hallways                   | Excellent      | Windows replaced in 2017                        |  |  |  |  |
| 100 Hall 200 Hall 300/400 Hallways Excellent Renovated restrooms in 2017  FLOORS Good  ELECTRICAL 100 Hall 300/400 Hallways EXCELLANEOUS FIXTURES/EQUIPMENT Sidewalks Bus Loop Parking Lot  GOOD  GROUNDS  Playground Equipment Paved Athletic Surfaces  Pood  Fair  Drinking fountains need replacement Renovated restrooms in 2017  Provincing fountains need replacement Renovated restrooms in 2017  Renovated restrooms in 2017  Main electrical switchgear upgraded in 2017  Dygraded in 2017  Excellent Upgraded in 2017  Café Bi-fold doors need to be repaired/replaced 2019 Installed on blacktop 2019  Existing gym is too small  Existing gym is too small  Additional parking capacity needed badly  Mulch needs replacement Poor Need to be repaived                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           | Walls (Painting)                   | Good/Excellent | Installed security vestibule in 2017            |  |  |  |  |
| 200 Hall 300/400 Hallways Excellent Renovated restrooms in 2017  FLOORS GOOD  ELECTRICAL 100 Hall GOOD 300/400 Hallways Excellent GOOD Hall GOOD 300/400 Hallways Excellent Upgraded in 2017  SECURITY & ALARMS GOOD ENERGY MANAGEMENT SYSTEM EXCELLANEOUS FIXTURES/EQUIPMENT MISCELLANEOUS FIXTURES/EQUIPMENT Fair Café Bi-fold doors need to be repaired/replaced 2019 Installed on blacktop 2019 Existing gym is too small  School needs a full size gymnasium Poor  CONCRETE & PAVEMENT Sidewalks Bus Loop Parking Lot Poor Additional parking capacity needed badly  GROUNDS Playground Equipment Paved Athletic Surfaces Poor Need to be repaved                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         | PLUMBING                           |                |                                                 |  |  |  |  |
| ### Support of the image of the | 100 Hall                           | Good           |                                                 |  |  |  |  |
| FLOORS  ELECTRICAL  100 Hall  200 Hall  300/400 Hallways  EXCellent  SECURITY & ALARMS  ENERGY MANAGEMENT SYSTEM  MISCELLANEOUS FIXTURES/EQUIPMENT  MISCELLANEOUS FIXTURES/EQUIPMENT  Fair  Café Bi-fold doors need to be repaired/replaced 2019 Installed on blacktop 2019  Existing gym is too small  CONCRETE & PAVEMENT  Sidewalks  Bus Loop  Parking Lot  GROUNDS  Playground Equipment  Poor  Main electrical switchgear upgraded in 2017  Main electrical switchgear upgraded in 2017  Main electrical switchgear upgraded in 2017  Copyraded in 2017  Café Bi-fold doors need to be repaired/replaced 2019 Installed on blacktop 2019  Existing gym is too small  Fair  Additional parking capacity needed badly  GROUNDS  Playground Equipment  Fair  Mulch needs replacement  Paved Athletic Surfaces  Poor  Need to be repaved                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      | 200 Hall                           | Fair           | Drinking fountains need replacement             |  |  |  |  |
| ELECTRICAL  100 Hall  200 Hall  300/400 Hallways  Excellent  Upgraded in 2017  SECURITY & ALARMS  ENERGY MANAGEMENT SYSTEM  MISCELLANEOUS FIXTURES/EQUIPMENT  Modular Classrooms  School needs a full size gymnasium  CONCRETE & PAVEMENT  Sidewalks  Bus Loop Parking Lot  GROUNDS  Playground Equipment Poor  Main electrical switchgear upgraded in 2017  Main electrical switchgear upgraded in 2017  Upgraded in 2017  Café Bi-fold doors need to be repaired/replaced 2019 Installed on blacktop 2019  Existing gym is too small  Fair  Additional parking capacity needed badly  GROUNDS  Playground Equipment Paved Athletic Surfaces  Poor  Need to be repaved                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        | 300/400 Hallways                   | Excellent      | Renovated restrooms in 2017                     |  |  |  |  |
| 100 Hall 200 Hall 300/400 Hallways Excellent  SECURITY & ALARMS Good ENERGY MANAGEMENT SYSTEM Excellent  MISCELLANEOUS FIXTURES/EQUIPMENT Modular Classrooms  School needs a full size gymnasium CONCRETE & PAVEMENT Sidewalks Bus Loop Parking Lot GROUNDS Playground Equipment Poor  Mulch needs replacement Paved Athletic Surfaces  Main electrical switchgear upgraded in 2017  Main electrical switchgear upgraded in 2017  Main electrical switchgear upgraded in 2017  Dygraded in 2017  Café Bi-fold doors need to be repaired/replaced 2019 Installed on blacktop 2019 Existing gym is too small  Café Bi-fold doors need to be repaired/replaced 2019 Installed on blacktop 2019 Existing gym is too small  Additional parking capacity needed badly  ROUNDS Playground Equipment Paved Athletic Surfaces Poor Need to be repaved                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   | FLOORS                             | Good           |                                                 |  |  |  |  |
| 200 Hall 300/400 Hallways Excellent Upgraded in 2017  SECURITY & ALARMS Good ENERGY MANAGEMENT SYSTEM Excellent Upgraded in 2017  MISCELLANEOUS FIXTURES/EQUIPMENT Fair Café Bi-fold doors need to be repaired/replaced 2019 Installed on blacktop 2019 Existing gym is too small  School needs a full size gymnasium Poor  CONCRETE & PAVEMENT Sidewalks Good Bus Loop Parking Lot GROUNDS Playground Equipment Poor Mulch needs replacement Poor Need to be repaved                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          | ELECTRICAL                         |                |                                                 |  |  |  |  |
| 300/400 HallwaysExcellentUpgraded in 2017SECURITY & ALARMSGoodENERGY MANAGEMENT SYSTEMExcellentUpgraded in 2017MISCELLANEOUS FIXTURES/EQUIPMENTFairCafé Bi-fold doors need to be repaired/replaced 2019 Installed on blacktop 2019Modular ClassroomsGoodExisting gym is too smallSchool needs a full size gymnasiumPoorCONCRETE & PAVEMENTGoodSidewalksGoodBus LoopGoodParking LotPoorAdditional parking capacity needed badlyGROUNDSFairMulch needs replacementPlayground EquipmentFairMulch needs replacementPaved Athletic SurfacesPoorNeed to be repaved                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   | 100 Hall                           | Good           | Main electrical switchgear upgraded in 2017     |  |  |  |  |
| SECURITY & ALARMS  ENERGY MANAGEMENT SYSTEM  Excellent  MISCELLANEOUS FIXTURES/EQUIPMENT  Modular Classrooms  School needs a full size gymnasium  Poor  CONCRETE & PAVEMENT  Sidewalks  Bus Loop  Parking Lot  GROUNDS  Playground Equipment  Paved Athletic Surfaces  Fair  Good  Lypgraded in 2017  Café Bi-fold doors need to be repaired/replaced 2019 Installed on blacktop 2019  Existing gym is too small  Existing gym is too small  Additional parking capacity needed badly  Mulch needs replacement  Need to be repaved                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             | 200 Hall                           | Good           |                                                 |  |  |  |  |
| ENERGY MANAGEMENT SYSTEM  MISCELLANEOUS FIXTURES/EQUIPMENT  Fair  Café Bi-fold doors need to be repaired/replaced 2019 Installed on blacktop 2019 Existing gym is too small  School needs a full size gymnasium  Poor  CONCRETE & PAVEMENT Sidewalks Bus Loop Parking Lot  Good Parking Lot  Poor  Additional parking capacity needed badly  GROUNDS  Playground Equipment Paved Athletic Surfaces  Poor  Need to be repaved                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   | 300/400 Hallways                   | Excellent      | Upgraded in 2017                                |  |  |  |  |
| MISCELLANEOUS FIXTURES/EQUIPMENT Fair Café Bi-fold doors need to be repaired/replaced 2019 Installed on blacktop 2019 Existing gym is too small  School needs a full size gymnasium Poor  CONCRETE & PAVEMENT Sidewalks Good Bus Loop Good Parking Lot Poor Additional parking capacity needed badly  GROUNDS Playground Equipment Paved Athletic Surfaces Poor Need to be repaired/replaced 2019 Installed on blacktop 2019 Existing gym is too small  Additional parking gym is too small  Existing gym is too small  Additional parking capacity needed badly  Mulch needs replacement Need to be repaved                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   | SECURITY & ALARMS                  | Good           |                                                 |  |  |  |  |
| Modular Classrooms  Good  Existing gym is too small  School needs a full size gymnasium  Poor  CONCRETE & PAVEMENT  Sidewalks  Good  Bus Loop  Parking Lot  Poor  Additional parking capacity needed badly  GROUNDS  Playground Equipment  Paved Athletic Surfaces  Poor  Need to be repaved                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   | ENERGY MANAGEMENT SYSTEM           | Excellent      | Upgraded in 2017                                |  |  |  |  |
| Modular ClassroomsGoodExisting gym is too smallSchool needs a full size gymnasiumPoorCONCRETE & PAVEMENTGoodSidewalksGoodBus LoopGoodParking LotPoorAdditional parking capacity needed badlyGROUNDSPlayground EquipmentFairMulch needs replacementPaved Athletic SurfacesPoorNeed to be repaved                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                | MISCELLANEOUS FIXTURES/EQUIPMENT   | Fair           | Café Bi-fold doors need to be repaired/replaced |  |  |  |  |
| CONCRETE & PAVEMENT  Sidewalks  Good  Bus Loop  Parking Lot  GROUNDS  Playground Equipment  Paved Athletic Surfaces  Good  Fair  Poor  Mulch needs replacement  Need to be repaved                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             | Modular Classrooms                 | Good           | •                                               |  |  |  |  |
| CONCRETE & PAVEMENT  Sidewalks  Good  Bus Loop  Parking Lot  GROUNDS  Playground Equipment  Paved Athletic Surfaces  Good  Fair  Poor  Mulch needs replacement  Need to be repaved                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             | School needs a full size gymnasium | Poor           |                                                 |  |  |  |  |
| Sidewalks  Bus Loop  Parking Lot  Good  Poor  Additional parking capacity needed badly  GROUNDS  Playground Equipment  Paved Athletic Surfaces  Fair  Poor  Need to be repaved                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 |                                    | . 551          |                                                 |  |  |  |  |
| Bus Loop Parking Lot Poor Additional parking capacity needed badly  GROUNDS Playground Equipment Paved Athletic Surfaces Poor Poor Need to be repaved                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          |                                    | Good           |                                                 |  |  |  |  |
| Parking Lot Poor Additional parking capacity needed badly  GROUNDS Playground Equipment Paved Athletic Surfaces Poor Additional parking capacity needed badly  Hulch needs replacement Need to be repaved                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |                                    |                |                                                 |  |  |  |  |
| GROUNDS Playground Equipment Fair Mulch needs replacement Paved Athletic Surfaces Poor Need to be repaved                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      | •                                  |                | Additional parking capacity needed badly        |  |  |  |  |
| Playground Equipment Fair Mulch needs replacement Paved Athletic Surfaces Poor Need to be repaved                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |                                    |                |                                                 |  |  |  |  |
| Paved Athletic Surfaces Poor Need to be repaved                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |                                    | Fair           | Mulch needs replacement                         |  |  |  |  |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |                                    |                | •                                               |  |  |  |  |
| Authoric Fichal                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                | Athletic Fields                    | Good           |                                                 |  |  |  |  |

| COVENTR                          | COVENTRY ELEMENTARY SCHOOL |                                         |  |  |  |  |  |
|----------------------------------|----------------------------|-----------------------------------------|--|--|--|--|--|
| COMPONENT                        | CONDITION                  | COMMENT                                 |  |  |  |  |  |
| ROOF                             |                            |                                         |  |  |  |  |  |
| Metal                            | Excellent                  | Replaced 2019                           |  |  |  |  |  |
| Built Up Low Slope               | Satisfactory               |                                         |  |  |  |  |  |
| Gym                              | Poor                       | Concerns with Suprema cap sheet         |  |  |  |  |  |
| HVAC                             |                            |                                         |  |  |  |  |  |
| Original Building                | Excellent                  | Replaced 200 wing condensing units      |  |  |  |  |  |
|                                  |                            | August 2018                             |  |  |  |  |  |
| 1996 Additions                   | Excellent                  | Replaced in 2020                        |  |  |  |  |  |
| BUILDING ENVELOP                 |                            |                                         |  |  |  |  |  |
| Doors, Windows, Fascia           |                            |                                         |  |  |  |  |  |
| Original Building                | Poor                       | Window seals failed-replacement         |  |  |  |  |  |
|                                  |                            | needed                                  |  |  |  |  |  |
| 1996 Additions                   | Good                       |                                         |  |  |  |  |  |
| Walls (Painting)                 | Excellent                  | Exterior painted in 2019                |  |  |  |  |  |
| PLUMBING                         | Fair                       | Need to replace fixtures and water      |  |  |  |  |  |
|                                  |                            | heaters                                 |  |  |  |  |  |
| FLOORS                           | Good                       |                                         |  |  |  |  |  |
| ELECTRICAL                       | Fair/Excellent             | Lighting in main building needs to be   |  |  |  |  |  |
|                                  |                            | replaced, addition lighting replaced in |  |  |  |  |  |
|                                  |                            | 2020                                    |  |  |  |  |  |
| SECURITY & ALARMS                | Good                       | Created security vestibule 2019         |  |  |  |  |  |
| P.A. System                      | Excellent                  | PA system replaced 2020                 |  |  |  |  |  |
| ENERGY MANAGEMENT SYSTEM         | Excellent                  | Replaced in 2020                        |  |  |  |  |  |
| MISCELLANEOUS FIXTURES/EQUIPMENT | Good                       |                                         |  |  |  |  |  |
| CONCRETE & PAVEMENT              |                            |                                         |  |  |  |  |  |
| Sidewalks                        | Good                       | Some sidewalks repaired                 |  |  |  |  |  |
| Bus Loop                         | Good                       |                                         |  |  |  |  |  |
| Parking Lot                      | Good                       | Additional parking needed               |  |  |  |  |  |
| GROUNDS                          |                            |                                         |  |  |  |  |  |
| Playground Equipment             | Fair                       | Mulch needs replacement                 |  |  |  |  |  |
| Paved Athletic Surfaces          | Good                       | Modular classroom is on pavement        |  |  |  |  |  |
| Athletic Fields                  | Good                       | Sprigged soccer field 2019              |  |  |  |  |  |

| DARE E                           | DARE ELEMENTARY SCHOOL |                                           |  |  |  |  |  |
|----------------------------------|------------------------|-------------------------------------------|--|--|--|--|--|
| COMPONENT                        | CONDITION              | COMMENT                                   |  |  |  |  |  |
| ROOF                             |                        |                                           |  |  |  |  |  |
| Original Building                | Excellent              | Blisters repaired, roof coated 2019       |  |  |  |  |  |
| Gym                              | Good                   |                                           |  |  |  |  |  |
| 2009 Additions                   | Excellent              | Blisters repaired, roof coated 2019       |  |  |  |  |  |
| HVAC                             |                        |                                           |  |  |  |  |  |
| Original Building                | Good                   |                                           |  |  |  |  |  |
| Gym                              | Fair                   | Replacement needs to be scheduled         |  |  |  |  |  |
| 2009 Additions                   | Good                   |                                           |  |  |  |  |  |
| BUILDING ENVELOP                 |                        |                                           |  |  |  |  |  |
| Doors, Windows, Fascia           |                        |                                           |  |  |  |  |  |
| Original Building                | Good                   |                                           |  |  |  |  |  |
| 2009 Additions                   | Good                   |                                           |  |  |  |  |  |
| Walls (Painting)                 | Good                   |                                           |  |  |  |  |  |
|                                  |                        |                                           |  |  |  |  |  |
| PLUMBING                         | Fair                   | Restrooms need renovation                 |  |  |  |  |  |
| FLOORS                           | Good                   | Gym floor replaced 2019                   |  |  |  |  |  |
| ELECTRICAL                       | Poor                   | Lighting and breaker panels need to be    |  |  |  |  |  |
| Lighting                         |                        | replaced                                  |  |  |  |  |  |
| Clocks                           | Poor                   | Clocks need to be replaced                |  |  |  |  |  |
| SECURITY & ALARMS                | Good                   | Installed security vestibule 2018         |  |  |  |  |  |
| ENERGY MANAGEMENT SYSTEM         | Good                   |                                           |  |  |  |  |  |
| MISCELLANEOUS FIXTURES/EQUIPMENT | Excellent              | Gym breezeway enclosed 2020               |  |  |  |  |  |
| Casework                         | Poor                   | Casework throughout the building          |  |  |  |  |  |
|                                  |                        | needs to be replaced                      |  |  |  |  |  |
| CONCRETE & PAVEMENT              |                        |                                           |  |  |  |  |  |
| Sidewalks                        | Excellent              | Repairs made 2018/2019                    |  |  |  |  |  |
| Bus Loop                         | Good                   | Needs to be redesigned                    |  |  |  |  |  |
| Parking Lot                      | Fair                   | Need additional parking and to            |  |  |  |  |  |
|                                  |                        | separate bus traffic from vehicle traffic |  |  |  |  |  |
| GROUNDS                          |                        |                                           |  |  |  |  |  |
| Playground Equipment             | Fair                   | Mulch needs replacement                   |  |  |  |  |  |
| Paved Athletic Surfaces          | Excellent/Fair         | Extend Center blacktop needs repaving     |  |  |  |  |  |
| Athletic Fields                  | Good                   |                                           |  |  |  |  |  |

| GRAFT                                              | ON BETHEL ELEN     | MENTARY SCHOOL                                                                                                                |
|----------------------------------------------------|--------------------|-------------------------------------------------------------------------------------------------------------------------------|
| COMPONENT                                          | CONDITION          | COMMENT                                                                                                                       |
| ROOF                                               | Good/Poor          | New membrane installed over Kindergarten wing 2018 Existing roof needs to have new cap sheet installed due to faulty material |
| HVAC                                               | Good               |                                                                                                                               |
| BUILDING ENVELOP                                   |                    |                                                                                                                               |
| Doors, Windows, Fascia                             | Good               |                                                                                                                               |
| Walls (Painting)                                   | Good               | Need to pressure wash exterior                                                                                                |
| PLUMBING                                           | Good               |                                                                                                                               |
| <b>FLOORS</b><br>Kitchen                           | Good<br>Excellent  | Replaced kitchen VCT                                                                                                          |
| ELECTRICAL                                         | Good               |                                                                                                                               |
| Clocks                                             | Excellent          | Replaced in 2019                                                                                                              |
| Lighting                                           | Excellent<br>/Poor | Library and 4&5 grade classrooms need new LED lighting                                                                        |
| SECURITY & ALARMS                                  | Good               |                                                                                                                               |
| P.A. System                                        | Excellent          | Replaced in 2019                                                                                                              |
| ENERGY MANAGEMENT SYSTEM                           | Good               |                                                                                                                               |
| MISCELLANEOUS FIXTURES/EQUIPMENT Modular Classroom | Good<br>Good       | Replaced ceiling tile 2018 Installed one in 2019 and a second on tennis court and a third on basketball court in 2020         |
| Kitchen Serving Lines                              | Excellent          | Installed two new serving lines                                                                                               |
| CONCRETE & PAVEMENT                                |                    |                                                                                                                               |
| Sidewalks                                          | Good               |                                                                                                                               |
| Bus Loop                                           | Good               |                                                                                                                               |
| Parking Lot                                        | Good/Fair          | Front parking lot needs repaving                                                                                              |
| GROUNDS                                            |                    |                                                                                                                               |
| Playground Equipment                               | Fair               | Mulch needs replacement                                                                                                       |
| Paved Athletic Surfaces                            | Good               | Modular classrooms are on paved surfaces                                                                                      |
| Athletic Fields                                    | Good               |                                                                                                                               |

| MAGRUDER ELEMENTARY SCHOOL       |           |                                              |
|----------------------------------|-----------|----------------------------------------------|
| COMPONENT                        | CONDITION | COMMENT                                      |
| ROOF                             | Excellent |                                              |
| HVAC                             |           |                                              |
| Original Building                | Excellent |                                              |
| 1997/2008 Additions              | Good      | Replaced shaft on cooling tower              |
| BUILDING ENVELOP                 |           |                                              |
| Doors, Windows, Fascia           | Good      | Need to replace multiple exterior doors      |
| Walls (Painting)                 | Good      | · · ·                                        |
| PLUMBING                         | Good      |                                              |
| FLOORS                           | Good      |                                              |
| ELECTRICAL                       | Good      |                                              |
| SECURITY & ALARMS                | Good      |                                              |
| Security Vestibule               | Fair      |                                              |
| P.A. System                      | Fair      | Need to redesign existing security vestibule |
| ENERGY MANAGEMENT SYSTEM         | Good      |                                              |
| MISCELLANEOUS FIXTURES/EQUIPMENT |           |                                              |
| 2 Classroom Modular              | Fair      |                                              |
| 4 Classroom Modular              | Good      | Currently under lease from Mobilease         |
| Restroom Partitions              | Poor      | Need to schedule replacement                 |
| CONCRETE & PAVEMENT              |           |                                              |
| Sidewalks                        | Good/Fair | Need to repair front sidewalks               |
| Bus Loop                         | Fair      | Need additional bus parking                  |
| Parking Lot                      | Fair      | Need additional vehicle parking badly        |
| GROUNDS                          |           |                                              |
| Playground Equipment             | Fair      | Need to replace mulch                        |
| Paved Athletic Surfaces          | Good      |                                              |
| Athletic Fields                  | Good      |                                              |

| MOUNT VERNON ELEMENTARY SCHOOL   |           |                                                       |
|----------------------------------|-----------|-------------------------------------------------------|
| COMPONENT                        | CONDITION | COMMENT                                               |
| ROOF                             |           |                                                       |
| Original Building                | Poor      | Few leaks along A wing hallway, B wing                |
|                                  |           | needs roof repaired or replaced, some gutters leaking |
| 2010 Addition                    | Good      | gutters reaking                                       |
| HVAC                             |           |                                                       |
| Original Building                | Poor      | All HVAC equipment replacement                        |
|                                  |           | needed soon                                           |
| 2010 Addition                    | Good      |                                                       |
| BUILDING ENVELOP                 |           |                                                       |
| Security Vestibule               |           | Security vestibule installed 2019                     |
| Enclosed Breezeway               |           | Enclosed breezeway 2020                               |
| Doors, Windows, Fascia           | Good      |                                                       |
| Walls (Painting)                 | Good/Fair |                                                       |
| PLUMBING                         |           |                                                       |
| Restrooms                        | Fair/Poor | Restrooms need renovation                             |
|                                  |           | Drinking fountains need to be replaced                |
| Drinking Fountains               | Poor      |                                                       |
| FLOORS                           | Good/Poor | Gym floor replaced 2019                               |
| ELECTRICAL                       | Good      |                                                       |
| SECURITY & ALARMS                | Good      |                                                       |
| P.A. System                      | Excellent | Replaced in 2019                                      |
| ENERGY MANAGEMENT SYSTEM         | Poor      | Need to replace old Novar system                      |
| MISCELLANEOUS FIXTURES/EQUIPMENT | Good      | Installed Solatube Lights in Library                  |
|                                  |           | Installed on paved surface 2020                       |
| Modular classroom                |           |                                                       |
| CONCRETE & PAVEMENT              |           |                                                       |
| Sidewalks                        | Good      |                                                       |
| Bus Loop                         | Excellent | Repaved 2018                                          |
| Parking Lot                      | Excellent | Repaved 2018                                          |
| GROUNDS                          |           |                                                       |
| Playground Equipment             | Fair      | Need to replace mulch                                 |
| Paved Athletic Surfaces          | Good      |                                                       |
| Athletic Fields                  | Good      |                                                       |

| SEAFORD ELEMENTARY SCHOOL           |              |                                                                               |  |  |
|-------------------------------------|--------------|-------------------------------------------------------------------------------|--|--|
| COMPONENT CONDITION COMMENT         |              |                                                                               |  |  |
| ROOF                                |              |                                                                               |  |  |
| Original Building                   | Poor         | Roof needs to be coated                                                       |  |  |
| Gym                                 | Good         |                                                                               |  |  |
| 2014 Addition                       | Good         |                                                                               |  |  |
| HVAC                                |              |                                                                               |  |  |
| Original Building                   | Good/Poor    | Need new make-up air units                                                    |  |  |
| Gym                                 | Excellent    | Replaced condensing unit 2019                                                 |  |  |
| 2014 Addition                       | Good         |                                                                               |  |  |
| BUILDING ENVELOP                    |              |                                                                               |  |  |
| Doors, Windows, Fascia              |              |                                                                               |  |  |
| Original Building                   | Poor         | Original single pane windows and exterior doors need to be replaced very soon |  |  |
| Gym                                 | Good         |                                                                               |  |  |
| 2014 Addition                       | Good         |                                                                               |  |  |
| Walls (Painting)                    | Good         |                                                                               |  |  |
| PLUMBING                            |              |                                                                               |  |  |
| Restrooms                           | Poor         | Original restrooms need renovation Drinking fountains need to be replaced     |  |  |
| Drinking Fountains                  | Poor         |                                                                               |  |  |
| FLOORS                              |              |                                                                               |  |  |
| VCT                                 | Good         |                                                                               |  |  |
| Gym floor                           | Poor         | Gym floor to be replaced in 2021                                              |  |  |
| ELECTRICAL  Main Switch has and     | D            | Main switchboard and original breaker                                         |  |  |
| Main Switchboard<br>Breaker Panels  | Poor<br>Poor | panels need to be replaced soon Old lights need to be replaced                |  |  |
| Lighting                            | Poor         | Old lights fleed to be replaced                                               |  |  |
| SECURITY & ALARMS                   | Good         | Security vestibule installed 2018                                             |  |  |
| P.A. System                         | Poor         | Need to replace original system soon                                          |  |  |
| ENERGY MANAGEMENT SYSTEM            | Poor         | Need to replace old Novar system                                              |  |  |
| MISCELLANEOUS FIXTURES/EQUIPMENT    |              | ,                                                                             |  |  |
| Interior Doors                      | Poor         | Need to replace interior doors                                                |  |  |
| Kitchen Equipment                   | Fair         | Need to replace some equipment                                                |  |  |
| CONCRETE & PAVEMENT                 |              |                                                                               |  |  |
| Sidewalks                           | Good         |                                                                               |  |  |
| Bus Loop                            | Fair/Poor    | Need additional spaces in bus loop                                            |  |  |
| Parking Lot                         | Fair/Poor    | Need additional parking and to repave existing parking                        |  |  |
| GROUNDS                             |              |                                                                               |  |  |
| Playground Equipment – 17 years old | Fair         | Need to replace mulch and possibly replace equipment                          |  |  |
| Paved Athletic Surfaces             | Excellent    | Basketball court was repaved and new goals were installed                     |  |  |
| Athletic Fields                     | Good         |                                                                               |  |  |

| TABB ELEMENTARY SCHOOL           |                |                                                                                            |
|----------------------------------|----------------|--------------------------------------------------------------------------------------------|
| COMPONENT                        | CONDITION      | COMMENT                                                                                    |
| ROOF                             |                |                                                                                            |
| Original Building                | Excellent      | Partial roof replaced summer 2018, remainder of roof replaced summer 2019                  |
| Gym                              | Excellent      | Was coated in 2018                                                                         |
| 2013 Addition                    | Good           |                                                                                            |
| HVAC                             |                |                                                                                            |
| Original Building                | Excellent      | Replaced system in 2018                                                                    |
| Gym                              | Good           |                                                                                            |
| 2013 Addition                    | Good           |                                                                                            |
| BUILDING ENVELOP                 |                |                                                                                            |
| Doors, Windows, Fascia           | Excellent      | Doors/windows replaced 2019                                                                |
| Original Building                | Excellent      | Soffits repaired 2019                                                                      |
| Gym                              | Excellent      | Windows replaced summer 2019                                                               |
| 2013 Addition                    | Good           |                                                                                            |
| Walls (Painting)                 | Good           | Original building painted 2018                                                             |
| PLUMBING                         | Good/Excellent | Original restrooms renovated 2018                                                          |
| FLOORS                           | Good           | Front office carpeted 2018                                                                 |
| ELECTRICAL                       | Good/Excellent | LED lighting installed in original building 2018  Main switchboard replaced 2018           |
| SECURITY & ALARMS                | Excellent      | System replaced 2018                                                                       |
| ENERGY MANAGEMENT SYSTEM         | Excellent      | System replaced 2018                                                                       |
| MISCELLANEOUS FIXTURES/EQUIPMENT | Excellent      | Doors and hardware replaced 2019                                                           |
| CONCRETE & PAVEMENT              |                |                                                                                            |
| Sidewalks                        | Good           | Partial sidewalk replacement 2018                                                          |
| Bus Loop                         | Good           |                                                                                            |
| Parking Lot                      | Poor/          | Main entrance loop needs to be                                                             |
|                                  | Good           | repaved Parking lot striped 2019                                                           |
| GROUNDS                          |                | . a. mig for striped 2013                                                                  |
| Playground Equipment             | Poor           | Severe drainage issues- repair needed soon- need to secure funding Mulch needs replacement |
| Paved Athletic Surfaces          | Good           | ·                                                                                          |
| Athletic Fields                  | Good           |                                                                                            |

| WALLER MILL ELEMENTARY FINE ARTS MAGNET SCHOOL |           |                                                                     |  |
|------------------------------------------------|-----------|---------------------------------------------------------------------|--|
| COMPONENT                                      | CONDITION | COMMENT                                                             |  |
| ROOF                                           | Excellent | Recovered 2016-2017                                                 |  |
| HVAC                                           | Excellent | Replaced 2016-17                                                    |  |
| BUILDING ENVELOP                               |           |                                                                     |  |
| Doors, Windows, Fascia                         | Excellent | Replaced 2016-17                                                    |  |
| Walls (Painting)                               | Excellent | Repainted 2016-17                                                   |  |
| PLUMBING                                       | Excellent | Replaced 2016-17                                                    |  |
| FLOORS                                         | Excellent | Replaced 2016-17 Gym floor logo needs replacement                   |  |
| ELECTRICAL                                     |           |                                                                     |  |
| Main Switchboard                               | Excellent | Replaced 2016-17                                                    |  |
| Breaker Panels                                 | Fair      | Should replace original FPE panels                                  |  |
| SECURITY & ALARMS                              |           |                                                                     |  |
| P.A. System                                    | Good      | Replaced 2016-17                                                    |  |
| ENERGY MANAGEMENT SYSTEM                       | Excellent | Replaced 2016-17                                                    |  |
| MISCELLANEOUS FIXTURES/EQUIPMENT               | Excellent | Replaced 2016-17                                                    |  |
| CONCRETE & PAVEMENT                            |           |                                                                     |  |
| Sidewalks                                      | Good      | Replaced 2016-17-some sidewalks in front of the school are settling |  |
| Bus Loop                                       | Excellent | Repaved 2017                                                        |  |
| Parking Lot                                    | Excellent | Expanded and repaved in 2016-17                                     |  |
| GROUNDS                                        |           |                                                                     |  |
| Playground Equipment                           | Excellent | Relocated in 2017                                                   |  |
| Paved Athletic Surfaces                        | Excellent | Repaved 2018                                                        |  |
| Athletic Fields                                | Good      |                                                                     |  |

| YORKTOWN ELEMENTARY MATH, SCIENCE & TECHNOLOGY MAGNET SCHOOL |                |                                         |
|--------------------------------------------------------------|----------------|-----------------------------------------|
| COMPONENT                                                    | CONDITION      | COMMENT                                 |
| ROOF                                                         |                |                                         |
| Original Building                                            | Excellent      | Roof replaced 2017                      |
| Gym                                                          | Excellent      | Roof coated 2017                        |
| 2009 Addition                                                | Good           |                                         |
| HVAC                                                         |                |                                         |
| Original Building                                            | Excellent      | HVAC replaced summer 2017               |
| Gym                                                          | Good           | Boiler replaced 2017                    |
| 2009 Addition                                                | Good           |                                         |
| BUILDING ENVELOP                                             |                |                                         |
| Doors, Windows, Fascia                                       |                |                                         |
| Original Building                                            | Good/Fair      | Some original exterior doors need to    |
| -<br>-                                                       |                | be replaced                             |
| Gym                                                          | Good           | Windows replaced summer 2017            |
| 2009 Addition                                                | Good           | Painted 2017                            |
| Walls (painting)                                             | Excellent      | Painted 2017                            |
| PLUMBING                                                     | Good/Excellent | Main restrooms renovated summer         |
|                                                              |                | 2017                                    |
|                                                              |                | Classroom restrooms retiled summer      |
|                                                              | - " .          | 2018                                    |
| FLOORS                                                       | Excellent      | Gym floor replaced 2017                 |
| ELECTRICAL                                                   | Good/Excellent | Main switchgear replaced summer         |
|                                                              |                | 2017 LED lighting installed in original |
|                                                              |                | building 2017                           |
| SECURITY & ALARMS                                            |                | building 2017                           |
| P.A. System                                                  | Excellent      | System replaced 2017                    |
| ENERGY MANAGEMENT SYSTEM                                     | Excellent      | System replaced 2017                    |
| MISCELLANEOUS FIXTURES/EQUIPMENT                             | Good           | Replaced ceiling tile 2018              |
| CONCRETE & PAVEMENT                                          |                |                                         |
| Sidewalks                                                    | Good/Excellent | Installed new sidewalks near addition   |
|                                                              |                | and head start trailer                  |
| Bus Loop                                                     | Good           |                                         |
| Parking Lot                                                  | Excellent      | Additional parking completed            |
| GROUNDS                                                      |                |                                         |
| Playground Equipment                                         | Fair           | Mulch needs replacement                 |
| Paved Athletic Surfaces                                      | N/A            | Modular building placed on basketball   |
|                                                              |                | court 2016                              |
| Athletic Fields                                              | Good           |                                         |
| Head Start Trailer                                           | N/A            | Relocated to other side of school 2016  |

| QUEENS LAKE MIDDLE SCHOOL        |              |                                                                                   |
|----------------------------------|--------------|-----------------------------------------------------------------------------------|
| COMPONENT                        | CONDITION    | COMMENT                                                                           |
| ROOF                             |              |                                                                                   |
| Original Building                | Fair         | Shingles are failing                                                              |
| Gym                              | Fair         |                                                                                   |
| 2004 Addition                    | Satisfactory |                                                                                   |
| HVAC                             | Satisfactory |                                                                                   |
| BUILDING ENVELOP                 |              |                                                                                   |
| Doors, Windows, Fascia           | Good/Poor    | Front canopy painted 2020 Original exterior doors need to be replaced             |
| Walls (Painting)                 | Satisfactory | ·                                                                                 |
| PLUMBING                         |              | Original restrooms need renovation                                                |
| Original Restrooms               | Poor         | soon                                                                              |
| Drinking Fountains               | Fair         | Drinking fountains need to be replaced                                            |
| FLOORS                           | Good         |                                                                                   |
| ELECTRICAL                       |              | Main switchboard needs replacement.                                               |
| Main Switchboard                 | Poor         | Need to upgrade lighting with LED                                                 |
| Lights                           | Poor         |                                                                                   |
| SECURITY & ALARMS                |              | Security vestibule needed                                                         |
| P.A. System                      | Poor         | PA system needs replacement                                                       |
| ENERGY MANAGEMENT SYSTEM         | Poor         | Need to replace old Novar system                                                  |
| MISCELLANEOUS FIXTURES/EQUIPMENT |              |                                                                                   |
| Locker Rooms                     | Poor         | Locker rooms need renovation                                                      |
| Signage                          | Good         | Need to replace signage with ADA                                                  |
|                                  | _            | compliant signage                                                                 |
| Cafeteria Sound System           | Poor         | Need new sound system                                                             |
| CONCRETE & PAVEMENT              |              |                                                                                   |
| Sidewalks                        | Good         | Sidewalk repair 2018                                                              |
| Bus Loop                         | Poor         | Additional bus parking needed / need to separate bus traffic from vehicle traffic |
| Parking Lot                      | Poor         | Need repaving and additional parking                                              |
| GROUNDS                          |              |                                                                                   |
| Paved Athletic Surfaces          | Good         |                                                                                   |
| Athletic Fields                  | Good         |                                                                                   |

| TABB MIDDLE SCHOOL               |              |                                                                          |
|----------------------------------|--------------|--------------------------------------------------------------------------|
| COMPONENT                        | CONDITION    | COMMENT                                                                  |
| ROOF                             |              |                                                                          |
| Original Building                | Excellent    | Roof replaced with metal roof 2019                                       |
| Gym                              | Satisfactory |                                                                          |
| HVAC                             | Fair         | Chiller replaced 2016                                                    |
| BUILDING ENVELOP                 |              |                                                                          |
| Doors, Windows, Fascia           | Good         |                                                                          |
| Walls (Painting)                 | Excellent    |                                                                          |
| PLUMBING                         | Good         |                                                                          |
| FLOORS                           | Good         |                                                                          |
| ELECTRICAL                       | Good         |                                                                          |
| SECURITY & ALARMS                | Good         | Installed security vestibule summer 2017                                 |
| P.A System                       | Poor         | PA system needs replacement                                              |
| ENERGY MANAGEMENT SYSTEM         | Poor         | Old Novar system needs to be                                             |
|                                  |              | replaced                                                                 |
| MISCELLANEOUS FIXTURES/EQUIPMENT |              |                                                                          |
| Main Gym                         | Poor         | Main gym too small, need a new larger gym                                |
| Locker Rooms                     | Fair         | Locker rooms need renovation                                             |
| Clock System                     | Poor         | Clock system needs to be replaced                                        |
| Cafeteria Sound System           | Poor         | Need to replace Cafeteria sound system                                   |
| Gym Floors                       | Excellent    | Installed new wood floors/paint and wall pads & led lighting             |
| CONCRETE & PAVEMENT              |              |                                                                          |
| Sidewalks                        | Good         |                                                                          |
| Bus Loop                         | Good         |                                                                          |
| Parking Lot                      | Good         | Striped parking lot 2019                                                 |
| GROUNDS                          |              |                                                                          |
| Paved Athletic Surfaces          | Good         |                                                                          |
| Athletic Fields                  | Good         | Sprigged soccer/football field 2019<br>Erosion on side of football field |

| YORKTOWN MIDDLE SCHOOL/YORK RIVER ACADEMY |                |                                                                                |  |
|-------------------------------------------|----------------|--------------------------------------------------------------------------------|--|
| COMPONENT                                 | CONDITION      | COMMENT                                                                        |  |
| ROOF                                      | Good           | Some gutters and downspouts need repair                                        |  |
| Gutters and Downspouts                    | Fair           | Some gutters and downspouts need repair                                        |  |
| HVAC                                      | Good           | Replaced compressors in Auditorium, Gym and Cafeteria HVAC units               |  |
| BUILDING ENVELOP                          |                |                                                                                |  |
| Doors                                     | Good/Fair      | Original exterior doors need to be replaced                                    |  |
| Doors (Auditorium)                        | Fair           | Original exterior doors need to be replaced                                    |  |
| Windows                                   | Good           |                                                                                |  |
| Fascia                                    | Good           |                                                                                |  |
| Walls (Painting)                          | Satisfactory   |                                                                                |  |
| PLUMBING                                  |                |                                                                                |  |
| Original Restrooms                        | Fair           | Original restrooms need renovation                                             |  |
| FLOORS                                    | Good/Excellent | Main gym floor replaced with wood 2021                                         |  |
| ELECTRICAL                                | Good           |                                                                                |  |
| Lighting                                  | Excellent      | Main gym lighting replaced with LED                                            |  |
| SECURITY & ALARMS                         | Good           | Installed security vestibule 2017                                              |  |
| ENERGY MANAGEMENT SYSTEM                  | Good           | Need to replace old Novar system                                               |  |
| MISCELLANEOUS FIXTURES/EQUIPMENT          |                |                                                                                |  |
| Locker rooms                              | Poor           | Locker rooms need renovation                                                   |  |
| Signage                                   | Fair           | Need to replace signage with ADA compliant signage                             |  |
| Auditorium Sound System                   | Poor           | Needs to be replaced                                                           |  |
| Auditorium Stage Lighting                 | Poor           | Needs to be replaced                                                           |  |
| CONCRETE & PAVEMENT                       |                |                                                                                |  |
| Sidewalks                                 | Good/Fair      | Some front sidewalks are in need of repair                                     |  |
| Bus Loop                                  | Good           |                                                                                |  |
| Parking Lot                               | Very Poor      | Side parking lot needs expansion and correct drainage/ back loop needs repaved |  |
| Fire Access Road to Boys & Girls Club     | Very Poor      | Need to reconstruct access road                                                |  |

| COMPONENT COMPUTION COMMENT      |            |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |
|----------------------------------|------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| COMPONENT                        | CONDITION  | COMMENT                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |
| ROOF                             | Excellent  | Roof repaired 2016 and coated 2017                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             |
|                                  | - u .      | Repaired 2021                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |
| Parapets                         | Excellent  | 110111100                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |
| HVAC                             | Excellent  | HS HVAC replaced (cooling towers)                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |
|                                  |            | replaced 2019                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |
| D. W. D. W. G. D. W. G. D. D.    |            | MS HVAC replaced in 2020                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       |
| BUILDING ENVELOP                 |            |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |
| Caulk Joints                     | Poor       | Vertical caulk joints in brick should be                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       |
|                                  |            | re-caulked                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     |
| Doors, Windows, Fascia           | Excellent  | Main entrance doors replaced 2019                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |
| Walls (Painting)                 | Excellent  | Futurious and an activities                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |
| D.L. I. A.D.L. I. G.             | 0 1        | Exterior needs power washing                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   |
| PLUMBING                         | Good       | Replaced toilets in teachers restrooms                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         |
| TI 0 0 0 0                       |            | 2019                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |
| FLOORS                           | Caral/Dans | Add the confirmation of th |
| Middle Gym Floor  ELECTRICAL     | Good/Poor  | Middle gym floor needs replacement                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             |
| ELECTRICAL                       | Excellent  | Main switchboard replaced                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |
|                                  |            | High school lighting replaced with LED                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         |
|                                  |            | 2019, MS lighting replaced in 2020                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             |
| CCCLIDITY O ALADAAC              |            | Dual generators installed 2019                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 |
| SECURITY & ALARMS                | Good       | Socurity vestibules installed 2010                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             |
| Fire Alarm                       | Good       | Security vestibules installed 2019                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             |
|                                  |            | PA system replaced in 2020                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     |
| P.A. System                      | Excellent  |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |
| ENERGY MANAGEMENT SYSTEM         | Excellent  | Replaced 2019-2020                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             |
| MISCELLANEOUS FIXTURES/EQUIPMENT |            | Media centers need                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             |
| HS and MS Media Centers          | Good       | updated/renovated                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |
| CONCRETE & PAVEMENT              |            |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |
| Sidewalks                        | Good       | Replaced multiple sections of cracked                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          |
|                                  |            | sidewalk 2019                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |
| Bus Loop                         | Poor       | Needs repaving                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 |
| Parking Lot                      | Poor       | Needs repaving, need additional                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |
| <b>3</b>                         |            | parking                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |
| GROUNDS                          |            |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |
|                                  | 1 .        |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |
| Paved Athletic Surfaces          | Good       |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |

| BRUTON HIGH SCHOOL                   |                |                                                 |
|--------------------------------------|----------------|-------------------------------------------------|
| COMPONENT                            | CONDITION      | COMMENT                                         |
| ROOF                                 |                |                                                 |
| Main Roof                            | Poor           | Rapid degradation of granules- roof will        |
| Gym Roof                             | Very Poor      | need coating very soon                          |
| Gutters and Downspouts               | Poor           | Temporary coating will be applied to roof       |
|                                      |                | Gutters and downspouts need repair              |
| HVAC                                 | Fair           | Existing system installed 2002 and is 20        |
|                                      |                | years old                                       |
| BUILDING ENVELOP                     |                |                                                 |
| Doors, Windows, Fascia               | Poor           | Fascia repair needed to increase building       |
| Commons Area Storefront Doors and    |                | energy efficiency, Rust is penetrating metal    |
| Windows                              | Poor           | panels                                          |
|                                      |                | Commons storefront needs to be replaced         |
| Walls (Painting)                     | Fair           | Partial painting in café 2017                   |
| PLUMBING                             |                |                                                 |
| Gym and School of the Arts restrooms | Poor/Excellent | SOA restrooms renovated 2021                    |
| Drinking Fountains                   | Good/Fair      | Drinking fountains need to be replaced          |
| FLOORS                               | Good           |                                                 |
| ELECTRICAL                           | Good           |                                                 |
| SECURITY & ALARMS                    | Good           | Security vestibule installed 2018               |
| ENERGY MANAGEMENT SYSTEM             | Good           |                                                 |
| MISCELLANEOUS FIXTURES/EQUIPMENT     |                |                                                 |
| Media Center                         | Excellent      | Media Center renovated into Learning            |
| Metal Canopy                         | Fair           | Commons                                         |
| Signage                              | Fair           | Canopy metal is rusting and needs re-           |
| Kitchen Equipment                    | Good           | painting                                        |
| Locker Rooms                         | Poor           | Need to replace signage with ADA compliant      |
|                                      |                | signage                                         |
|                                      |                | Equipment is older but serviceable              |
|                                      |                | Locker rooms are in desperate need of           |
|                                      |                | renovation                                      |
| CONCRETE & PAVEMENT                  |                |                                                 |
| Sidewalks                            | Fair           | Some sidewalks have cracks that need to be      |
|                                      |                | repaired                                        |
| Bus Loop                             | Fair           | Needs repaving                                  |
| Parking Lot                          | Good/Fair      | Main parking lot and entrance/exit road is      |
|                                      | ,              | older and in fair condition                     |
|                                      |                | Parking lot striped 2018                        |
| GROUNDS                              |                | ·                                               |
| Paved Athletic Surfaces              | Good           | Track resurfaced 2017                           |
| -                                    |                |                                                 |
|                                      |                |                                                 |
| Athletic Fields                      | Good/Very      | Football field drainage has failed; field holds |
|                                      | Poor           | water and does not drain. Crown is non-         |
|                                      |                | existent. Recommend converting to               |
|                                      |                | synthetic turf field.                           |

| TABB HIGH SCHOOL                 |              |                                                                                   |
|----------------------------------|--------------|-----------------------------------------------------------------------------------|
| COMPONENT                        | CONDITION    | COMMENT                                                                           |
| ROOF                             |              |                                                                                   |
| Metal                            | Satisfactory | Experiencing several leaks in valleys                                             |
| Low Slope Roof                   | Satisfactory | Needs coating                                                                     |
| HVAC                             | Fair         | Very high energy consumption                                                      |
| BUILDING ENVELOP                 |              |                                                                                   |
| Doors                            | Poor         | Original 1972 doors need to be replaced                                           |
| Windows                          | Poor         | Original 1972 windows need to be replaced                                         |
| Fascia                           | Very Poor    | Rust is penetrating the metal facial                                              |
| Walls (Painting)                 | Excellent    | Painted 2018                                                                      |
| PLUMBING                         | Good         |                                                                                   |
| Gym and Arts Areas Restrooms     | Poor         | Gym and Arts areas restrooms need to be renovated                                 |
| FLOORS                           | Good         |                                                                                   |
| ELECTRICAL                       |              |                                                                                   |
| Main Switchboard                 | Fair         | Original switchboard should be replaced                                           |
| Breaker Panels                   | Fair         | Original breaker panels should be replaced                                        |
| Lighting                         | Fair         | Light should be upgraded with LED                                                 |
| SECURITY & ALARMS                | Good         | Fire alarm replaced 2018                                                          |
| P.A. System                      | Fair         | PA system needs replacement                                                       |
| ENERGY MANAGEMENT SYSTEM         | Fair         | Need to replace old Novar system                                                  |
| MISCELLANEOUS FIXTURES/EQUIPMENT |              |                                                                                   |
| Locker Rooms                     | Very Poor    | Locker rooms and desperately need                                                 |
| Signage                          | Fair         | renovation-used for shelter operations                                            |
|                                  |              | Need to upgrade signage with ADA                                                  |
| Kitchen Equipment                | Fair         | compliant signage                                                                 |
|                                  |              | Equipment is older but serviceable                                                |
| CONCRETE & PAVEMENT              |              |                                                                                   |
| Sidewalks                        | Good         | Repaired 2018                                                                     |
| Bus Loop                         | Excellent    | VDOT repaved 2021                                                                 |
| Parking Lot                      | Fair         | Needs repaving                                                                    |
| GROUNDS                          |              |                                                                                   |
| Paved Athletic Surfaces          | Fair         | Tennis court needs resurfacing                                                    |
| Athletic Fields                  | Good         | New irrigation controls installed 2019 Fields need lighting for evening practices |

| TORK FIGH SCF                    | HOOL CAMPUS - YORK HI | GH JCHOOL                                                                                     |
|----------------------------------|-----------------------|-----------------------------------------------------------------------------------------------|
| COMPONENT                        | CONDITION             | COMMENT                                                                                       |
| ROOF                             | Poor                  | Roof is being repaired and recoated                                                           |
| Gutters and Downspouts           | Poor                  |                                                                                               |
| HVAC                             | Good                  |                                                                                               |
| BUILDING ENVELOP                 |                       |                                                                                               |
| Doors (Exterior)                 | Good                  | Original auditorium exterior doors need to be replaced/Repaint exterior doors                 |
| Windows                          | Good                  |                                                                                               |
| Fascia                           | Good                  |                                                                                               |
| Walls (Painting)                 | Satisfactory          | 2006 was last building-wide painting                                                          |
| PLUMBING                         | ·                     |                                                                                               |
| Hot Water                        | Poor                  | No hot water to some restroom sinks Drinking fountains need to be replaced                    |
| Drinking Fountains               | Good/Fair             | Water bottle filling stations added                                                           |
| FLOORS                           | Good                  |                                                                                               |
| ELECTRICAL                       |                       |                                                                                               |
| Main Switch Board                | Very Poor             | Main switch board needs replacement                                                           |
| Breaker Panels                   | Poor                  | ASAP                                                                                          |
| Lighting                         | Fair                  | Original breaker panels should be replaced                                                    |
|                                  |                       | Lighting should be upgraded to LED                                                            |
| SECURITY & ALARMS                | Good                  |                                                                                               |
| P.A. System                      | Good                  |                                                                                               |
| ENERGY MANAGEMENT SYSTEM         | Good                  |                                                                                               |
| MISCELLANEOUS FIXTURES/EQUIPMENT |                       |                                                                                               |
| Locker Rooms                     | Very Poor             | Renovation needed soon                                                                        |
| Restrooms                        | Excellent/Good        | Restrooms need renovation                                                                     |
|                                  |                       | Café and 400 hallway restrooms                                                                |
|                                  |                       | refurbished –tile floor/new stall                                                             |
| De ana (lutarian)                | F                     | partitions 2019                                                                               |
| Doors (Interior)                 | Excellent             | Doors replaced 2019                                                                           |
| Media Center                     | Excellent             | Media center renovated 2019                                                                   |
| CONCRETE & PAVEMENT              |                       |                                                                                               |
| Sidewalks                        | Good                  | Repairing areas in 2017                                                                       |
| Bus Loop                         | Fair                  | Need to expand bus loop and separate                                                          |
| Parking Lot                      | Good                  | bus traffic from vehicle traffic  Need to expand parking to accommodate games at Bailey Field |

| YORK HIGH SCHOOL CAMPUS - TV STUDIO/LLLC/PRINT SHOP |              |                                                              |  |  |  |  |
|-----------------------------------------------------|--------------|--------------------------------------------------------------|--|--|--|--|
| COMPONENT                                           | CONDITION    | COMMENT                                                      |  |  |  |  |
| ROOF                                                | Very Poor    | Needs repair and coating                                     |  |  |  |  |
| HVAC                                                |              |                                                              |  |  |  |  |
| Print Shop                                          | Poor         | Print shop needs fresh air                                   |  |  |  |  |
| Ductwork                                            | Poor         | Fiber board ductwork is falling apart                        |  |  |  |  |
| BUILDING ENVELOP                                    |              |                                                              |  |  |  |  |
| Doors                                               | Very Poor    | Needs replacement ASAP                                       |  |  |  |  |
| Windows                                             | Very Poor    | Needs replacement ASAP                                       |  |  |  |  |
| Fascia                                              | Poor         |                                                              |  |  |  |  |
| Walls (Painting)                                    | Fair         |                                                              |  |  |  |  |
| PLUMBING                                            |              |                                                              |  |  |  |  |
| Restrooms                                           | Very Poor    | Restrooms need renovation                                    |  |  |  |  |
| Drinking Fountains                                  | Fair         | Need to replace drinking fountains                           |  |  |  |  |
| Hot Water                                           | Poor         | Limited hot water in building                                |  |  |  |  |
| FLOORS                                              | Satisfactory |                                                              |  |  |  |  |
| ELECTRICAL                                          |              |                                                              |  |  |  |  |
| Breaker Panels                                      | Very Poor    | Panels need to be replaced                                   |  |  |  |  |
| Lighting                                            | Very Poor    | Old, inefficient light fixtures need to be replaced with LED |  |  |  |  |
| SECURITY & ALARMS                                   | Satisfactory |                                                              |  |  |  |  |
| ENERGY MANAGEMENT SYSTEM                            | Poor         | Need to replace old Novar system                             |  |  |  |  |
| MISCELLANEOUS                                       |              |                                                              |  |  |  |  |
| FIXTURES/EQUIPMENT                                  | Poor         | Need to replace signage with ADA compliant signage           |  |  |  |  |
| Signage                                             | Poor         | Suspended ceilings throughout are old, sagging and need to   |  |  |  |  |
| Ceilings                                            | Very Poor    | be replaced                                                  |  |  |  |  |
| Food Service Offices                                |              | Offices need to be renovated/overcrowded                     |  |  |  |  |
| CONCRETE & PAVEMENT                                 |              |                                                              |  |  |  |  |
| Sidewalks                                           | Satisfactory |                                                              |  |  |  |  |
| Parking Lot                                         | Poor         | Need to repave and add additional parking                    |  |  |  |  |

| SCHOOL BOARD OFFICE              |           |                                                                            |  |  |  |  |  |  |
|----------------------------------|-----------|----------------------------------------------------------------------------|--|--|--|--|--|--|
| COMPONENT                        | CONDITION | COMMENT                                                                    |  |  |  |  |  |  |
| ROOF                             | Fair      |                                                                            |  |  |  |  |  |  |
| HVAC                             | Good      | Server room HVAC installed summer 2017                                     |  |  |  |  |  |  |
| BUILDING ENVELOP                 |           |                                                                            |  |  |  |  |  |  |
| Doors                            | Good      |                                                                            |  |  |  |  |  |  |
| Windows                          | Good      |                                                                            |  |  |  |  |  |  |
| Fascia                           | Good      |                                                                            |  |  |  |  |  |  |
| Walls (Painting)                 | Good      |                                                                            |  |  |  |  |  |  |
| BASEMENT                         | Good      | Replaced failed waterproofing around basement in 2017                      |  |  |  |  |  |  |
| FLOORS                           | Good      |                                                                            |  |  |  |  |  |  |
| ELECTRICAL                       | Good      |                                                                            |  |  |  |  |  |  |
| SECURITY & ALARMS                |           |                                                                            |  |  |  |  |  |  |
| Fire Alarm                       | Good      | Fire alarm installed                                                       |  |  |  |  |  |  |
| Cameras                          | Good      | Cameras installed                                                          |  |  |  |  |  |  |
| ENERGY MANAGEMENT SYSTEM         | Excellent | Replace with Alerton in 2019                                               |  |  |  |  |  |  |
| MISCELLANEOUS FIXTURES/EQUIPMENT | Good      |                                                                            |  |  |  |  |  |  |
| CONCRETE & PAVEMENT              |           |                                                                            |  |  |  |  |  |  |
| Sidewalks                        | Good      |                                                                            |  |  |  |  |  |  |
| Parking Lot                      | Excellent | Parking lot repaved 2019  Not enough parking. Needs expansion and repaving |  |  |  |  |  |  |

| OPERATIONS COMPLEX - BUS ADMINISTRATION/GARAGE |              |                                  |  |  |  |  |  |
|------------------------------------------------|--------------|----------------------------------|--|--|--|--|--|
| COMPONENT                                      | CONDITION    | COMMENT                          |  |  |  |  |  |
| ROOF                                           |              |                                  |  |  |  |  |  |
| Admin Office                                   | Good         |                                  |  |  |  |  |  |
| Shop                                           | Very Poor    | Needs recoating/possible         |  |  |  |  |  |
|                                                |              | replacement                      |  |  |  |  |  |
| HVAC                                           | Fair         | Units need replacement           |  |  |  |  |  |
| BUILDING ENVELOP                               |              |                                  |  |  |  |  |  |
| Doors                                          | Good         |                                  |  |  |  |  |  |
| Windows                                        | Good         | Replaced office windows          |  |  |  |  |  |
| Walls (Painting)                               | Good         |                                  |  |  |  |  |  |
| PLUMBING                                       | Fair         | Need to eliminate sewer lift     |  |  |  |  |  |
|                                                |              | station and put on new sewer     |  |  |  |  |  |
|                                                |              | main                             |  |  |  |  |  |
| FLOORS                                         | Good         |                                  |  |  |  |  |  |
| ELECTRICAL                                     | Poor         | All panels need to be replaced   |  |  |  |  |  |
| Breaker Panels                                 |              | Lighting should be replaced with |  |  |  |  |  |
| Lighting                                       | Poor         | LED                              |  |  |  |  |  |
| SECURITY & ALARMS                              | Good         |                                  |  |  |  |  |  |
| ENERGY MANAGEMENT SYSTEM                       | Good         |                                  |  |  |  |  |  |
| MISCELLANEOUS FIXTURES/EQUIPMENT               | Satisfactory |                                  |  |  |  |  |  |
| CONCRETE & PAVEMENT                            |              |                                  |  |  |  |  |  |
| Parking Lot                                    | Good         |                                  |  |  |  |  |  |

| OPERATIONS COMPLEX - IT WAREHOUSE |           |                                   |  |  |  |  |  |
|-----------------------------------|-----------|-----------------------------------|--|--|--|--|--|
| COMPONENT                         | CONDITION | COMMENT                           |  |  |  |  |  |
| ROOF                              | Good      |                                   |  |  |  |  |  |
| HVAC                              | Good      |                                   |  |  |  |  |  |
| BUILDING ENVELOP                  |           |                                   |  |  |  |  |  |
| Doors                             | Good      |                                   |  |  |  |  |  |
| Windows                           | Good      |                                   |  |  |  |  |  |
| Fascia                            | Good      |                                   |  |  |  |  |  |
| Walls (Painting)                  | Good      |                                   |  |  |  |  |  |
| PLUMBING                          | Good      |                                   |  |  |  |  |  |
| FLOORS                            | Good      |                                   |  |  |  |  |  |
| ELECTRICAL                        |           |                                   |  |  |  |  |  |
| Breaker Panels                    | Good      | Installed surge protection 2018   |  |  |  |  |  |
| Lighting                          | Fair      | Need to replace with LED lighting |  |  |  |  |  |
| SECURITY & ALARMS                 | Good      |                                   |  |  |  |  |  |
| ENERGY MANAGEMENT SYSTEM          | Good      |                                   |  |  |  |  |  |
| MISCELLANEOUS FIXTURES/EQUIPMENT  | Good      |                                   |  |  |  |  |  |
| CONCRETE & PAVEMENT               |           |                                   |  |  |  |  |  |
| Sidewalks                         | Good      |                                   |  |  |  |  |  |

| OPERATIONS COMPLEX - MAINTENANCE/WAREHOUSE |              |                                    |  |  |  |  |  |
|--------------------------------------------|--------------|------------------------------------|--|--|--|--|--|
| COMPONENT                                  | CONDITION    | COMMENT                            |  |  |  |  |  |
| ROOF                                       |              |                                    |  |  |  |  |  |
| Metal Building                             | Poor         | Holes, rust in areas               |  |  |  |  |  |
| Warehouse                                  | Good         |                                    |  |  |  |  |  |
| HVAC                                       | Fair         | Needs replacement                  |  |  |  |  |  |
| BUILDING ENVELOP                           |              |                                    |  |  |  |  |  |
| Doors                                      | Fair         | Needs replacement                  |  |  |  |  |  |
| Windows                                    | Fair         | Needs replacement                  |  |  |  |  |  |
| Fascia                                     | Fair         | Needs replacement                  |  |  |  |  |  |
| Walls (Painting)                           | Very Poor    | Exterior walls were partially      |  |  |  |  |  |
|                                            |              | repainted 2020                     |  |  |  |  |  |
| PLUMBING                                   | Satisfactory |                                    |  |  |  |  |  |
| FLOORS                                     | Fair         | Carpet needs replaced              |  |  |  |  |  |
| ELECTRICAL                                 |              | Breaker panels need replacement    |  |  |  |  |  |
| Breaker Panels                             | Very Poor    | Lighting needs to be replaced with |  |  |  |  |  |
| Lighting                                   | Poor         | LED                                |  |  |  |  |  |
| SECURITY & ALARMS                          | Good         |                                    |  |  |  |  |  |
| ENERGY MANAGEMENT SYSTEM                   | Fair         | Need to replace old Novar system   |  |  |  |  |  |
| MISCELLANEOUS FIXTURES/EQUIPMENT           | Very Poor    | Units need replacement- at end     |  |  |  |  |  |
| Walk in units                              |              | of life                            |  |  |  |  |  |
| CONCRETE & PAVEMENT                        | Good         |                                    |  |  |  |  |  |
| Parking Lot                                | Good         |                                    |  |  |  |  |  |

## Exhibit 7 - CIP Project Worksheets

# County of York, Virginia Capital Improvement Program Submission Fiscal Years 2024 - 2029 PROJECT NUMBER: N/A PROJECT NAME: Six to Eight Classroom Expansion CATEGORY: SBO Admin. Svcs. DEPARTMENT: YCSD Capital Plans & Projects PROJECT TYPE: New Construction and Renovation PROJECT LOCATION: Dare Elementary School

|              | Programmed Funding |              |    |        |                                         |        |    |            |    |           |           |    |           |                |
|--------------|--------------------|--------------|----|--------|-----------------------------------------|--------|----|------------|----|-----------|-----------|----|-----------|----------------|
|              | Total              | Appropriated |    |        | Non-Appropriated programmed CIP Funding |        |    |            |    |           |           |    |           |                |
| Project Cost |                    | To Date      |    | FY2024 |                                         | FY2025 |    | FY2026     |    | FY2027    | FY2028    |    | FY2029    | Future Funding |
| \$           | 17,150,000         | N/A          | \$ | -      | \$                                      | -      | \$ | <b>;</b> - | \$ | 1,750,000 | 7,700,000 | \$ | 7,700,000 | N/A            |
| FY20         | 023 Approved CIP   |              | \$ | -      | \$                                      | -      |    |            |    |           |           | \$ | -         | N/A            |
| FY20         | 022 Approved CIP   |              | \$ |        | \$                                      | -      | \$ | \$ -       | \$ | -         | \$ -      | \$ | -         | N/A            |

## **Description, Scope and Timeline**

Funding is requested to construct a new six to eight classroom building addition. Small expansions to the media center and main offices at the front of the school will be included. Cafeteria expansion is also part of this project.

Anticipated Timeline:

Funding - July 2026, July 2027, July 2028 A&E Design Complete - June 2027 Invitation for Bids - July 2027 Construction - June 2028 - August 2029

#### **Purpose and Need**

Due to increased residential construction and increasing enrollment in several elementary school zones, additional classroom space is needed.

#### History and Current Status

The building opened in 1965. In 2009 nine classroooms were added to the school to meet increasing enrollment. Continuing residential development and increased enrollment in the lower end of the county is driving the need for an additional six to eight classrooms.

## **Operating Budget Impacts**

The additional square footage will increase utility costs. Additional teaching and maintenance staff will also be required.

#### **Anticipated Performance/Outcome Measures**

The additional classrooms will relieve enrollment pressure on existing elementary schools, reduce class sizes and provide a more appropriate learning environment.

| ı | Strategic Plan Goals (Check all applicable) |                     |   |                         |  |  |  |  |
|---|---------------------------------------------|---------------------|---|-------------------------|--|--|--|--|
|   | Χ                                           | Student Achievement |   | School Culture          |  |  |  |  |
|   | Χ                                           | Student Experiences | Х | Operational Stewardship |  |  |  |  |
| П | X                                           | Staff Support       |   |                         |  |  |  |  |



## Capital Improvement Program Submission Fiscal Years 2024 - 2029

PROJECT NUMBER: N/A PROJECT NAME: Create Bus Loop and Additional Parking Spaces STATUS: Requested
CATEGORY: SBO Admin. Svcs.
PROJECT TYPE: Parking Lot Expansion

PROJECT NAME: Create Bus Loop and Additional Parking Spaces
DIVISION: YCSD
DIVISION: YCSD
FUND: 70

PROJECT LOCATION: Dare Elementary School & School Board Office

|                     | Programmed Funding |                                         |        |        |            |              |        |                |  |  |
|---------------------|--------------------|-----------------------------------------|--------|--------|------------|--------------|--------|----------------|--|--|
| Total               | Appropriated       | Non-Appropriated programmed CIP Funding |        |        |            |              |        |                |  |  |
| Project Cost        | To Date            | FY2024                                  | FY2025 | FY2026 | FY2027     | FY2028       | FY2029 | Future Funding |  |  |
| \$ 1,100,000        | N/A                | \$ -                                    | \$ -   |        | \$ 100,000 | \$ 1,000,000 | \$ -   | N/A            |  |  |
| FY2023 Approved CIP |                    | \$ -                                    |        |        | \$ -       | \$ -         | \$ -   | N/A            |  |  |
| FY2022 Approved CIP |                    | \$ -                                    | \$ -   | \$ -   | \$ -       | \$ -         | \$ -   | N/A            |  |  |

#### **Description, Scope and Timeline**

Funding is requested to design and construct additional parking between the facilities as well as separate the bus and personal vehicle traffic flows. Anticipated Timeline:

Funding - July 2026 and July 2027 A&E Design Complete - June 2027 Invitation for Bids - July 2027 Construction - Summer 2028

#### **Purpose and Need**

The bus and personal vehicle traffic patterns at the school should be separated to increase safety. The volume of vehicular traffic entering the parking lot causes tie ups on Dare Road during arrival and dismissal times. Pedestrian and vehicular traffic is a safety concern. Additional parking space is also needed for meetings, special events and Parks & Recreation activities.

## **History and Current Status**

A study has been done by a retired civil engineer proposing several methods to improve bus and personal vehicle traffic flows. School staff is currently parking on gravel behind Dare Elementary in an attempt to reduce traffic and congestion in the parking lot. Dealing with existing embankments will be a design challenge that will add cost to

## **Operating Budget Impacts**

There will be additional utility and maintenance costs which will be necessary in order to support and maintain the larger parking lot.

## **Anticipated Performance/Outcome Measures**

Additional parking will help relieve traffic congestion and increase safety. Improvements will be consistent with other YCSD parking lots.

|   | Strategic Plan Goals (Check all applicable) |                     |   |                         |  |  |  |  |
|---|---------------------------------------------|---------------------|---|-------------------------|--|--|--|--|
|   | Χ                                           | Student Achievement |   | School Culture          |  |  |  |  |
| I | Χ                                           | Student Experiences | Х | Operational Stewardship |  |  |  |  |
|   | Χ                                           | Staff Support       |   |                         |  |  |  |  |



| Schedule of Activities      |            |
|-----------------------------|------------|
| Project Activities          | Amount     |
| A&E                         | \$ 110,000 |
| Land                        | \$ -       |
| Construction                | \$ 880,000 |
| Furnishings                 | \$ -       |
| Equipment                   | \$ -       |
| Contingencies               | \$ 110,000 |
| Other: Please explain below | \$ -       |
|                             | \$ -       |

Total Budgetary Cost Estimate: \$



| Means of Financing                          |                |                 |
|---------------------------------------------|----------------|-----------------|
| Funding Subclass                            |                | Amount          |
| Program Support/Revenue                     |                |                 |
| Financing/Debt Issuance                     |                | \$<br>1,100,000 |
| Federal, State, Other: Please explain below |                | \$<br>-         |
|                                             |                | \$<br>-         |
|                                             |                | \$<br>-         |
| Local Funding                               |                | \$<br>-         |
|                                             | Total Funding: | \$<br>1,100,000 |
| CONTACT PERSON: Mark Tschirhart             |                | ·               |

PHONE: 757.876.8681

1,100,000

## County of York, Virginia Capital Improvement Program Submission Fiscal Years 2024 - 2029 PROJECT NUMBER: N/A PROJECT NAME: Replace Gym HVAC system CATEGORY: SBO Admin. Svcs. DEPARTMENT: YCSD Capital Plans & Projects DIVISION: YCSD PROJECT TYPE: Equipment Replacement PROJECT LOCATION: Dare Elementary School

|                     | Programmed Funding |        |    |        |     |      |      |                  |     |            |      |        |  |                |
|---------------------|--------------------|--------|----|--------|-----|------|------|------------------|-----|------------|------|--------|--|----------------|
| Total               | Appropriated       |        |    |        |     | N    | on-A | Appropriated pro | gra | mmed CIP F | undi | ng     |  |                |
| Project Cost        | To Date            | FY2024 |    | FY2025 | FY2 | 2026 |      | FY2027           |     | FY2028     |      | FY2029 |  | Future Funding |
| \$ 2,200,000        | N/A                | \$ .   | \$ | -      | \$  |      | \$   | 200,000          | \$  | 2,000,000  |      |        |  | N/A            |
| FY2023 Approved CIP |                    | \$ .   | \$ | -      | \$  |      |      |                  |     |            | \$   | -      |  | N/A            |
| FY2022 Approved CIP |                    | \$ .   | \$ | -      | \$  | -    | \$   | -                | \$  | -          | \$   | -      |  | N/A            |

#### **Description, Scope and Timeline**

Funding is requested for remove and replace the existing HVAC system.

Anticipated Timeline:

Funding - July 2026 and July 2027 A&E Design Complete - June 2027 Invitation for Bids - July 2027 Construction - Summer 2028

## Purpose and Need

The existing system is at the end of its useful life and needs to be replaced.

## History and Current Status

The gymnasium addition was built in 1997. The existing HVAC system will be over 30 years old in FY27. It requires continuous maintenance to keep it operational and should be replaced. The unit uses R-22, an obsolete refrigerant, which is very expensive.


#### Operating Budget Impacts

The new HVAC equipment will be more energy efficient and require less maintenance, thus reducing operating cost.

## **Anticipated Performance/Outcome Measures**

The new system will provide better temperature and humidity control in the gym. Replacement will be consistent with other YCSD HVAC replacements.

|   |   | Strategic Plan Goals (Check all applicable) |   |                         |  |  |  |  |  |  |  |  |
|---|---|---------------------------------------------|---|-------------------------|--|--|--|--|--|--|--|--|
|   | Χ | Student Achievement                         |   | School Culture          |  |  |  |  |  |  |  |  |
|   | Χ | Student Experiences                         | Х | Operational Stewardship |  |  |  |  |  |  |  |  |
| Г | Χ | Staff Support                               |   |                         |  |  |  |  |  |  |  |  |



|                                                                 | County of York, Virginia                              |           |           |  |  |  |  |  |  |
|-----------------------------------------------------------------|-------------------------------------------------------|-----------|-----------|--|--|--|--|--|--|
| Capital Improvement Program Submission Fiscal Years 2024 - 2029 |                                                       |           |           |  |  |  |  |  |  |
| PROJECT NUMBER: N/A                                             | PROJECT NAME: Replace HVAC Equipment and Replace Roof | STATUS:   | Requested |  |  |  |  |  |  |
| CATEGORY: SBO Admin. Svcs.                                      | DEPARTMENT: YCSD Capital Plans & Projects             | DIVISION: | YCSD      |  |  |  |  |  |  |
| PROJECT TYPE: Replacement                                       |                                                       | FUND:     | 70        |  |  |  |  |  |  |
| PROJECT LOCATION: Mount Vernon Fle                              | mentary School                                        |           |           |  |  |  |  |  |  |

|                     | Programmed Funding |            |        |      |        |      |                  |               |      |        |                |  |  |  |
|---------------------|--------------------|------------|--------|------|--------|------|------------------|---------------|------|--------|----------------|--|--|--|
| Total               | Appropriated       |            |        |      | N      | on-A | Appropriated pro | grammed CIP F | undi | ng     |                |  |  |  |
| Project Cost        | To Date            | FY2024     | FY2025 |      | FY2026 |      | FY2027           | FY2028        |      | FY2029 | Future Funding |  |  |  |
| \$ 2,740,000        | \$ 2,540,000       | \$ 200,000 | \$     | - \$ | -      | \$   | -                | \$ -          | \$   | -      | N/A            |  |  |  |
| FY2023 Approved CIP | \$ -               | \$ -       | \$     | - \$ | -      | \$   | -                | \$ -          | \$   | -      | N/A            |  |  |  |
| FY2022 Approved CIP |                    | \$ -       | \$     | - \$ |        | \$   | -                | \$ -          | \$   | -      | N/A            |  |  |  |

## Description, Scope and Timeline

Funding is requested to remove and replace the existing rooftop HVAC equipment and controls.

Anticipated Timeline:

Funding - July 2022 and July 2023 A&E Design Complete - October 2022 Invitation for Bids - November 2022 Construction - Summer of 2023 and 2024

#### **Purpose and Need**

The exisiting rooftop HVAC units and roof are at the end of useful life and need to be replaced.

## **History and Current Status**

The exisiting HVAC system consists of roof top mounted equipment. The equipment is at end of its' useful life and need to be replaced. Improvements will be consistent with other YCSD HVAC systems and controls replacements.

## **Operating Budget Impacts**

New HVAC equipment and controls will be more efficient reducing operating cost and will also result in less man hours for maintenance.

## **Anticipated Performance/Outcome Measures**

New equipment and controls will provide better temperature and humidity control and be more energy efficient.

|   | Strategic Plan Goals (Check all applicable) |   |                         |  |  |  |  |  |  |  |  |  |  |
|---|---------------------------------------------|---|-------------------------|--|--|--|--|--|--|--|--|--|--|
| Х | Student Achievement                         |   | School Culture          |  |  |  |  |  |  |  |  |  |  |
| Х | Student Experiences                         | Х | Operational Stewardship |  |  |  |  |  |  |  |  |  |  |
| Х | Staff Support                               |   |                         |  |  |  |  |  |  |  |  |  |  |



| Schedule of Activities      |              |
|-----------------------------|--------------|
| Project Activities          | Amount       |
| A&E                         | \$ 274,000   |
| Land                        | \$ -         |
| Building                    | \$ 2,192,000 |
| Furnishings                 | \$ -         |
| Equipment                   | \$ -         |
| Contingencies               | \$ 274,000   |
| Other: Please explain below | \$ -         |
|                             | \$ -         |



| Means of Financing                          |                |        |           |  |  |
|---------------------------------------------|----------------|--------|-----------|--|--|
| Funding Subclass                            |                | Amount |           |  |  |
| Program Support/Revenue                     |                |        |           |  |  |
| Financing/Debt Issuance                     |                | \$     | 200,000   |  |  |
| Federal, State, Other: Please explain below |                | \$     | -         |  |  |
|                                             |                | \$     |           |  |  |
|                                             |                | \$     | -         |  |  |
| Local Funding - CASH                        |                | \$     | 2,540,000 |  |  |
|                                             | Total Funding: | \$     | 2,740,000 |  |  |
| CONTACT PERSON: Mark Tschirhart             |                |        |           |  |  |

Total Budgetary Cost Estimate: \$

**PHONE:** 757.876.8681

2,740,000

## County of York, Virginia Capital Improvement Program Submission Fiscal Years 2024 - 2029

PROJECT NUMBER: N/A PROJECT NAME: Nine Classroom Expansion & Renovation

CATEGORY: SBO Admin. Svcs. DEPARTMENT: YCSD Capital Plans & Projects

PROJECT TYPE: New Construction and Renovation

FUND: 70

PROJECT LOCATION: Seaford Elementary School

|                     | Programmed Funding |            |    |           |    |        |    |        |     |                  |     |              |      |        |                |
|---------------------|--------------------|------------|----|-----------|----|--------|----|--------|-----|------------------|-----|--------------|------|--------|----------------|
| Total               | Ap                 | propriated |    |           |    |        |    | N      | on- | Appropriated pro | gro | ammed CIP Fo | ındi | ng     |                |
| Project Cost        |                    | To Date    |    | FY2024    |    | FY2025 |    | FY2026 |     | FY2027           |     | FY2028       |      | FY2029 | Future Funding |
| \$ 19,223,761       | \$                 | 17,283,761 | \$ | 1,940,000 |    |        | \$ | -      | \$  | -                | \$  |              | \$   | -      | N/A            |
| FY2023 Approved CIP |                    |            | \$ | -         | \$ | -      | \$ | -      | \$  | -                | \$  | -            |      | N/A    |                |
| FY2022 Approved CIP |                    |            | \$ | -         | \$ | -      | \$ | -      | \$  | -                | \$  | -            | \$   | -      | N/A            |

#### **Description, Scope and Timeline**

Funding is requested to construct a new nine classroom building addition. Small expansions to the media center and main offices at the front of the school will be included. Roof repair and coatings, along with window replacement, is also part of this project.

Anticipated Timeline: Funding - July 2021

A&E Design Complete - October 2021 Invitation for Bids - November 2021

Construction - December 2021 to September 2023

#### **Purpose and Need**

Due to increased residential construction and increasing enrollment in several elementary school zones, additional classroom space is needed.

## **History and Current Status**

The building opened in 1962. In 2014, the school received a six-classroom addition to meet increasing enrollment. Continuing residential development and increased enrollment in the school zone is driving the need for an additional nine classrooms and other modifications to the existing school.

#### **Operating Budget Impacts**

The additional square footage will increase utility costs. Additional teaching and maintenance staff will also be required.

## **Anticipated Performance/Outcome Measures**

The additional classrooms will relieve enrollment pressure on existing elementary schools, reduce elementary class size and provide a more appropriate learning

| ı |   | Strategic Plan Goals (Check all applicable) |   |                         |  |  |  |  |  |  |  |  |
|---|---|---------------------------------------------|---|-------------------------|--|--|--|--|--|--|--|--|
| I | Χ | Student Achievement                         |   | School Culture          |  |  |  |  |  |  |  |  |
| I | Х | Student Experiences                         | Х | Operational Stewardship |  |  |  |  |  |  |  |  |
| ſ | Х | Staff Support                               |   |                         |  |  |  |  |  |  |  |  |



| Schedule of Activities      |               |
|-----------------------------|---------------|
| Project Activities          | Amount        |
| A&E                         | \$ 1,922,376  |
| Land                        | \$ -          |
| Building                    | \$ 15,379,009 |
| Furnishings                 | \$ -          |
| Equipment                   | \$ -          |
| Contingencies               | \$ 1,922,376  |
| Other: Please explain below | \$ -          |
|                             | \$ -          |



| Means of Financing                          |       |            |
|---------------------------------------------|-------|------------|
| Funding Subclass                            |       | Amount     |
| Program Support/Revenue                     |       |            |
| Financing/Debt Issuance                     | \$    | 15,123,761 |
| Federal, State, Other: Please explain below | \$    | -          |
|                                             | \$    | -          |
| Cash                                        | \$    | 4,100,000  |
| Local Funding - Revenue Stabilization       |       |            |
| Total Fundin                                | g: \$ | 19,223,761 |
|                                             |       |            |

Total Budgetary Cost Estimate: \$

CONTACT PERSON: Mark Tschirhart
PHONE: 757.876.8681

19.223.761

## County of York, Virginia Capital Improvement Program Submission Fiscal Years 2024 - 2029 PROJECT NUMBER: N/A PROJECT NAME: Expansion STATUS: Requested DIVISION: YCSD Capital Plans & Projects DIVISION: YCSD PROJECT TYPE: A&E for New Construction FUND: 70

PROJECT LOCATION: Waller Mill Elementary School

|              | Programmed Funding |              |    |                                         |    |        |    |        |    |        |    |           |    |           |                |
|--------------|--------------------|--------------|----|-----------------------------------------|----|--------|----|--------|----|--------|----|-----------|----|-----------|----------------|
|              | Total              | Appropriated |    | Non-Appropriated programmed CIP Funding |    |        |    |        |    |        |    |           |    |           |                |
| Project Cost |                    | To Date      |    | FY2024                                  |    | FY2025 |    | FY2026 |    | FY2027 |    | FY2028    |    | FY2029    | Future Funding |
| \$           | 6,600,000          | N/A          | \$ | -                                       | \$ | -      | \$ | -      | \$ | -      | \$ | 1,100,000 | \$ | 5,500,000 | N/A            |
| FY202        | 23 Approved CIP    |              | \$ | -                                       | \$ | -      | \$ | -      | \$ | -      | \$ | -         | \$ | -         | N/A            |
| FY202        | 22 Approved CIP    |              | \$ | -                                       | \$ | -      | \$ | -      | \$ | -      | \$ | -         | \$ | -         | N/A            |

#### **Description, Scope and Timeline**

Funding is requested to design the construction of a new six classroom building addition. Small expansions to the cafeteria and gymnasium will be included. Anticipated Timeline:

Funding - July 2027

A&E Design Complete - May 2028 Invitation for Bids - June 2028

Construction - August 2028 to Decmber 2029

#### **Purpose and Need**

Due to increased residential construction and increasing enrollment in several elementary school zones, additional classroom space is needed.

## History and Current Status

The building opened in 1969. In 2016, the school was renovated and ten classrooms and a gymnasium were added to meet increasing enrollment. Continuing residential development and increased enrollment in the school zone is driving the need for an additional six classrooms and other modifications to the core of the existing school.

#### Operating Budget Impacts

The additional square footage will increase utility costs. Additional teaching and maintenance staff will also be required.

## Anticipated Performance/Outcome Measures

The additional classrooms will relieve enrollment pressure on existing elementary schools, reduce elementary class size and provide a more appropriate learning

|   | Strategic Plan Goals (Check all applicable) |                     |   |                         |  |  |  |  |  |  |  |  |
|---|---------------------------------------------|---------------------|---|-------------------------|--|--|--|--|--|--|--|--|
|   | Χ                                           | Student Achievement |   | School Culture          |  |  |  |  |  |  |  |  |
|   | Х                                           | Student Experiences | Х | Operational Stewardship |  |  |  |  |  |  |  |  |
| Г | Υ                                           | Staff Support       |   |                         |  |  |  |  |  |  |  |  |





| Schedule of Activities      |              |
|-----------------------------|--------------|
| Project Activities          | Amount       |
| A&E                         | \$ 1,000,000 |
| Land                        | \$ -         |
| Building                    | \$ 5,600,000 |
| Furnishings                 | \$ -         |
| Equipment                   | \$ -         |
| Contingencies               |              |
| Other: Please explain below | \$ -         |
|                             | Ś -          |

|                                            | Total Budgetary Cost Estimate: | >  | 6,600,000 |
|--------------------------------------------|--------------------------------|----|-----------|
| Means of Fina                              | ncing                          |    |           |
| Funding Subclass                           |                                |    | Amount    |
| Program Support/Revenue                    |                                |    |           |
| inancing/Debt Issuance                     |                                | \$ | 6,600,000 |
| ederal, State, Other: Please explain below |                                | \$ | -         |
|                                            |                                | \$ | -         |
|                                            |                                | \$ | -         |
| ocal Funding                               |                                | \$ | -         |
|                                            | Total Funding:                 | \$ | 6,600,000 |
| CONTACT PERSON: Mark Tschirhart            |                                |    |           |

CONTACT PERSON: Mark Tschirhart
PHONE: 757.876.8681

## Capital Improvement Program Submission Fiscal Years 2024 - 2029

|                                | Capital Improvement Frogram Submission Fiscal Tears 2024 - 2025 |                   |
|--------------------------------|-----------------------------------------------------------------|-------------------|
| PROJECT NUMBER: N/A            | PROJECT NAME: Expand Bus Loop and Parking Lot                   | STATUS: Requested |
| CATEGORY: SBO Admin. Svcs.     | DEPARTMENT: YCSD Capital Plans & Projects                       | DIVISION: YCSD    |
| PROJECT TYPE: New Construction |                                                                 | FUND: 70          |

PROJECT LOCATION: Queens Lake Middle School

|                     | Programmed Funding |        |                                         |        |           |        |        |                |  |  |  |  |  |  |  |
|---------------------|--------------------|--------|-----------------------------------------|--------|-----------|--------|--------|----------------|--|--|--|--|--|--|--|
| Total               | Appropriated       |        | Non-Appropriated programmed CIP Funding |        |           |        |        |                |  |  |  |  |  |  |  |
| Project Cost        | To Date            | FY2024 | FY2025                                  | FY2026 | FY2027    | FY2028 | FY2029 | Future Funding |  |  |  |  |  |  |  |
| \$ 815,000          | N/A                | \$ -   |                                         |        | \$815,000 | \$ -   | \$ -   | N/A            |  |  |  |  |  |  |  |
| FY2023 Approved CIP |                    |        | \$ -                                    | \$ -   | \$ -      | \$ -   | \$ -   | N/A            |  |  |  |  |  |  |  |
| FY2022 Approved CIP |                    | \$ -   | \$ -                                    | \$ -   | \$ -      | \$ -   | \$ -   | N/A            |  |  |  |  |  |  |  |

#### Description, Scope and Timeline

Funding is requested to design and construct additional parking as well as to separate the bus and personal vehicle traffic patterns. Anticipated Timeline:

Funding - July 2026

A&E Design Complete - November 2026 Invitation for Bids - November 2026 Construction - Summer 2027

#### **Purpose and Need**

The bus and personal vehicle traffic patterns at the school should be separated to increase safety. The volume of vehicular traffic entering the parking lot causes tie ups on West Queens Drive during arrival and dismissal times. Pedestrian and vehicular traffic is a safety concern. Additional parking space is also needed for meetings, special events and Parks & Recreation activities.

## **History and Current Status**

As more parents drive their students to school, it is causing increased congestion at the school. More parking and a separate bus loop is needed to relieve congestion and improve traffic flow. There is a need to hire a civil engineer to study the issue and provide a solution which can be implemented to improve safety for both pedestrian and vehicular traffic.

## **Operating Budget Impacts**


There will be additional utility and maintenance costs which will be necessary in order to support and maintain the larger parking lot.

## Anticipated Performance/Outcome Measures

Additional parking will help relieve congestion and increase safety. Improvements are consistent with other YCSD parking lot upgrades.

#### 







| Means of Financing                          | 5              |            |
|---------------------------------------------|----------------|------------|
| Funding Subclass                            | Amount         |            |
| Program Support/Revenue                     |                |            |
| Financing/Debt Issuance                     |                | \$ 815,000 |
| Federal, State, Other: Please explain below |                | \$ -       |
|                                             |                | \$ -       |
|                                             |                | \$ -       |
| Local Funding - CASH                        |                |            |
|                                             | Total Funding: | \$ 815,000 |
| CONTACT DEDCON. Mark Tachirhart             |                |            |

CONTACT PERSON: Mark Tschirhart
PHONE: 757.876.8681

|                                 | Capital improvement Program Submission Fiscal Years 2024 - 2029 |                   |
|---------------------------------|-----------------------------------------------------------------|-------------------|
| PROJECT NUMBER: N/A             | PROJECT NAME: Expansion (8) Classrooms A&E + Construction       | STATUS: Requested |
| CATEGORY: SBO Admin. Svcs.      | DEPARTMENT: YCSD Capital Plans & Projects                       | DIVISION: YCSD    |
| PROJECT TYPE: A&F + New Constru | ction                                                           | FUND: 70          |

PROJECT LOCATION: Queens Lake Middle School

|              | Programmed Funding |              |        |    |                                         |    |           |    |           |    |           |    |        |   |                |
|--------------|--------------------|--------------|--------|----|-----------------------------------------|----|-----------|----|-----------|----|-----------|----|--------|---|----------------|
|              | Total              | Appropriated |        |    | Non-Appropriated programmed CIP Funding |    |           |    |           |    |           |    |        |   |                |
| Project Cost |                    | To Date      | FY2024 |    | FY2025                                  |    | FY2026    |    | FY2027    |    | FY2028    |    | FY2029 |   | Future Funding |
| \$           | 20,711,208         | N/A          |        | \$ | 1,111,208                               | \$ | 1,600,000 | \$ | 9,000,000 | \$ | 9,000,000 | \$ |        | - | N/A            |
| FY2          | 023 Approved CIP   |              |        |    |                                         |    |           | \$ | -         | \$ | -         | \$ |        | - | N/A            |
| FY2          | 022 Approved CIP   |              | \$ -   | \$ | -                                       | \$ |           | \$ | -         | \$ |           | \$ |        | - | N/A            |

#### **Description, Scope and Timeline**

Funding is requested for the expansion of Queens Lake Middle. Architectural & engineering design will be provided for an eight classroom addition, cafeteria expansion, and main office expansion. Construction will follow in FY 2027 and 2028.

Anticipated Timeline:

Funding: July 2025, 2026, 2027 and 2028 A&E Design Complete: July 2026 Solicitation for Bids: July 2026 Construction: July 2027 - August 2028

## **Purpose and Need**

Due to increased residential construction and increasing enrollment in the school zone, additional classroom space is needed.

The school was expanded and renovated in 2004 to meet increasing enrollment. Continuing residential development in the school zone is again driving the need for further classroom expansion as enrollment rises.

## **Operating Budget Impacts**

The additional square footage will increase utility costs. Additional teaching staff will be required and more maintenance staff will be needed to maintain the building.

## Anticipated Performance/Outcome Measures

Additional classrooms will relieve pressure, reduce class sizes and provide a better learning and teaching environment. Improvements will be consistent with other YCSD classroom additions.

| ı | Strategic Plan Goals (Check all applicable) |                     |   |                         |  |  |  |  |  |  |  |  |
|---|---------------------------------------------|---------------------|---|-------------------------|--|--|--|--|--|--|--|--|
|   | Χ                                           | Student Achievement |   | School Culture          |  |  |  |  |  |  |  |  |
|   | Χ                                           | Student Experiences | Х | Operational Stewardship |  |  |  |  |  |  |  |  |
| Γ | Χ                                           | Staff Support       |   |                         |  |  |  |  |  |  |  |  |





| Schedule of Activities         |                  |
|--------------------------------|------------------|
| Project Activities             | Amount           |
| A&E                            | \$<br>2,071,121  |
| Land                           | \$<br>-          |
| Building                       | \$<br>16,568,966 |
| Furnishings                    | \$<br>-          |
| Equipment                      | \$<br>-          |
| Contingencies                  | \$<br>2,071,121  |
| Other: Please explain below    | \$<br>-          |
|                                | \$<br>-          |
| Total Budgetary Cost Estimate: | \$<br>20,711,208 |

|                                             | rotal Budgetally cost Estimate. | ٠  |            |
|---------------------------------------------|---------------------------------|----|------------|
| Means of Fin                                | ancing                          |    |            |
| Funding Subclass                            |                                 |    | Amount     |
| Program Support/Revenue                     |                                 |    |            |
| Financing/Debt Issuance                     |                                 | \$ | 19,600,000 |
| Federal, State, Other: Please explain below |                                 | \$ | -          |
|                                             |                                 | \$ | -          |
|                                             |                                 | \$ | -          |
| Local Funding: Proffer                      |                                 | \$ | 1,111,208  |
|                                             | Total Funding:                  | \$ | 20,711,208 |
| CONTACT PERSON: Mark Tschirhart             |                                 |    |            |

**PHONE:** 757.876.8681

# County of York, Virginia Capital Improvement Program Submission Fiscal Years 2024 - 2029 PROJECT NUMBER: N/A PROJECT NAME: Renovate Locker Rooms STATUS: Requested DIVISION: YCSD PROJECT TYPE: Renovation PROJECT LOCATION: Queens Lake Middle School

| Programmed Funding  |              |    |        |        |                                         |        |    |         |    |        |    |        |     |                |  |
|---------------------|--------------|----|--------|--------|-----------------------------------------|--------|----|---------|----|--------|----|--------|-----|----------------|--|
| Total               | Appropriated |    |        |        | Non-Appropriated programmed CIP Funding |        |    |         |    |        |    |        |     |                |  |
| Project Cost        | To Date      |    | FY2024 | FY2025 |                                         | FY2026 |    | FY2027  |    | FY2028 |    | FY2029 |     | Future Funding |  |
| \$ 660,000          | N/A          | \$ | -      |        | \$                                      | 60,000 | \$ | 600,000 | \$ | -      | \$ |        | -   | N/A            |  |
| FY2023 Approved CIP |              |    |        |        | \$                                      | -      | \$ | -       | \$ | -      | \$ |        | - [ | N/A            |  |
| FY2022 Approved CIP |              | \$ |        |        | \$                                      |        | \$ | -       | \$ | -      | \$ |        | -   | N/A            |  |

#### **Description, Scope and Timeline**

Funding is requested to completely renovate the locker rooms.

Timeline:

Funding - July 2024, July 2025 A&E Design Complete - May 2025 Invitation for Bids - May 2025 Construction - Summer 2026

## Purpose and Need

The existing locker rooms are in very poor condition.

#### History and Current Status

The school was opened in 1966 and the locker rooms will be 59 years old in FY2025. The locker rooms were not upgraded during the 2004 renovation.

## **Operating Budget Impacts**

New fixtures and new lockers will require less maintenance and will reduce maintenance costs.

## **Anticipated Performance/Outcome Measures**

The locker room renovations will be ADA compliant and provide a better environment for students.

|   |   | Strategic Plan      | Goals (Check all | applicable)             |
|---|---|---------------------|------------------|-------------------------|
|   | Χ | Student Achievement |                  | School Culture          |
| I | Χ | Student Experiences | Х                | Operational Stewardship |
| ſ | Χ | X Staff Support     |                  |                         |





| Schedule of Activities                      |            |
|---------------------------------------------|------------|
| Project Activities                          | Amount     |
| A&E                                         | \$ 66,000  |
| Land                                        | \$ -       |
| Construction                                | \$ 528,000 |
| Furnishings                                 | \$ -       |
| Equipment                                   | \$ -       |
| Contingencies                               | \$ 66,000  |
| Other: Please explain below                 | \$ -       |
|                                             | \$ -       |
| Total Budgetary Cost Estimate:              | \$ 660,000 |
| Means of Financing                          |            |
| Funding Subclass                            | Amount     |
| Program Support/Revenue                     |            |
| Financing/Debt Issuance                     | \$ 660,000 |
| Federal, State, Other: Please explain below | \$ -       |
|                                             | \$ -       |
|                                             | \$ -       |
| Local Funding - CASH                        |            |
| Total Funding:                              | \$ 660,000 |
| CONTACT PERSON: Mark Tschirhart             |            |
| <b>PHONE:</b> 757.876.8681                  |            |

Anticipated

# County of York, Virginia Capital Improvement Program Submission Fiscal Years 2024 - 2029 PROJECT NUMBER: N/A PROJECT NAME: Renovate Locker Rooms STATUS: Requested CATEGORY: SBO Admin. Svcs. DEPARTMENT: YCSD Capital Plans & Projects DIVISION: YCSD PROJECT TYPE: Renovation PROJECT LOCATION: Tabb Middle School

| Programmed Funding |                             |     |        |    |                                         |        |         |    |        |    |        |        |  |   |                |  |
|--------------------|-----------------------------|-----|--------|----|-----------------------------------------|--------|---------|----|--------|----|--------|--------|--|---|----------------|--|
| Total Appropriated |                             |     |        |    | Non-Appropriated programmed CIP Funding |        |         |    |        |    |        |        |  |   |                |  |
|                    | Project Cost To Date FY2024 |     | FY2024 |    | FY2025                                  | FY2026 |         |    | FY2027 |    | FY2028 | FY2029 |  |   | Future Funding |  |
| \$                 | 660,000                     | N/A |        | \$ | 60,000                                  | \$     | 600,000 |    |        | \$ |        | \$     |  | - | N/A            |  |
| F                  | Y2023 Approved CIP          |     |        |    |                                         | \$     | -       | \$ | -      | \$ | -      | \$     |  | - | N/A            |  |
| F                  | Y2022 Approved CIP          |     | \$ -   | \$ | -                                       | \$     | -       | \$ | -      | \$ | -      | \$     |  | - | N/A            |  |

#### **Description, Scope and Timeline**

Funding is requested to completely renovate the locker rooms.

Anticipated Timeline:

Funding - July 2024, July 2025 A&E Design Complete - May 2025 Invitation for Bids - June 2025 Construction - Summer 2025

#### Purpose and Need

The existing locker rooms are in very poor condition and in need of repair.

## History and Current Status

The school was constructed in 1967 and the existing locker rooms will be 58 years old in FY2025 and were not renovated during the 2000 renovations.

## Operating Budget Impacts


New plumbing fixtures and lockers will require less repairs and reduce maintenance costs. New LED lighting will also reduce operating costs.

## **Anticipated Performance/Outcome Measures**

The locker room renovations will be ADA compliant and provide a better environment for students.

| Strategic Plan Goals (Check all applicable) |   |                     |   |                         |  |  |  |  |  |  |  |
|---------------------------------------------|---|---------------------|---|-------------------------|--|--|--|--|--|--|--|
|                                             | Χ | Student Achievement |   | School Culture          |  |  |  |  |  |  |  |
| ſ                                           | Χ | Student Experiences | Х | Operational Stewardship |  |  |  |  |  |  |  |
| ſ                                           | Х | X Staff Support     |   |                         |  |  |  |  |  |  |  |







| Total B                                     | udgetary Cost Estimate: \$ | 660,000 |
|---------------------------------------------|----------------------------|---------|
| Means of Financing                          |                            |         |
| Funding Subclass                            |                            | Amount  |
| Program Support/Revenue                     | \$                         | -       |
| Financing/Debt Issuance                     | \$                         | 660,000 |
| Federal, State, Other: Please explain below | \$                         | -       |
|                                             | \$                         | -       |
|                                             | \$                         | -       |
| Local Funding - Cash                        |                            |         |
|                                             | Total Funding: \$          | 660,000 |
| CONTACT PERSON: Mark Tschirhart             |                            |         |

**PHONE:** 757.876.8681

## Capital Improvement Program Submission Fiscal Years 2024 - 2029

|                                             | capital improvement i rogiam sasmission i scale Leur Leurs          |                   |  |  |  |  |  |  |  |  |
|---------------------------------------------|---------------------------------------------------------------------|-------------------|--|--|--|--|--|--|--|--|
| N/A                                         | PROJECT NAME: Replace HVAC Equipment and Building Automation System | STATUS: Requested |  |  |  |  |  |  |  |  |
| CATEGORY: SBO Admin. Svcs.                  | DEPARTMENT: YCSD Capital Plans & Projects                           | DIVISION: YCSD    |  |  |  |  |  |  |  |  |
| PROJECT TYPE: Replace HVAC and RAS Controls |                                                                     |                   |  |  |  |  |  |  |  |  |

PROJECT LOCATION: Tabb Middle School

|                     | Programmed Funding |              |                                         |        |        |        |        |                |  |  |  |  |
|---------------------|--------------------|--------------|-----------------------------------------|--------|--------|--------|--------|----------------|--|--|--|--|
| Total               | Appropriated       |              | Non-Appropriated programmed CIP Funding |        |        |        |        |                |  |  |  |  |
| Project Cost        | To Date            | FY2024       | FY2025                                  | FY2026 | FY2027 | FY2028 | FY2029 | Future Funding |  |  |  |  |
| \$ 6,000,000        | \$ 4,200,000       | \$ 1,800,000 | \$ -                                    | \$ -   | \$ -   | \$ -   | \$ -   | N/A            |  |  |  |  |
| FY2023 Approved CIP | \$ 4,200,000       | \$ -         | \$ -                                    | \$ -   | \$ -   | \$ -   | \$ -   | N/A            |  |  |  |  |
| FY2022 Approved CIP |                    | \$ -         | \$ -                                    | \$ -   | \$ -   | \$ -   | \$ -   | N/A            |  |  |  |  |

#### Description, Scope and Timeline

Funding is requested to remove and replace the existing geothermal water-sourced heat pumps, make-up air units, chiller and building automation controls.

Anticipated Timeline:

Funding - July 2022

A&E Design Complete - November 2022 Invitation for Bids - November 2022 Construction - June 2023 - August 2024

#### **Purpose and Need**

The existing geothermal heat pumps and make-up air units are at the end of useful life and need to be replaced. They are designed for operation with R-22 refrigerant which has become obsolete. Repair parts are difficult to obtain resulting in extended down time which impacts indoor air quality within the complex.

#### **History and Current Status**

The existing HVAC system, consisting of geothermal heat pumps and make-up air units, was installed in 2000 and will be 23 years old in FY 2023. Equipment is at the end of useful life and needs to be replaced. Improvements will be consistent with other YCSD HVAC system and controls replacements.

## **Operating Budget Impacts**

The new geothermal heat pumps, make-up air units and building automation system will be more efficient reducing operating and repair costs.

## Anticipated Performance/Outcome Measures

Better temperature and humidity control will save operating costs through energy efficiency. Improved indoor air quality will contribute to an enhanced learning environment.

|   | Strategic Plan Goals (Check all applicable) |   |                         |  |  |  |  |  |  |  |  |
|---|---------------------------------------------|---|-------------------------|--|--|--|--|--|--|--|--|
| Х | Student Achievement                         |   | School Culture          |  |  |  |  |  |  |  |  |
| Х | Student Experiences                         | Х | Operational Stewardship |  |  |  |  |  |  |  |  |
| Х | Staff Support                               |   |                         |  |  |  |  |  |  |  |  |



| Schedule of Activities                   |    |           |
|------------------------------------------|----|-----------|
| Project Activities                       | -  | Amount    |
| A&E                                      | \$ | 600,000   |
| Land                                     | \$ |           |
| Construction                             | \$ | 4,800,000 |
| Furnishings                              | \$ | -         |
| Equipment                                | \$ | -         |
| Contingencies                            | \$ | 600,000   |
| Other: Please explain below              | \$ | 1,800,000 |
| Additional estimated costs from engineer | \$ | -         |
| Total Budgetary Cost Estimate:           | \$ | 7,800,000 |



|                                             |         | -,,       |
|---------------------------------------------|---------|-----------|
| Means of Financing                          |         |           |
| Funding Subclass                            |         | Amount    |
| Program Support/Revenue                     |         |           |
| Financing/Debt Issuance                     | \$      | 4,340,000 |
| Federal, State, Other: Please explain below | \$      | -         |
|                                             | \$      | -         |
|                                             | \$      | -         |
| Local Funding - ESSER Recapture / EOY Funds | \$      | 1,660,000 |
| Total Fund                                  | ing: \$ | 6,000,000 |
| CONTACT PERSON: Mark Tschirhart             |         |           |
| PHONE: 757.876.8681                         |         |           |

## County of York, Virginia Capital Improvement Program Submission Fiscal Years 2024 - 2029 PROJECT NUMBER: N/A PROJECT NAME: Renovate Locker Rooms STATUS: Requested CATEGORY: SBO Admin. Svcs. DEPARTMENT: YCSD Capital Plans & Projects DIVISION: YCSD PROJECT TYPE: Renovations FUND: 70

PROJECT LOCATION: Yorktown Middle School

|                    | Programmed Funding |         |        |    |                                         |    |         |    |        |    |        |    |        |  |                |
|--------------------|--------------------|---------|--------|----|-----------------------------------------|----|---------|----|--------|----|--------|----|--------|--|----------------|
| Total Appropriated |                    |         |        |    | Non-Appropriated programmed CIP Funding |    |         |    |        |    |        |    |        |  |                |
| Project Cost       |                    | To Date | FY2024 |    | FY2025                                  |    | FY2026  |    | FY2027 |    | FY2028 |    | FY2029 |  | Future Funding |
| \$                 | 660,000            | N/A     |        | \$ | 60,000                                  | \$ | 600,000 | \$ | -      | \$ | -      | \$ | -      |  | N/A            |
| FY2023 App         | oroved CIP         |         |        |    |                                         | \$ |         | \$ | -      | \$ | -      | \$ | -      |  | N/A            |
| FY2022 App         | proved CIP         |         | \$ -   | \$ | -                                       | \$ | -       | \$ | -      | \$ | -      | \$ | -      |  | N/A            |

#### **Description, Scope and Timeline**

Funding is requested to completely renovate the locker rooms.

Anticipated Timeline:

Funding - July 2024, July 2025 A&E Design Complete - May 2025 Invitation for Bids - June 2025 Construction - Summer 2026

#### **Purpose and Need**

The existing locker rooms are in very poor condition and in need of repair.

## **History and Current Status**

The original building was opened in 1954. The existing locker rooms will be 70 years old in FY2024 and were not upgraded during the 2007 renovation.

## Operating Budget Impacts

New plumbing fixtures and lockers will require less repairs and reduce maintenance costs. New LED lighting will also reduce operating costs.

#### Anticipated Performance/Outcome Measures

The renovated locker rooms will be ADA compliant and provide a better environment for students.

|   | Strategic Plan      | Goals (Check all | applicable)             |
|---|---------------------|------------------|-------------------------|
| Χ | Student Achievement |                  | School Culture          |
| Χ | Student Experiences | Х                | Operational Stewardship |
| Х | X Staff Support     |                  |                         |



# County of York, Virginia Capital Improvement Program Submission Fiscal Years 2024 - 2029 PROJECT NUMBER: N/A PROJECT NAME: Renovate Locker Rooms STATUS: Requested DIVISION: YCSD PROJECT TYPE: Renovation PROJECT LOCATION: Bruton High School

|     |                   |              |         |                                         | Pro | og     | rammed Fundin | ıg |        |                |         |    |   |   |     |
|-----|-------------------|--------------|---------|-----------------------------------------|-----|--------|---------------|----|--------|----------------|---------|----|---|---|-----|
|     | Total             | Appropriated |         | Non-Appropriated programmed CIP Funding |     |        |               |    |        |                |         |    |   |   |     |
|     | Project Cost      | To Date      | FY2024  | 24 FY2025 FY2026 FY2027 FY2028          |     | FY2028 | FY2029        |    |        | Future Funding |         |    |   |   |     |
| \$  | 990,000           | N/A          | \$<br>- |                                         |     |        |               | \$ | 90,000 | \$             | 900,000 | \$ | - | - | N/A |
| FY2 | 2023 Approved CIP |              |         |                                         |     |        | \$ -          | \$ | -      | \$             | -       | \$ | - | - | N/A |
| FY2 | 2022 Approved CIP |              | \$<br>• | \$                                      | -   | 1      | \$ -          | \$ | -      | \$             | -       | \$ | - | - | N/A |

## **Description, Scope and Timeline**

Funding is requested to completely renovate the locker rooms.

Anticipated Timeline:

Funding - July 2026 & July 2027

A&E Design Complete - November 2026 Invitation for Bids - November 2026 Construction - Summer 2027

## **Purpose and Need**

The current locker rooms are in poor condition and in need of repair.

## **History and Current Status**

The school opened in 1976 and the locker rooms are 46 years old. They were not renovated during the 2002 renovation.


## Operating Budget Impacts

New fixtures and lockers will require less maintenance and reduce maintenance costs. Low flow plumbing fixtures will use less water.

## Anticipated Performance/Outcome Measures

The locker room renovations will be ADA compliant and provide a better environment for students.

## Strategic Plan Goals (Check all applicable) X Student Achievement School Culture X Student Experiences X Operational Stewardship X Staff Support \_\_\_\_\_\_ Staff Support





| Means of Financing                          |            |
|---------------------------------------------|------------|
| Funding Subclass                            | Amount     |
| Program Support/Revenue                     |            |
| Financing/Debt Issuance                     | \$ 990,000 |
| Federal, State, Other: Please explain below | \$ -       |
|                                             | \$ -       |
|                                             | \$ -       |
| Local Funding - CASH                        |            |
| Total Funding:                              | \$ 990,000 |
| CONTACT PERSON: Mark Tschirhart             |            |
| PHONE: 757.876.8681                         |            |

## County of York, Virginia Capital Improvement Program Submission Fiscal Years 2024 - 2029 PROJECT NUMBER: N/A PROJECT NAME: Replace HVAC Equipment and Building Automation System STATUS: Requested DIVISION: YCSD Capital Plans & Projects PROJECT TYPE: Replace HVAC and BAS Controls FUND: 70

PROJECT LOCATION: Bruton High School

|                     | Programmed Funding |        |                                         |              |        |        |        |                |  |  |  |  |  |  |  |
|---------------------|--------------------|--------|-----------------------------------------|--------------|--------|--------|--------|----------------|--|--|--|--|--|--|--|
| Total               | Appropriated       |        | Non-Appropriated programmed CIP Funding |              |        |        |        |                |  |  |  |  |  |  |  |
| Project Cost        | To Date            | FY2024 | FY2025                                  | FY2026       | FY2027 | FY2028 | FY2029 | Future Funding |  |  |  |  |  |  |  |
| \$ 3,400,000        | \$ -               | \$ -   | \$ -                                    | \$ 3,400,000 |        |        | \$ -   | N/A            |  |  |  |  |  |  |  |
| FY2023 Approved CIP |                    | \$ -   | \$ -                                    | \$ -         |        | \$ -   | \$ -   | N/A            |  |  |  |  |  |  |  |
| FY2022 Approved CIP |                    | \$ -   | \$ -                                    | \$ -         | \$ -   | \$ -   | \$ -   | N/A            |  |  |  |  |  |  |  |

#### Description, Scope and Timeline

Funding is requested to repair and coat the roof

Anticipated Timeline:

Funding - July 2025

A&E Design Complete - November 2025 Invitation for Bids - November 2025 Construction - Summers 2026 & 2027

#### **Purpose and Need**

The existing geothermal heat pumps and make-up air units are at the end of useful life and need to be replaced. They are designed for operation with R-22 refrigerant which has become obsolete. Repair parts are difficult to obtain resulting in extended down time which impacts indoor air quality within the complex.

#### **History and Current Status**

The existing HVAC system, consisting of geothermal heat pumps and make-up air units, was installed in 2002 and will be 25 years old in FY 2027. Equipment is at the end of useful life and needs to be replaced. Improvements will be consistent with other YCSD HVAC system and controls replacements.

## **Operating Budget Impacts**

The new geothermal heat pumps, make-up air units and building automation system will be more efficient reducing operating and repair costs.

## Anticipated Performance/Outcome Measures

Better temperature and humidity control will save operating costs through energy efficiency. Improved indoor air quality will contribute to an enhanced learning environment.

| Strategic Plan Goals (Check all applicable) |                     |   |                         |  |  |  |  |  |  |  |  |
|---------------------------------------------|---------------------|---|-------------------------|--|--|--|--|--|--|--|--|
| Χ                                           | Student Achievement |   | School Culture          |  |  |  |  |  |  |  |  |
| Χ                                           | Student Experiences | Х | Operational Stewardship |  |  |  |  |  |  |  |  |
| Х                                           | Staff Support       |   |                         |  |  |  |  |  |  |  |  |



| 9                           | chedule of Activities          |                 |
|-----------------------------|--------------------------------|-----------------|
| Project A                   | ctivities                      | Amount          |
| A&E                         |                                | \$<br>340,000   |
| Land                        |                                | \$<br>-         |
| Construction                |                                | \$<br>2,720,000 |
| Furnishings                 |                                | \$<br>-         |
| Equipment                   |                                | \$<br>-         |
| Contingencies               |                                | \$<br>340,000   |
| Other: Please explain below |                                | \$<br>-         |
|                             |                                | \$<br>-         |
|                             | Total Budgetary Cost Estimate: | \$<br>3,400,000 |



| Means of Financing                          |            |           |
|---------------------------------------------|------------|-----------|
| Funding Subclass                            |            | Amount    |
| Program Support/Revenue                     |            |           |
| Financing/Debt Issuance                     | \$         | 3,400,000 |
| Federal, State, Other: Please explain below | \$         | -         |
|                                             | \$         | -         |
|                                             | \$         | -         |
| Local Funding                               | \$         | -         |
| Total F                                     | unding: \$ | 3,400,000 |
| CONTACT PERSON: Mark Tschirhart             |            |           |
| PHONE: 757.876.8681                         |            |           |

## County of York, Virginia Capital Improvement Program Submission Fiscal Years 2024- 2029 PROJECT NUMBER: N/A PROJECT NAME: Replace / Coat Low Slope Roof Phases 1 & 2 CATEGORY: SBO Admin. Svcs. PROJECT TYPE: Roof Replacement County of York, Virginia STATUS: Requested DIVISION: YCSD FUND: 70

PROJECT LOCATION: Bruton High School

|                     | Programmed Funding |        |           |        |                                         |    |        |        |   |        |   |        |   |  |                |  |
|---------------------|--------------------|--------|-----------|--------|-----------------------------------------|----|--------|--------|---|--------|---|--------|---|--|----------------|--|
| Total Appropriated  |                    |        |           |        | Non-Appropriated programmed CIP Funding |    |        |        |   |        |   |        |   |  |                |  |
| Project Cost        | To Date            | FY2024 |           | FY2025 |                                         |    | FY2026 | FY2027 |   | FY2028 |   | FY2029 |   |  | Future Funding |  |
| \$ 5,500,000        |                    | \$     | 1,700,000 | \$     | 3,800,000                               |    |        | \$     | - | \$     | - | \$     | - |  | N/A            |  |
| FY2023 Approved CIP |                    |        |           | \$     | -                                       | \$ | -      | \$     | - | \$     | - | \$     | - |  | N/A            |  |
| FY2022 Approved CIP |                    | \$     | -         | \$     | -                                       | \$ | -      | \$     | - | \$     | - | \$     | - |  | N/A            |  |

#### **Description, Scope and Timeline**

Funding is requested to repair and coat the existing low slope roof.

Timeline:

Funding - July 2023 &2024

A&E Design Complete - November 2023 Invitation for Bids - November 2023 Construction - Summer 2024 & 2025

#### **Purpose and Need**

In order to preserve the existing low slope roof integrity, repairing and coating the low slope roof is necessary. A 20 year warranty will be provided following completion.

#### **History and Current Status**

The roof was replaced in 2002. In 2024 it will be 22 years old and in need of repair and a protective coating.

#### **Operating Budget Impacts**

Repairing the roof and applying the white coating will reduce maintenance and HVAC operating costs.

## **Anticipated Performance/Outcome Measures**

Preventing roof leaks will help prevent humidity issues and stained ceiling tiles, providing a healthy learning environment. The new roof coating will enable HVAC systems to maintain better control of building temperature and humidity.

|   |   | Strategic Plan Goals (Check all applicable) |   |                         |  |  |  |  |  |  |  |  |
|---|---|---------------------------------------------|---|-------------------------|--|--|--|--|--|--|--|--|
| I | Χ | Student Achievement                         |   | School Culture          |  |  |  |  |  |  |  |  |
| I | Χ | Student Experiences                         | Х | Operational Stewardship |  |  |  |  |  |  |  |  |
| Γ | Х | Staff Support                               |   |                         |  |  |  |  |  |  |  |  |



| Project Activities             | Amount          |
|--------------------------------|-----------------|
| A&E                            | \$<br>550,000   |
| and                            | \$<br>-         |
| Construction                   | \$<br>4,450,000 |
| Furnishings                    | \$<br>-         |
| Equipment                      | \$<br>-         |
| Contingencies                  | \$<br>500,000   |
| Other: Please explain below    | \$<br>-         |
|                                | \$<br>-         |
| Total Budgetary Cost Estimate: | \$<br>5,500,000 |

Schedule of Activities



| ivieans of Financin                         | g              |                 |
|---------------------------------------------|----------------|-----------------|
| Funding Subclass                            | Amount         |                 |
| Program Support/Revenue                     |                |                 |
| Financing/Debt Issuance                     |                | \$<br>5,500,000 |
| Federal, State, Other: Please explain below |                | \$<br>-         |
|                                             |                | \$<br>-         |
|                                             |                | \$<br>-         |
| Local Funding                               |                | \$<br>-         |
|                                             | Total Funding: | \$<br>5,500,000 |
| CONTACT PERSON: Mark Tschirhart             |                |                 |

ONTACT PERSON: Mark Tschirhart
PHONE: 757.876.8681

Anticipated

## County of York, Virginia Capital Improvement Program Submission Fiscal Years 2024 - 2029

|                                  | Capital improvement Program Submission Piscal Teals 2024 - 2025                    |                   |
|----------------------------------|------------------------------------------------------------------------------------|-------------------|
| PROJECT NUMBER: N/A              | PROJECT NAME: A&E + Replace HVAC Equipment & BAS Controls - Add Security Vestibule | STATUS: Requested |
| CATEGORY: SBO Admin. Svcs.       | DEPARTMENT: YCSD Capital Plans & Projects                                          | DIVISION: YCSD    |
| PROJECT TYPE: A&E + HVAC Replace | ement and Partial Renovation                                                       | FUND: 2500        |

PROJECT LOCATION: Tabb High School

|                    | Programmed Funding |              |    |           |    |                                         |      |              |        |    |        |   |        |  |   |                |
|--------------------|--------------------|--------------|----|-----------|----|-----------------------------------------|------|--------------|--------|----|--------|---|--------|--|---|----------------|
| Total Appropriated |                    |              |    |           |    | Non-Appropriated programmed CIP Funding |      |              |        |    |        |   |        |  |   |                |
| Project Cost       |                    | To Date      |    | FY2024    |    | FY2025                                  |      | FY2026       | FY2027 |    | FY2028 |   | FY2029 |  |   | Future Funding |
| \$                 | 12,970,000         | \$ 1,500,000 | \$ | 4,470,000 | \$ | 7,000,000                               |      |              |        |    | ٧,     | - | \$     |  | - | N/A            |
| FY202              | 23 Approved CIP    |              |    |           |    |                                         |      |              |        |    | 5      | - | \$     |  | - | N/A            |
| FY202              | 22 Approved CIP    |              | \$ |           | \$ | -                                       | \$   | -            | \$     | -  | 5      | - | \$     |  | - | N/A            |
|                    |                    |              |    |           |    | Descripti                               | ion, | Scope and Ti | neli   | ne |        |   |        |  |   |                |

Funding is requested to replace the HVAC system and controls. This project will include the removal and replacement of the existing water sourced heat pumps, make-up air units, boilers and cooling towers.

Anticipated Timeline:

Funding - July 2023 & July 2024 A&E Design Complete - May 2024 Invitation for Bids - May 2024

Construction - July 2025 to August 2026

#### **Purpose and Need**

The exisiting heat pumps and make-up air units are at the end of useful life and need to be replaced. They are designed for operation with R-22 refrigerant which has become obsolete. Repair parts are difficult to obtain resulting in extended down time which impacts indoor air quality within the building.

## **History and Current Status**

The exisiting HVAC system was installed in 1998. The equipment will be 27 years old in FY2025. Equipment is at the end of useful life and requires constant repairs. Equipment should be replaced and the planned improvements will be consistent with other YCSD HVAC system replacements.

#### **Operating Budget Impacts**


The new HVAC equipment and building automation system controls will be more efficient at reducing operating and repair costs.

## Anticipated Performance/Outcome Measures

Better temperature and humidity control will save operating costs through energy efficiency. Improved indoor air quality will contribute to an enhanced learning

| ı | Strategic Plan Goals (Check all applicable) |                     |   |                         |  |  |  |  |  |  |
|---|---------------------------------------------|---------------------|---|-------------------------|--|--|--|--|--|--|
| I | Χ                                           | Student Achievement |   | School Culture          |  |  |  |  |  |  |
| ſ | Χ                                           | Student Experiences | Х | Operational Stewardship |  |  |  |  |  |  |
| ſ | Χ                                           | Staff Support       |   |                         |  |  |  |  |  |  |







|                                             | Total Daugetally Cost Lottimates | 7  |            |
|---------------------------------------------|----------------------------------|----|------------|
| Means of Fi                                 | nancing                          |    |            |
| Funding Subclass                            |                                  |    | Amount     |
| Program Support/Revenue                     |                                  | \$ | -          |
| Financing/Debt Issuance                     |                                  | \$ | 11,470,000 |
| Federal, State, Other: Please explain below |                                  | \$ | -          |
|                                             |                                  | \$ | -          |
|                                             |                                  | \$ | -          |
| Local Funding (cash)                        |                                  | \$ | 1,500,000  |
|                                             | Total Funding:                   | \$ | 12,970,000 |
| CONTACT PERSON: Mark Tschirhart             | <u> </u>                         |    |            |

PHONE: 757.876.8681

# County of York, Virginia Capital Improvement Program Submission Fiscal Years 2024 - 2029 PROJECT NUMBER: N/A PROJECT NAME: Renovate Locker Rooms STATUS: Requested CATEGORY: SBO Admin. Svcs. DEPARTMENT: YCSD Capital Plans & Projects DIVISION: YCSD PROJECT TYPE: Renovation FUND: 2500 PROJECT LOCATION: Tabb High School

|                    |                     | Programmed Funding |           |    |                                         |    |        |    |        |    |         |    |        |   |                |  |
|--------------------|---------------------|--------------------|-----------|----|-----------------------------------------|----|--------|----|--------|----|---------|----|--------|---|----------------|--|
| Total Appropriated |                     |                    |           |    | Non-Appropriated programmed CIP Funding |    |        |    |        |    |         |    |        |   |                |  |
|                    | Project Cost        | To Date            | FY2024    |    | FY2025                                  |    | FY2026 |    | FY2027 |    | FY20287 |    | FY2029 |   | Future Funding |  |
|                    | \$ 1,920,000        | N/A                | \$ 120,00 | 00 | \$ 1,800,000                            |    |        |    |        | \$ |         | \$ |        | - | N/A            |  |
|                    | FY2023 Approved CIP |                    |           |    |                                         | \$ | -      | \$ | -      | \$ | -       | \$ |        | - | N/A            |  |
|                    | FY2022 Approved CIP | •                  | \$        | -  | \$ -                                    | \$ | -      | \$ | -      | \$ | -       | \$ |        | - | N/A            |  |

#### **Description, Scope and Timeline**

Funding is requested to completely renovate the existing locker rooms.

Anticipated Timeline:

Funding - July 2023, July 2024 A&E Design Complete - November 2024 Invitation for Bids - November 2024 Construction - Summer 2025

## Purpose and Timeline

The current locker rooms are in poor condition and in need of repair.

## **History and Current Status**

The original building was opened in 1972. The existing locker rooms will be 53 years old in FY2025 and were not renovated during the 1998 renovation.

#### Operating Budget Impacts

New plumbing fixtures and lockers will require less repairs and reduce maintenance costs. New LED lighting will reduce operating costs.

## Anticipated Performance/Outcome Measures

The locker room renovations will be ADA compliant and provide a better environment for students.

|   |   | Strategic Plan Goals (Check all applicable) |   |                         |  |  |  |  |  |
|---|---|---------------------------------------------|---|-------------------------|--|--|--|--|--|
|   | Χ | Student Achievement                         |   | School Culture          |  |  |  |  |  |
|   | Χ | Student Experiences                         | Х | Operational Stewardship |  |  |  |  |  |
| ſ | X | Staff Support                               |   |                         |  |  |  |  |  |



| Schedule of Activities         |                 |
|--------------------------------|-----------------|
| Project Activities             | Amount          |
| A&E                            | \$<br>192,000   |
| Land                           | \$<br>-         |
| Construction                   | \$<br>1,536,000 |
| Furnishings                    | \$<br>-         |
| Equipment                      | \$<br>-         |
| Contingencies                  | \$<br>192,000   |
| Other: Please explain below    | \$<br>-         |
|                                | \$<br>-         |
| Total Budgetary Cost Estimate: | \$<br>1,920,000 |



| Means of Financing                          |                |                 |
|---------------------------------------------|----------------|-----------------|
| Funding Subclass                            |                | Amount          |
| Program Support/Revenue                     |                |                 |
| Financing/Debt Issuance                     |                | \$<br>1,920,000 |
| Federal, State, Other: Please explain below |                | \$<br>-         |
|                                             |                | \$<br>-         |
|                                             |                | \$<br>-         |
| Local Funding                               |                |                 |
|                                             | Total Funding: | \$<br>1,920,000 |
| CONTACT DEPSON: Mark Techirhart             |                |                 |

CONTACT PERSON: Mark Tschirhart
PHONE: 757.876.8681

# County of York, Virginia Capital Improvement Program Submission Fiscal Years 2024 - 2029 PROJECT NUMBER: N/A PROJECT NAME: Renovate Locker Room & Team Rooms CATEGORY: SBO Admin. Svcs. DEPARTMENT: YCSD Capital Plans & Projects PROJECT TYPE: Renovation PROJECT LOCATION: York High School

| Programmed Funding |                 |         |        |   |                                         |    |           |    |        |    |        |    |        |   |                |
|--------------------|-----------------|---------|--------|---|-----------------------------------------|----|-----------|----|--------|----|--------|----|--------|---|----------------|
| Total Appropriated |                 |         |        |   | Non-Appropriated programmed CIP Funding |    |           |    |        |    |        |    |        |   |                |
| F                  | Project Cost    | To Date | FY2024 |   | FY2025                                  |    | FY2026    |    | FY2027 |    | FY2028 |    | FY2029 |   | Future Funding |
| \$                 | 1,650,000       | N/A     |        |   | \$ 150,000                              | \$ | 1,500,000 | \$ | -      | \$ | -      | \$ |        | - | N/A            |
| FY202              | 23 Approved CIP |         |        |   |                                         | \$ | -         | \$ | -      | \$ | -      | \$ |        | - | N/A            |
| FY202              | 22 Approved CIP |         | \$     | - | \$ -                                    | \$ | -         | \$ | -      | \$ | -      | \$ |        | - | N/A            |

#### **Description, Scope and Timeline**

Funding is requested to completely renovate the existing locker and team rooms.

Anticipated Timeline:

Funding - July 2024, July 2025 A&E Design Complete - May 2025 Invitation for Bids - May 2025 Construction - Summer 2026

#### **Purpose and Need**

The locker and team rooms are in a very poor condition and in need of repair.

## **History and Current Status**

The original building was opened in 1954. The existing locker and team rooms will be 70 years old in FY2024 and were not upgraded during the 2006 renovation.

## Operating Budget Impacts

New plumbing fixtures and lockers will require less repairs and reduce maintenance costs. New LED lighting will also reduce operation costs.

## **Anticipated Performance/Outcome Measures**

The locker and team rooms renovations will be ADA compliant and provide a better environment for students.

|   | Strategic Plan      | Goals (Check all | applicable)             |
|---|---------------------|------------------|-------------------------|
| Χ | Student Achievement |                  | School Culture          |
| Χ | Student Experiences | Х                | Operational Stewardship |
| Χ | Staff Support       |                  |                         |



| Schedule of Activities         |                 |
|--------------------------------|-----------------|
| Project Activities             | Amount          |
| A&E                            | \$<br>165,000   |
| Land                           | \$<br>-         |
| Building                       | \$<br>1,320,000 |
| Furnishings                    | \$<br>-         |
| Equipment                      | \$<br>-         |
| Contingencies                  | \$<br>165,000   |
| Other: Please explain below    | \$<br>-         |
|                                | \$<br>-         |
| Total Budgetary Cost Estimate: | \$<br>1,650,000 |



| Wealts of Financing                         |              |
|---------------------------------------------|--------------|
| Funding Subclass                            | Amount       |
| Program Support/Revenue                     |              |
| Financing/Debt Issuance                     | \$ 1,650,000 |
| Federal, State, Other: Please explain below | \$ -         |
|                                             | \$ -         |
|                                             | \$ -         |
| Local Funding                               | \$ -         |
| Total Funding:                              | \$ 1,650,000 |
| CONTACT PERSON: Mark Tschirhart             |              |
| PHONE: 757.876.8681                         |              |

### County of York, Virginia Capital Improvement Program Submission Fiscal Years 2024 - 2029 PROJECT NAME: Construct Bus Parking Loop and Parking Lot Expansion DEPARTMENT: YCSD Capital Plans & Projects DIVISION: YCSD

**FUND:** 2500

CATEGORY: SBO Admin. Svcs. DE PROJECT TYPE: Construction Site Work

PROJECT LOCATION: York High School

PROJECT NUMBER: N/A

| Programmed Funding  |              |    |        |    |         |    |           |      |                  |     |             |     |        |     |                |
|---------------------|--------------|----|--------|----|---------|----|-----------|------|------------------|-----|-------------|-----|--------|-----|----------------|
| Total               | Appropriated |    |        |    |         |    | N         | on-A | Appropriated pro | gra | mmed CIP Fo | ınd | ing    |     |                |
| Project Cost        | To Date      |    | FY2024 |    | FY2025  |    | FY2026    |      | FY2027           |     | FY2028      |     | FY2029 |     | Future Funding |
| \$ 1,650,000        | N/A          | \$ | -      | \$ | 150,000 | \$ | 1,500,000 | \$   | -                | \$  |             | \$  |        | -   | N/A            |
| FY2023 Approved CIP |              | \$ | -      | \$ | -       | \$ | -         | \$   | -                | \$  | -           | \$  |        | - [ | N/A            |
| FY2022 Approved CIP |              | \$ | -      | \$ | -       | \$ | -         | \$   | -                | \$  | -           | \$  | -      | -   | N/A            |

### **Description, Scope and Timeline**

Funding is requested to design and construct an additional parking loop and lot will be designed and constructed. The improvements will separate the bus and personal vehicle traffic patterns. This will also provide additional parking for Bailey Field.

Anticipated Timeline:

Funding - July 2024, July 2025 A&E Design Complete - Feb 2025 Invitation for Bids -Mar 2025 Construction - Summer 2025

### Purpose and Need

Additional parking space is needed for both buses and personal vehicles. The bus and personal vehicle traffic flows will be separated to increase safety. Congested parking results in traffic tie ups and is a safety concern for both pedestrian and vehicular traffic.

### **History and Current Status**

As more students drive to school and more parents drive their students to school it is causing increased congestion at the school. More parking and a separate bus loop is needed to relieve congestion and improve traffic flow. Additional parking is needed for events at Bailey Field. A civil engineer needs to be hired to study the issue and provide a solution which can be implemented to improve safety for both pedestrian and vehicular traffic.

### Operating Budget Impacts

There will be additional maintenance costs to maintain a larger parking lot and higher utility cost for lighting the increased parking area.

### **Anticipated Performance/Outcome Measures**

Additional parking and separate bus and personal vehicle traffic flows will relieve congestion and increase safety. Improvements are consistent with other YCSD parking lots.

| Strategic Plan Goals (Check all applicable) |   |                     |   |                         |  |  |  |  |
|---------------------------------------------|---|---------------------|---|-------------------------|--|--|--|--|
|                                             | Χ | Student Achievement |   | School Culture          |  |  |  |  |
| Ī                                           | Χ | Student Experiences | Х | Operational Stewardship |  |  |  |  |
| Ī                                           | Х | Staff Support       |   |                         |  |  |  |  |



|                             | Schedule of Activities         |    |           |
|-----------------------------|--------------------------------|----|-----------|
| Project                     | Activities                     |    | Amount    |
| A&E                         |                                | \$ | 85,000    |
| Land                        |                                | \$ | -         |
| Construction                |                                | \$ | 1,400,000 |
| Furnishings                 |                                | \$ | -         |
| Equipment                   |                                | \$ | -         |
| Contingencies               |                                | \$ | 165,000   |
| Other: Please explain below |                                | \$ | -         |
|                             |                                | \$ | -         |
|                             | Total Budgetary Cost Estimate: | Ś  | 1.650.000 |



| Means of Financing                          |                 |
|---------------------------------------------|-----------------|
| Funding Subclass                            | Amount          |
| Program Support/Revenue                     | \$<br>-         |
| Financing/Debt Issuance                     | \$<br>1,650,000 |
| Federal, State, Other: Please explain below | \$<br>-         |
|                                             | \$<br>-         |
|                                             | \$<br>-         |
| Local Funding - CASH                        |                 |
| Total Funding:                              | \$<br>1,650,000 |
| CONTACT PERSON: Mark Tschirhart             |                 |
| PHONE: 757.876.8681                         | ·               |

### County of York, Virginia Capital Improvement Program Submission Fiscal Years 2024 - 2029 PROJECT NUMBER: N/A PROJECT NAME: Renovate Annex Facility STATUS: Requested CATEGORY: SBO Admin. Svcs **DEPARTMENT:** YCSD Capital Plans & Projects DIVISION: YCSD PROJECT TYPE: Renovation **FUND:** 2500 PROJECT LOCATION: York High School

|                     |              |        | Pro          | Programmed Funding |         |     |                  |     |            |     |        |   |                |
|---------------------|--------------|--------|--------------|--------------------|---------|-----|------------------|-----|------------|-----|--------|---|----------------|
| Total               | Appropriated |        |              |                    | N       | on- | Appropriated pro | gra | nmed CIP F | und | ing    |   |                |
| Project Cost        | To Date      | FY2024 | FY2025       |                    | FY2026  |     | FY2027           |     | FY2028     |     | FY2029 |   | Future Funding |
| \$ 880,000          | N/A          |        | \$<br>80,000 | \$                 | 800,000 | \$  | -                | \$  | -          | \$  |        | - | N/A            |
| FY2023 Approved CIP |              |        |              | \$                 | -       | \$  | -                | \$  | -          | \$  |        | - | N/A            |
| FY2022 Approved CIP |              | \$ -   | \$<br>-      | \$                 | -       | \$  | -                | \$  | -          | \$  |        | - | N/A            |

### **Description, Scope and Timeline**

Funding is requested to design and renovate the annex at York high School.

Anticipated Timeline:

Funding - July 2024, July 2025 A&E Design Complete - May 2025 Invitation for Bids - May 2025 Construction - Summer 2026

### Purpose and Need

The annex is in poor condition throughout and needs renoavtion.

The original building was opened in 1954. The existing building, HVAC systems, plumbing, electrical system and lighting are in poor condition. Windows are single pane with steel frames and no gaskets and need to be replaced.

### **Operating Budget Impacts**

Operationg costs should be reduced with the installation of new high efficiency HVAC systems and the replacement of T-12 fluorescent lights with LED.

### Anticipated Performance/Outcome Measures

The building will be more comfortable and usable for students and staff. Restrooms will have hot water and be ADA compliant.

### Strategic Plan Goals (Check all applicable) X Student Achievement School Culture Student Experiences Operational Stewardship Staff Support



| Schedule of Activities         |               |
|--------------------------------|---------------|
| Project Activities             | Amount        |
| A&E                            | \$<br>49,131  |
| Land                           | \$<br>-       |
| Construction                   | \$<br>742,869 |
| Furnishings                    | \$<br>-       |
| Equipment                      | \$<br>-       |
| Contingencies                  | \$<br>88,000  |
| Other: Please explain below    | \$<br>-       |
|                                | \$<br>-       |
| Total Budgetary Cost Estimate: | \$<br>880,000 |



| ivieans of Financin                         | g              |               |
|---------------------------------------------|----------------|---------------|
| Funding Subclass                            |                | Amount        |
| Program Support/Revenue                     |                | \$<br>-       |
| Financing/Debt Issuance                     |                | \$<br>880,000 |
| Federal, State, Other: Please explain below |                | \$<br>-       |
|                                             |                | \$<br>-       |
|                                             |                | \$<br>-       |
| Local Funding - CASH                        |                |               |
|                                             | Total Funding: | \$<br>880,000 |
| CONTACT PERSON: Mark Tschirhart             |                |               |
|                                             |                |               |

PHONE: 757.876.8681

### County of York, Virginia

### Capital Improvement Program Submission Fiscal Years 2024-2029

PROJECT NUMBER: N/A PROJECT NAME: Temporary Modular Classrooms STATUS: Requested
CATEGORY: SBO Admin. Svcs.
PROJECT TYPE: New Construction

PROJECT TYPE: New Construction

PROJECT TYPE: New Construction

PROJECT TYPE: New Construction

PROJECT LOCATION: Various Schools

### **Programmed Funding** Appropriated Non-Appropriated programmed CIP Funding Total FY2029 Project Cost To Date FY2024 FY2025 FY2026 FY2027 FY2028 **Future Funding** 2,700,000 300,000 350,000 \$ 350,000 350,000 450,000 500,000 FY2023 Approved CIP - \$ NΑ FY2022 Approved CIP NA - S - Š

### **Description and Scope**

Funding is requested for the leasing of existing modular classrooms and to install additional units as required by increasing student enrollment.

### **Purpose and Need**

Enrollment at multiple elemtary schools has exceeded the instructional capacity of each school for the past 3 years. Modular classrooms have been leased and are currently in use at these schools. Due to increased enrollment at several elementary schools and new residential construction, additional modular classrooms are needed.

### **History and Current Status**

Additional classroom space will be needed at these schools due to current enrollment and the continuing residential development in both school zones.

### **Operating Budget Impacts**

Modular classrooms will bring additional costs to heat, cool and light the building. Funding will be required for additional teaching, support and maintenance staff as well as for operational costs of the new modular classrooms. Additional buses and drivers will also be required to transport students.

### Anticipated Performance/Outcome Measures

Modular classrooms will relieve enrollment pressure on existing schools, reduce class sizes and provide a better learning environment.

### 



| -                                  |                                |    |           |
|------------------------------------|--------------------------------|----|-----------|
|                                    | Schedule of Activities         |    |           |
|                                    | Project Activities             | -  | Amount    |
| A&E (funding from stabilization fu | nds)                           |    |           |
| Land                               |                                | \$ |           |
| Construction                       |                                |    |           |
| Furnishings                        |                                | \$ | -         |
| Equipment                          |                                | \$ | 2,700,000 |
| Contingencies                      |                                |    |           |
| Other: Please explain below        |                                | \$ | -         |
|                                    |                                | \$ | -         |
|                                    | Total Budgetary Cost Estimate: | \$ | 2,700,000 |

| 100                                                | budgetary cost Estimate. | 7  | 2,700,000 |
|----------------------------------------------------|--------------------------|----|-----------|
| Means of Financing                                 |                          |    |           |
| Funding Subclass                                   |                          |    | Amount    |
| Program Support/Revenue (from stabilization funds) |                          |    |           |
| Financing/Debt Issuance                            |                          | \$ | 2,700,000 |
| Federal, State, Other: Please explain below        |                          | \$ | -         |
|                                                    |                          | \$ | -         |
|                                                    |                          | \$ | -         |
| Local Funding                                      |                          | \$ | -         |
|                                                    | Total Funding:           | \$ | 2,700,000 |
| CONTACT PERSON: Mark Tschirhart                    |                          |    |           |
| PHONE: 757.876.8681                                |                          |    |           |

### County of York, Virginia

### Capital Improvement Program Submission Fiscal Years 2024 - 2029

PROJECT NUMBER: N/A PROJECT NAME: MES Security Vestibule Improvements STATUS: Requested CATEGORY: SBO Admin. Svcs. DEPARTMENT: YCSD Capital Plans & Projects DIVISION: YCSD PROJECT TYPE: Equipment Replacement FUND: 2500

PROJECT LOCATION: Various

|                     | Programmed Funding |        |                                         |            |        |        |        |                |  |  |  |  |
|---------------------|--------------------|--------|-----------------------------------------|------------|--------|--------|--------|----------------|--|--|--|--|
| Total               | Appropriated       |        | Non-Appropriated programmed CIP Funding |            |        |        |        |                |  |  |  |  |
| Project Cost        | To Date            | FY2024 | FY2025                                  | FY2026     | FY2027 | FY2028 | FY2029 | Future Funding |  |  |  |  |
| \$ 100,000          | N/A                |        |                                         | \$ 100,000 |        | \$ -   | \$ -   | N/A            |  |  |  |  |
| FY2023 Approved CIF |                    |        |                                         |            | \$ -   | \$ -   | \$ -   | N/A            |  |  |  |  |
| FY2022 Approved CIF |                    | \$ -   | \$ -                                    | \$ -       | \$ -   | \$ -   | \$ -   | N/A            |  |  |  |  |

### **Description, Scope and Timeline**

Funding is requested to design and construct additional parking between the facilities as well as separate the bus and personal vehicle traffic flows.

Anticipated Timeline: Funding - July 2025

A&E Design Complete - Mar 2026 Invitation for Bids - June 2026 Construction - Summer 2027

### **Purpose and Need**

The existing security vestibule is not working as designed and needs to be improved.

### History and Current Status

The office is cramped and traffic flow through the office is congested and difficult.

### **Operating Budget Impacts**

An improved vestibule would reduce the amount of heat and air-conditioning entering and leaving the building through the front doors.

### Anticipated Performance/Outcome Measures

The improved security vestibule would improve traffic flow through the office and speed up checking students and visitors in and out.

|   | Strategic Plan Goals (Check all applicable) |   |                         |  |  |  |  |  |  |
|---|---------------------------------------------|---|-------------------------|--|--|--|--|--|--|
| Χ | Student Achievement                         |   | School Culture          |  |  |  |  |  |  |
| Х | Student Experiences                         | Х | Operational Stewardship |  |  |  |  |  |  |
| Х | Staff Support                               |   |                         |  |  |  |  |  |  |



| Schedule of Activities         |            |
|--------------------------------|------------|
| Project Activities             | Amount     |
| A&E                            |            |
| Land                           | \$ -       |
| Construction                   | \$ 100,000 |
| Furnishings                    | \$ -       |
| Equipment                      |            |
| Contingencies                  |            |
| Other: Please explain below    | \$ -       |
|                                | \$ -       |
| Total Budgetary Cost Estimate: | \$ 100,000 |

|                                             | 7 T              |         |
|---------------------------------------------|------------------|---------|
| Means of Financing                          |                  |         |
| Funding Subclass                            |                  | Amount  |
| Program Support/Revenue                     | \$               | 100,000 |
| Financing/Debt Issuance                     |                  |         |
| Federal, State, Other: Please explain below | \$               | -       |
|                                             | \$               | -       |
|                                             | \$               | -       |
| Local Funding                               | \$               | -       |
| To                                          | otal Funding: \$ | 100,000 |
| CONTACT PERSON: Mark Tschirhart             |                  |         |

CONTACT PERSON: Mark Tschirhart
PHONE: 757.876.8681

### County of York, Virginia Capital Improvement Program Submission Fiscal Years 2024 - 2029 PROJECT NUMBER: N/A PROJECT NAME: 800 MHz radio replacement STATUS: Requested **DEPARTMENT:** YCSD Capital Plans & Projects DIVISION: YCSD CATEGORY: SBO Admin. Svcs. **FUND:** 2500 PROJECT TYPE: Equipment Replacement PROJECT LOCATION: Various **Programmed Funding** Appropriated To Date Non-Appropriated programmed CIP Funding Total FY2024 FY2025 FY2026 **Future Funding Project Cost** FY2027 FY2028 750,000 N/A 250,000 250.000 250,000 FY2023 Approved CIP - \$ N/A FY2022 Approved CIP \$ - \$ - \$ - \$ N/A **Description, Scope and Timeline** Funding is requested for replacement of the school division 800 MHz radios. **Purpose and Need** The existing equipment is past the end of useful life and not compatible with new technologies. **History and Current Status** School division 800 MHz radios are 16 years old. Typical radio life expectancy is 10 years **Operating Budget Impacts** Newer equipment will require less repairs and be more compatible with current technologies. Anticipated Performance/Outcome Measures The County and School Division will be able to continue to provide effective and outstanding communications Strategic Plan Goals (Check all applicable) X Student Achievement School Culture Student Experiences Χ Operational Stewardship X Staff Support Schedule of Activities **Project Activities** Amount and Construction Furnishings Equipment 750,000 Contingencies Other: Please explain below 750,000 Total Budgetary Cost Estimate: \$ Means of Financing **Funding Subclass** Amount Program Support/Revenue 750,000 Financing/Debt Issuance ederal, State, Other: Please explain below

Local Funding

CONTACT PERSON: Mark Tschirhart
PHONE: 757.876.8681

750,000

Total Funding: \$

### County of York, Virginia Capital Improvement Program Submission Fiscal Years 2024 - 2029 PROJECT NUMBER: N/A PROJECT NAME: PA system replacement CATEGORY: SBO Admin. Svcs. DEPARTMENT: YCSD Capital Plans & Projects PROJECT TYPE: Equipment Replacement PROJECT LOCATION: Various COUNTY of York, Virginia STATUS: Requested DIVISION: YCSD PROJECT SOURCE FUND: 2500

| ļ |                     |              |                                         |    | Progra | ımır | ned Funding |    |        |    |        |  |        |   |                |  |  |
|---|---------------------|--------------|-----------------------------------------|----|--------|------|-------------|----|--------|----|--------|--|--------|---|----------------|--|--|
| ļ | Total               | Appropriated | Non-Appropriated programmed CIP Funding |    |        |      |             |    |        |    |        |  |        |   |                |  |  |
|   | Project Cost        | To Date      | FY2024                                  |    | FY2025 |      | FY2026      |    | FY2027 |    | FY2028 |  | FY2029 |   | Future Funding |  |  |
|   | \$ 750,000          | N/A          | \$<br>750,000                           |    |        |      |             |    |        | \$ | -      |  | \$     |   | N/A            |  |  |
|   | FY2023 Approved CIP |              | \$<br>-                                 | \$ | -      | \$   | -           | \$ | -      | \$ | -      |  | \$     | - | N/A            |  |  |
|   | FY2022 Approved CIP |              | \$<br>-                                 | \$ | -      | \$   | -           | \$ | -      | \$ | -      |  | \$     | - | N/A            |  |  |

### Description, Scope and Timeline

Funding is requested for replacement of the PA systems at Magruder Elementary, Dare Elementary and Waller Mill Elementary.

### Purpose and Need

The existing equipment is past the end of useful life and not compatible with new technologies.

### **History and Current Status**

Many schoool PA systems are original equipment and repair parts are hard to obtain.

### Operating Budget Impacts

Newer equipment will require less repairs and be more compatible with current technologies.

### Anticipated Performance/Outcome Measures

Schools will be able to continue to provide clear and effective communications for normal daily routines and in emergencies.

| Strategic Plan Goals (Check all applicable) |   |                     |   |                         |  |  |  |  |  |  |  |
|---------------------------------------------|---|---------------------|---|-------------------------|--|--|--|--|--|--|--|
|                                             | Χ | Student Achievement |   | School Culture          |  |  |  |  |  |  |  |
| ſ                                           | Х | Student Experiences | X | Operational Stewardship |  |  |  |  |  |  |  |
| I                                           | Х | Staff Support       |   |                         |  |  |  |  |  |  |  |

|                                | Project Activities                          | Amount        |
|--------------------------------|---------------------------------------------|---------------|
|                                | A&E                                         |               |
|                                | Land                                        | \$<br>-       |
|                                | Construction                                |               |
|                                | Furnishings                                 | \$<br>-       |
|                                | Equipment                                   | \$<br>750,000 |
|                                | Contingencies                               |               |
|                                | Other: Please explain below                 | \$<br>-       |
|                                |                                             | \$<br>-       |
| York County<br>School Division | Total Budgetary Cost Estimate:              | \$<br>750,000 |
| york Joung                     | Means of Financing                          |               |
| SCHOOL DIVISION Y              | Funding Subclass                            | Amount        |
|                                | Program Support/Revenue                     | \$<br>750,000 |
|                                | Financing/Debt Issuance                     |               |
|                                | Federal, State, Other: Please explain below | \$<br>-       |
|                                |                                             | \$<br>-       |
|                                |                                             | \$<br>-       |
|                                | Local Funding                               | \$<br>-       |
|                                | Total Funding:                              | \$<br>750,000 |
|                                | CONTACT PERSON: Mark Tschirhart             |               |
|                                | PHONE: 757.876.8681                         |               |

**Schedule of Activities** 

# County of York, Virginia Capital Improvement Program Submission Fiscal Years 2024 - 2029 PROJECT NUMBER: N/A PROJECT NAME: PA system replacement CATEGORY: SBO Admin. Svcs. DEPARTMENT: YCSD Capital Plans & Projects PROJECT TYPE: Equipment Replacement PROJECT LOCATION: Various Programmed Funding Total Appropriated Appropriated Non-Appropriated programmed CIP Funding

|                     |              |        |                                         | Progra    | ımmea Funaing |    |        |    |        |    |        |   |                |  |  |  |
|---------------------|--------------|--------|-----------------------------------------|-----------|---------------|----|--------|----|--------|----|--------|---|----------------|--|--|--|
| Total               | Appropriated |        | Non-Appropriated programmed CIP Funding |           |               |    |        |    |        |    |        |   |                |  |  |  |
| Project Cost        | To Date      | FY2024 |                                         | FY2025    | FY2026        |    | FY2027 |    | FY2028 |    | FY2029 |   | Future Funding |  |  |  |
| \$ 1,000,000        | N/A          |        | \$                                      | 1,000,000 |               |    |        | \$ | -      | \$ |        | - | N/A            |  |  |  |
| FY2023 Approved CIP |              | \$ -   | \$                                      | -         | \$ -          | \$ | -      | \$ | -      | \$ |        | - | N/A            |  |  |  |
| FY2022 Approved CIP |              | \$ -   | \$                                      | -         | \$ -          | \$ | -      | \$ | -      | \$ |        | - | N/A            |  |  |  |
| ' '                 |              | \$ -   | \$                                      | -         | \$ -          | \$ | -      | \$ | -      | \$ |        |   |                |  |  |  |

### Description, Scope and Timeline

Funding is requested for replacement of the PA systems at Queens Lake Middle, Tabb Middle, Bruton High and Tabb High.

### Purpose and Need

The existing equipment is past the end of useful life and not compatible with new technologies.

### **History and Current Status**

Mulitple schoool PA systems are original equipment and repair parts are hard to obtain.

### **Operating Budget Impacts**

Newer equipment will require less repairs and be more compatible with current technologies.

### Anticipated Performance/Outcome Measures

Schools will be able to continue to provide clear and effective communications for normal daily routines and in emergencies.

|   | Strategic Plan Go   | oals (Check all ap | plicable)               |
|---|---------------------|--------------------|-------------------------|
| Χ | Student Achievement |                    | School Culture          |
| Х | Student Experiences | X                  | Operational Stewardship |
| Х | Staff Support       |                    |                         |

**Schedule of Activities** 

|                                | Project Activities                          | Amount       |
|--------------------------------|---------------------------------------------|--------------|
|                                | A&E                                         |              |
|                                | Land                                        | \$ -         |
|                                | Construction                                |              |
|                                | Furnishings                                 | \$ -         |
|                                | Equipment                                   | \$ 1,000,000 |
|                                | Contingencies                               |              |
|                                | Other: Please explain below                 | \$ -         |
|                                |                                             | \$ -         |
| York County<br>School Division | Total Budgetary Cost Estimate:              | \$ 1,000,000 |
|                                | Means of Financing                          |              |
|                                | Funding Subclass                            | Amount       |
|                                | Program Support/Revenue                     | \$ 1,000,000 |
|                                | Financing/Debt Issuance                     |              |
|                                | Federal, State, Other: Please explain below | \$ -         |
|                                |                                             | \$ -         |
|                                |                                             | \$ -         |
|                                | Local Funding                               | \$ -         |
|                                | Total Funding:                              | \$ 1,000,000 |
|                                | CONTACT PERSON: Mark Tschirhart             |              |
|                                | PHONE: 757.876.8681                         |              |

## County of York, Virginia Capital Improvement Program Submission Fiscal Years 2024 - 2029 PROJECT NUMBER: N/A PROJECT NAME: Pre-School Learning Spaces STATUS: Requested DIVISION: YCSD PROJECT TYPE: New Construction PROJECT LOCATION: To be determined

|                    | Programmed Funding |         |    |        |   |    |                                         |     |    |        |    |            |    |           |    |           |                |
|--------------------|--------------------|---------|----|--------|---|----|-----------------------------------------|-----|----|--------|----|------------|----|-----------|----|-----------|----------------|
| Total Appropriated |                    |         |    |        |   |    | Non-Appropriated programmed CIP Funding |     |    |        |    |            |    |           |    |           |                |
| P                  | Project Cost       | To Date |    | FY2024 |   |    | FY2025                                  |     |    | FY2026 |    | FY2027     |    | FY2028    |    | FY2029    | Future Funding |
| \$                 | 6,050,000          | N/A     |    |        |   |    |                                         |     |    |        | ٧, | \$ 550,000 | \$ | 2,200,000 | \$ | 3,300,000 | NA             |
| FY202              | 23 Approved CIP    |         | \$ |        | - | \$ | -                                       | - [ | \$ | -      |    |            |    |           |    |           | NA             |
| FY202              | 22 Approved CIP    |         | \$ |        | - | \$ |                                         | -   | \$ | -      | 5  | \$ -       | \$ |           | \$ | -         | NA             |

### **Description, Scope and Timeline**

Additional pre-school spaces are needed.

Anticipated Timeline:

Funding - July 2025, July 2026, July 2027 A&E Design Complete - May 2026 Invitation for Bids - May 2026 Construction - June 2026 - August 2027

### **Purpose and Need**

Due to increased residential construction in the school zone and increasing enrollment, additional pre-school space is needed.

### **History and Current Status**

The continuing residential development is driving the need for additional pre-school classroom space.

### **Operating Budget Impacts**

Funding will be required for additional teaching, support and maintenance staff as well as for operational costs. Additional buses and drivers will also be required to transport students.

### **Anticipated Performance/Outcome Measures**

Additional pre-school space will relieve enrollment pressure on existing schools, reduce class sizes and provide a better teaching environment.

| Ì | Strategic Plan Goals (Check all applicable) |                     |   |                         |  |  |  |  |  |  |  |  |  |
|---|---------------------------------------------|---------------------|---|-------------------------|--|--|--|--|--|--|--|--|--|
| ĺ | Χ                                           | Student Achievement |   | School Culture          |  |  |  |  |  |  |  |  |  |
|   | Х                                           | Student Experiences | Х | Operational Stewardship |  |  |  |  |  |  |  |  |  |
| ſ | Χ                                           | Staff Support       |   |                         |  |  |  |  |  |  |  |  |  |

|                       | Schedule of Activities                             |    |           |
|-----------------------|----------------------------------------------------|----|-----------|
|                       | Project Activities                                 |    | Amount    |
|                       | A&E (funding from stabilization funds)             | \$ | 550,000   |
|                       | Land                                               | \$ | -         |
|                       | Construction                                       | \$ | 4,895,000 |
|                       | Furnishings                                        | \$ | -         |
|                       | Equipment                                          | \$ | -         |
|                       | Contingencies                                      | \$ | 605,000   |
| $\mathcal{I}$         | Other: Please explain below                        | \$ | -         |
| County DI DIVISION TO |                                                    | \$ | -         |
| Joung                 | Total Budgetary Cost Estimate:                     | \$ | 6,050,000 |
| DL DIVISION 9         | Means of Financing                                 |    |           |
|                       | Funding Subclass                                   |    | Amount    |
|                       | Program Support/Revenue (from stabilization funds) |    |           |
|                       | Financing/Debt Issuance                            | \$ | 6,050,000 |
|                       | Fordered Code Other Photographic halons            | 4  |           |

| 8                                                  |              |
|----------------------------------------------------|--------------|
| Funding Subclass                                   | Amount       |
| Program Support/Revenue (from stabilization funds) |              |
| Financing/Debt Issuance                            | \$ 6,050,000 |
| Federal, State, Other: Please explain below        | \$ -         |
|                                                    | \$ -         |
|                                                    | \$ -         |
| Local Funding - Cash                               |              |
| Total Funding:                                     | \$ 6,050,000 |
| CONTACT PERSON: Mark Tschirhart                    |              |
| PHONE: 757.876.8681                                |              |
|                                                    | •            |

### County of York, Virginia Capital Improvement Program Submission Fiscal Years 2024 - 2029 PROJECT NUMBER: N/A PROJECT NAME: New Elementary School CATEGORY: SBO Admin. Svcs. PROJECT TYPE: New Construction PROJECT LOCATION: To be determined County of York, Virginia Capital Improvement Program Submission Fiscal Years 2024 - 2029 PROJECT NAME: New Elementary School DEPARTMENT: YCSD Capital Plans & Projects DIVISION: YCSD FUND: 2500

|              | Programmed Funding |              |    |        |                                         |   |    |             |    |        |        |     |            |                |  |
|--------------|--------------------|--------------|----|--------|-----------------------------------------|---|----|-------------|----|--------|--------|-----|------------|----------------|--|
|              | Total              | Appropriated |    |        | Non-Appropriated programmed CIP Funding |   |    |             |    |        |        |     |            |                |  |
| Project Cost |                    | To Date      |    | FY2024 | FY2025                                  |   |    | FY2026      |    | FY2027 | FY2028 | T   | FY2029     | Future Funding |  |
| \$           | 600,000            | N/A          | \$ |        | \$                                      | - | ٧, | <b>;</b> -  | \$ | -      |        |     | \$ 600,000 | NA             |  |
| FY2023       | Approved CIP       |              | \$ |        | \$                                      | - | \$ | <b>\$</b> - |    |        |        |     | \$ -       | NA             |  |
| FY2022       | Approved CIP       |              | \$ | -      | \$                                      | - | \$ | \$ -        | \$ | -      | \$ -   | . [ | \$ -       | NA             |  |

### **Description, Scope and Timeline**

A new elementary school along with all necessary site amenities will be constructed.

Anticipated Timeline:

Funding - July 2028

A&E Design Complete - November 2029 Invitation for Bids - February 2030 Construction - June 2031 - August 2033

### **Purpose and Need**

Due to increased residential construction in the school zone and increasing enrollment, an additional elementary school is needed.

### **History and Current Status**

The continuing residential development in the school zone is driving the need for additional classroom space and therefore a new school as enrollment increases.

### **Operating Budget Impacts**

Funding will be required for additional teaching, support and maintenance staff as well as for operational costs of the new school. Additional buses and drivers will also be required to transport students.

### **Anticipated Performance/Outcome Measures**

A new school will relieve enrollment pressure on existing schools, reduce class sizes and provide a better teaching environment.


| Ì | Strategic Plan Goals (Check all applicable) |                     |   |                         |  |  |  |
|---|---------------------------------------------|---------------------|---|-------------------------|--|--|--|
| ĺ | Χ                                           | Student Achievement |   | School Culture          |  |  |  |
|   | Х                                           | Student Experiences | Х | Operational Stewardship |  |  |  |
| ſ | Χ                                           | Staff Support       |   |                         |  |  |  |

|                                | Schedule of Activities                             |        |         |
|--------------------------------|----------------------------------------------------|--------|---------|
|                                | Project Activities                                 | Amount |         |
|                                | A&E (funding from stabilization funds)             | \$     | 600,000 |
|                                | Land                                               | \$     | -       |
|                                | Construction                                       |        |         |
|                                | Furnishings                                        | \$     | -       |
|                                | Equipment                                          | \$     | -       |
|                                | Contingencies                                      |        |         |
|                                | Other: Please explain below                        | \$     | -       |
| () 1 to the state of           |                                                    | \$     | -       |
| York County<br>SCHOOL DIVISION | Total Budgetary Cost Estimate:                     | \$     | 600,000 |
| SCHOOL DIVISION Y              | Means of Financing                                 |        |         |
|                                | Funding Subclass                                   |        | Amount  |
|                                | Program Support/Revenue (from stabilization funds) |        |         |
|                                | Financing/Debt Issuance                            | \$     | 600,000 |
|                                | Federal State Other: Please explain below          | ċ      |         |


| Funding Subclass                                   | Amount |         |  |
|----------------------------------------------------|--------|---------|--|
| Program Support/Revenue (from stabilization funds) |        |         |  |
| Financing/Debt Issuance                            | \$     | 600,000 |  |
| Federal, State, Other: Please explain below        | \$     | -       |  |
|                                                    | \$     | -       |  |
|                                                    | \$     | -       |  |
| Local Funding - Cash                               |        |         |  |
| Total Funding                                      | \$     | 600,000 |  |
| CONTACT PERSON: Mark Tschirhart                    |        |         |  |
| PHONE: 757.876.8681                                |        | •       |  |

Exhibit 8 – School Zone Attendance Maps


Map 1 – Bethel Manor Elementary School Zone




Map 2 – Coventry Elementary School Zone




Map 3 – Dare Elementary School Zone




Map 4 – Grafton Bethel Elementary School Zone




Map 5 – Magruder Elementary School Zone




Map 6 – Mount Vernon Elementary School Zone




Map 7 – Seaford Elementary School Zone




Map 8 – Tabb Elementary School Zone




Map 9 – Waller Mill Elementary School Zone




Map 10 - Yorktown Elementary School Zone




Map 11 - Bruton High and Queens Lake Middle School Zone



Map 12 - Grafton High and Middle School Zone



Map 13 - Tabb High and Middle School Zone



Map 14 - York High and Middle School Zone

